

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|-------------|----------------------|---|
| 79 | GX-B1328/20-7-23017 | 2023. 4. 19 | 本次共检绝缘手套2只，2只绝缘手套合格。 |  |
| 80 | GX-B1328/20-7-23018 | 2023. 4. 19 | 本次共检绝缘靴2只，2只绝缘靴合格。 |  |
| 81 | GX-B1328/20-7-23015 | 2023. 4. 21 | 本次共检绝缘手套6只，6只绝缘手套合格。 |  |
| 82 | GX-B1328/20-7-23016 | 2023. 4. 21 | 本次共检绝缘靴4只，4只绝缘靴合格。 |  |

| | | | | |
|----|---------------------|-----------|----------|---|
| 83 | GX-B1517/20-7-23018 | 2023-4-21 | 综合判定：合格。 |  |
| 84 | GX-B1517/20-7-23019 | 2023-4-21 | 综合判定：合格。 |  |
| 85 | GX-B1517/20-7-23020 | 2023-4-21 | 综合判定：合格。 |  |
| 86 | GX-B1517/20-7-23021 | 2023-4-21 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-----------|----------|---|
| 87 | GX-B1517/20-7-23022 | 2023-4-21 | 综合判定：合格。 |  |
| 88 | GX-B1517/20-7-23023 | 2023-4-21 | 综合判定：合格。 |  |
| 89 | GX-B1517/20-7-23009 | 2023-4-21 | 综合判定：合格。 |  |
| 90 | GX-B1517/20-7-23010 | 2023-4-21 | 综合判定：合格。 |  |

| | | | | | | |
|----|---------------------|-----------|----------|--|---|--|
| 91 | GX-B1517/20-7-23011 | 2023-4-21 | 综合判定：合格。 | |  | |
| 92 | GX-B1517/20-7-23012 | 2023-4-21 | 综合判定：合格。 | |  | |
| 93 | GX-B1517/20-7-23013 | 2023-4-21 | 综合判定：合格。 | |  | |
| 94 | GX-B1517/20-7-23014 | 2023-4-21 | 综合判定：合格。 | |  | |


| | | | | | | |
|----|---------------------|-----------|----------|--|---|--|
| 95 | GX-B1517/20-7-23015 | 2023-4-21 | 综合判定：合格。 | |  | |
| 96 | GX-B1517/20-7-23016 | 2023-4-21 | 综合判定：合格。 | |  | |
| 97 | GX-B1517/20-7-23017 | 2023-4-21 | 综合判定：合格。 | |  | |
| 98 | GX-B1499/21-7-23004 | 2023-4-22 | 所检项目合格 | |  | |

| | | | | |
|-----|---------------------------|-----------|---------|---|
| 99 | GX-B1499/21-7-23005 | 2023-4-22 | 所检项目合格 |  |
| 100 | GX-B1499/21-7-23006 | 2023-4-22 | 所检项目合格 |  |
| 101 | GX-B1359/21-7-23016~23017 | 2023-4-22 | 所检项目合格 |  |
| 102 | GX-B1352/21-7-23064~23093 | 2023-4-24 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------------|-------------|------------------------------|---|
| 103 | GX-B1352/21-7-23094~23123 | 2023-4-24 | 所检项目合格。 |  |
| 104 | GX-B1312/20-7-23051~23053 | 2023. 4. 22 | 本次共检电力变压器3台，3台所检项目合格。 |  |
| 105 | GX-B1321/20-7-23145~23146 | 2023. 4. 22 | 本次共检电力电缆2条，2条电力电缆所检项目合格。 |  |
| 106 | GX-B1495/20-7-23326~23333 | 2023. 4. 22 | 本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。 |  |

| | | | | |
|-----|---------------------------|-------------|----------------------------------|---|
| 107 | GX-B1352/21-7-23601~23610 | 2023. 4. 22 | 本次共检矿用防爆低压交流真空馈电开关10台,10台所检项目合格。 |  |
| 108 | GX-B1354/20-7-23007 | 2023-4-25 | 电网接地电容电流符合规定 |  |
| 109 | GX-B1354/20-7-23006 | 2023-4-25 | 电网接地电容电流符合规定 |  |
| 110 | GX-B1354/20-7-23003 | 2023-4-25 | 电网接地电容电流符合规定 |  |

| | | | | |
|-----|--------------------------|------------|------------------------------|---|
| 111 | GX-B131/20-7-23067~23078 | 2023. 4. 7 | 本次共检电力变压器12台，12台电力变压器所检项目合格。 |  |
| 112 | GX-B131/20-7-23079~23088 | 2023. 4. 7 | 本次共检电力变压器10台，10台电力变压器所检项目合格。 |  |
| 113 | GX-B131/20-7-23089~23092 | 2023. 4. 7 | 本次共检电力变压器4台，4台电力变压器所检项目合格。 |  |
| 114 | GX-B131/20-7-23095~23103 | 2023. 4. 7 | 本次共检电力变压器9台，9台电力变压器所检项目合格。 |  |

| | | | | |
|-----|---------------------------|------------|----------------------------|---|
| 115 | GX-B131/20-7-23104~23107 | 2023. 4. 7 | 本次共检电力变压器4台，4台电力变压器所检项目合格。 |  |
| 116 | GX-B131/20-7-23108~23110 | 2023. 4. 7 | 本次共检电力变压器3台，3台电力变压器所检项目合格。 |  |
| 117 | GX-B2321/20-7-23065~23071 | 2023. 4. 7 | 本次共检电力电缆7条，7条电力电缆均合格。 |  |
| 118 | GX-B2321/20-7-23072~23080 | 2023. 4. 7 | 本次共检电力电缆9条，9条电力电缆均合格。 |  |

| | | | | |
|-----|----------------------------|-------------|--------------------------------|---|
| 119 | GX-B2321/20-7-23086~23097 | 2023. 4. 7 | 本次共检电力电缆12条，12条电力电缆均合格。 |  |
| 120 | GX-B2321/20-7-230098~23105 | 2023. 4. 7 | 本次共检电力电缆8条，8条电力电缆均合格。 |  |
| 121 | GX-B1323/21-7-23032~23037 | 2023. 4. 11 | 本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。 |  |
| 122 | GX-B1323/21-7-23038~23044 | 2023. 4. 11 | 本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。 |  |

| | | | | | | |
|-----|---------------------------|------------|--------------------------------|--|---|--|
| 123 | GX-B1495/20-7-23186~23195 | 2023. 4. 7 | 本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。 | |  | |
| 124 | GX-B1495/20-7-23196~23208 | 2023. 4. 7 | 本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。 | |  | |
| 125 | GX-B1495/20-7-23209~23221 | 2023. 4. 7 | 本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。 | |  | |
| 126 | GX-B1495/20-7-23231~23244 | 2023. 4. 7 | 本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。 | |  | |

| | | | | |
|-----|---------------------------|------------|--------------------------------|--|
| 127 | GX-B1495/20-7-23245~23258 | 2023. 4. 7 | 本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。 |  A worker in a blue uniform and red helmet is kneeling on a green mat, working on a piece of equipment. The background shows red storage units. A yellow timestamp '2023/3/7' is visible in the bottom right corner of the image. |
| 128 | GX-B1495/20-7-23259~23268 | 2023. 4. 7 | 本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。 |  A worker in a dark jacket is standing next to a control panel with a green light. A yellow timestamp '2023/3/4' is visible in the bottom right corner of the image. |