


序号	报告编号	发布日期	结论	影像资料
214	GX-B1499/21-4-23006	2023. 4. 27	所检项目合格	
215	GX-B1499/21-4-23007	2023. 4. 27	所检项目合格	
216	GX-B1499/21-4-23008	2023. 4. 27	所检项目合格	

217	GX-B1308/21-4-23001	2023. 4. 27	所检项目合格	
218	GX-B1350/21-4-23030	2023. 4. 25	本次共检接地装置3处，3处所检项目合格	
219	GX-B1312/20-4-23296~23297	2023. 4. 28	本次共检电力变压器2台，2台所检项目合格	
220	GX-B1312/20-4-23298~23299	2023. 4. 28	本次共检电力变压器2台，2台所检项目合格	

221	GX-B1312/20-4-23300~23301	2023. 4. 28	本次共检电力变压器2台，2台所检项目合格	
222	GX-B1321/20-4-23492~23501	2023. 4. 28	本次共检电力电缆10条，10条所检项目合格	
223	GX-B1321/20-4-23502~23506	2023. 4. 28	本次共检电力电缆5条，5条所检项目合格	