

序号	报告编号	发布日期	结论	影像资料
72	GX-B1377/22-F-23100	2023. 4. 28	所检项目合格	
73	GX-B1377/22-F-23096	2023. 4. 28	所检项目合格	

74	GX-B1377/22-F-23097	2023. 4. 28	所检项目合格	
75	GX-B1377/22-F-23098	2023. 4. 28	所检项目合格	
76	GX-B1377/22-F-23099	2023. 4. 28	所检项目合格	

77	GX-B1377/22-F-23093	2023. 4. 28	所检项目合格	
78	GX-B1377/22-F-23094	2023. 4. 28	所检项目合格	

79	GX-B1377/22-F-23095	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. They are wearing light-colored jackets and are positioned around a piece of white equipment, possibly a scale or a small analytical instrument. The background includes a window with blinds and some other lab equipment.
80	GX-B1378/22-F-23101	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory setting. They are wearing dark jackets and are working with a piece of equipment, possibly a scale or a small analytical instrument. The background includes a window with yellow curtains and some other lab equipment.

81	GX-B1378/22-F-23102	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. They are wearing light-colored jackets and face masks. One person is holding a white document, and they appear to be reviewing it together. In the background, there is a window with yellow curtains and some laboratory equipment. A timestamp '2023/4/7' is visible in the bottom right corner of the image.
82	GX-B1489/21-F- 23024	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. They are wearing light-colored jackets and face masks. One person is holding a white document, and they appear to be reviewing it together. In the background, there is a window with yellow curtains and some laboratory equipment. A timestamp '2023/4/8' is visible in the bottom right corner of the image.

83	GX-B1489/21-F- 23025	2023. 4. 28	所检项目合格	 A photograph showing two female laboratory technicians in grey lab coats and blue face masks. They are standing in a laboratory setting, looking at a computer monitor. One technician is holding a small white object. The date '2023/4/18' is visible in the bottom right corner of the photo.
84	GX-B1489/21-F- 23026	2023. 4. 28	所检项目合格	 A photograph showing two female laboratory technicians in grey lab coats and blue face masks. They are standing in a laboratory setting, looking at a computer monitor. The date '2023/4/18' is visible in the bottom right corner of the photo.

85	GX-B1492/21-F-23008	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory setting. They are wearing light-colored lab coats and blue surgical masks. They are standing near a piece of laboratory equipment, possibly a spectrophotometer or a similar analytical instrument, which has a computer monitor and various cables attached. The background shows a typical laboratory environment with shelves and other equipment.
86	GX-B1378/22-F-23108~F-23109	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory setting, similar to the one above. They are wearing light-colored lab coats and blue surgical masks. They are standing near a piece of laboratory equipment, possibly a spectrophotometer or a similar analytical instrument, which has a computer monitor and various cables attached. The background shows a typical laboratory environment with shelves and other equipment.


87	GX-B1377/22-F-23114	2023. 4. 28	所检项目合格	
88	GX-B1377/22-F-23115	2023. 4. 28	所检项目合格	



89	GX-B1377/22-F-23116	2023. 4. 28	所检项目合格	
90	GX-B1377/22-F-23112	2023. 4. 28	所检项目合格	



91	GX-B1377/22-F-23113	2023. 4. 28	所检项目合格	
92	GX-B1378/22-F-23110	2023. 4. 28	所检项目合格	
93	GX-B1502/21-F-23006	2023. 4. 28	I类, 容易自燃	

94	GX-B1501/21-F-23006	2023. 4. 28	有爆炸性	
95	GX-B1502/21-F-23007	2023. 4. 28	I 类, 容易自燃	
96	GX-B1501/21-F-23007	2023. 4. 28	有爆炸性	
97	GX-B1502/21-F-23008	2023. 4. 28	I 类, 容易自燃	
98	GX-B1501/21-F-23008	2023. 4. 28	有爆炸性	

99	GX-B1377/22-F-23111	2023. 4. 26	所检项目合格	
100	GX-B1489/21-F- 23007~F-23020	2023. 4. 28	所检项目合格	

101	GX-B1377/22-F-23106	2023. 4. 28	所检项目合格	 <p>A photograph showing two female technicians in grey lab coats and blue face masks in a laboratory. They are standing at a workbench, looking at a document. In the background, there is a large piece of scientific equipment, possibly a spectrophotometer or similar instrument. A date stamp '2023/4/17' is visible in the bottom right corner of the photo.</p>
102	GX-B1377/22-F-23107	2023. 4. 28	所检项目合格	 <p>A photograph showing two female technicians in grey lab coats and blue face masks in a laboratory. They are standing at a workbench, looking at a document. A computer monitor is open on the workbench in front of them. Various pieces of laboratory equipment are visible on the table. A date stamp '2023/4/17' is visible in the bottom right corner of the photo.</p>

103	GX-B1377/22-F-23108	2023. 4. 28	所检项目合格	
104	GX-B1377/22-F-23109	2023. 4. 28	所检项目合格	

105	GX-B1377/22-F-23110	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory. They are wearing light-colored lab coats and face masks. They are standing at a workstation with various pieces of equipment, including what appears to be a spectrophotometer or similar analytical instrument. The date '2023/4/17' is visible in the bottom right corner of the image.
106	GX-B1378/22-F-23104~F-23107	2023. 4. 28	所检项目合格	 A photograph showing two individuals in a laboratory. They are wearing light-colored lab coats and face masks. They are standing at a workstation, possibly a biosafety cabinet or a similar enclosed laboratory equipment. The date '2023/4/15' is visible in the bottom right corner of the image.

107	GX-B1489/21-F- 23021~F-23023	2023. 4. 28	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing grey lab coats and blue face masks. One technician is holding a document and looking at it, while the other stands beside her. In the background, there is a computer monitor, a printer, and other lab equipment. A timestamp '2023/4/14' is visible in the bottom right corner of the photo.
108	GX-B1377/22-F-23102	2023. 4. 28	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing grey lab coats and blue face masks. They are standing at a lab bench with a large piece of equipment, possibly a spectrophotometer or a similar analytical instrument. There are various bottles and containers on the bench. A timestamp '2023/4/15' is visible in the bottom right corner of the photo.



109	GX-B1377/22-F-23103	2023. 4. 28	所检项目合格	
110	GX-B1377/22-F-23104	2023. 4. 28	所检项目合格	

111	GX-B1377/22-F-23105	2023. 4. 28	所检项目合格	 A photograph showing two female laboratory technicians in a clean, well-lit lab. They are wearing light-colored lab coats, face masks, and gloves. One technician is standing near a piece of laboratory equipment, possibly a spectrophotometer or a similar analytical instrument, while the other is standing next to her, looking at something in her hands. The background shows typical lab equipment and a clean environment. A small date stamp '2023/4/15' is visible in the bottom right corner of the photo.
-----	---------------------	-------------	--------	---