

序号	报告编号	发布日期	结论	影像资料
1	GX-B1322/21-3-23074~23075	2023. 5. 4	所检项目合格	 A photograph showing a worker in a red uniform and red helmet working on electrical equipment. The worker is kneeling and using a tool. The date '2023.4.8' is visible in the bottom right corner of the image.
2	GX-B1308/21-3-23011	2023年5月4日	所检项目合格	 A photograph showing a worker in a blue uniform and red helmet working on electrical equipment. The worker is kneeling and using a tool. The date '2023.4.27' is visible in the bottom right corner of the image.

3	GX-B1308/21-3-23012	2023年5月4日	所检项目合格		
4	GX-B1499/21-3-23078	2023年5月4日	所检项目合格		

5	GX-B1499/21-3-23079	2023年5月4日	所检项目合格			
6	GX-B1499/21-3-23080	2023年5月4日	所检项目合格			

7	GX-B1499/21-3-23081	2023年5月4日	所检项目合格			
8	GX-B1499/21-3-23082	2023年5月4日	所检项目合格			

9	GX-B1308/21-3-23010	2023年5月4日	所检项目合格	
10	GX-B1306/21-3-23011	2023. 5. 4	所检项目合格。 。	

11	GX-B1306/21-3-23012	2023. 5. 4	所检项目合格。 。	
12	GX-B1451/20-3-23131	2023. 5. 4	所检项目合格	
13	GX-B1495/20-3-232183	2023. 5. 4	所检项目合格	

14	GX-B1307/20-3-23006	2023. 5. 5	综合判定：合格	 <p>2023.4.26</p>
15	GX-B1307/20-3-23007	2023. 5. 5	综合判定：合格	 <p>2023.4.26</p>

16	GX-B1307/20-3-23008	2023.5.5	综合判定：合格	
17	GX-B1307/20-3-23009	2023.5.5	综合判定：合格	
18	GX-B1322/21-3-23072-23073	2023年5月4日	本次共检电力电缆2条，2条电力电缆所检项目合格。	
19	GX-B1313/21-3-23049-23051	2023年5月4日	本次共检电力变压器3台，3台电力变压器所检项目合格。	

20	GX-B1328/20-3-23124	2023年5月4日	本次共检绝缘手套10只，10只绝缘手套合格。	
21	GX-B1328/20-3-23125	2023年5月4日	本次共检绝缘鞋10只，10只绝缘鞋合格。	
22	GX-B1328/20-3-23126	2023年5月4日	合格。	
23	GX-B1328/20-3-23127	2023年5月4日	合格。	
24	GX-B1328/20-3-23119	2023年5月4日	本次共检绝缘手套12只，12只绝缘手套合格。	

25	GX-B1328/20-3-23120	2023年5月4日	本次共检绝缘鞋12只，12只绝缘鞋合格。	 A photograph showing a worker in a red hard hat and dark jacket kneeling on a concrete floor, testing an insulating shoe with a device. A red fire extinguisher and other equipment are visible in the background. A date stamp '2023.4.25' is at the bottom right.
26	GX-B1328/20-3-23121	2023年5月4日	合格。	 A photograph showing a worker in a red hard hat and dark jacket kneeling on a concrete floor, testing an insulating shoe with a device. A red fire extinguisher and other equipment are visible in the background. A date stamp '2023.4.25' is at the bottom right.

27	GX-B1328/20-3-23122	2023年5月4日	本次共检便携式接地和接地短路装置2套，2套便携式接地和接地短路装置合格。	 <p>2023.4.25</p>
28	GX-B1328/20-3-23123	2023年5月4日	本次共检验电器3支，3支验电器合格。	 <p>2023.4.25</p>

29	GX-B1313/21-3-23045-23048	2023年5月4日	本次共检电力 变压器4台，4 台电力变压器 所检项目合格 。	
30	GX-B1322/21-3-23069-23071	2023年5月4日	本次共检电力 电缆3条，3条 电力电缆所检 项目合格。	

31	GX-B1321/20-3-23811	2023年5月4日	所检项目合格	
32	GX-B1312/20-3-23286	2023年5月4日	所检项目合格。	

33	GX-B1427/21-3-23010	2023年5月6日	符合标准要求	 <p>2023.04.11</p>
34	GX-B1427/21-3-23011	2023年5月6日	符合标准要求	 <p>2023.04.11</p>

35	GX-B1310/21-3-23025	2023年5月6日	符合标准要求	
36	GX-B1310/21-3-23026	2023年5月6日	符合标准要求	

37	GX-B1310/21-3-23027	2023年5月6日	符合标准要求	 <p>2023.04.11</p>
38	GX-B1310/21-3-23028	2023年5月6日	符合标准要求	 <p>2023.04.11</p>

39	GX-B1310/21-3-23029	2023年5月6日	符合标准要求	 <p>2023.04.11</p>
40	GX-B1310/21-3-23030	2023年5月6日	符合标准要求	 <p>2023.04.11</p>