













序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-5-23108	2023. 5. 4	符合标准要求	
2	GX-B1310/21-5-23109	2023. 5. 4	符合标准要求	

3	GX-B1310/21-5-23110	2023. 5. 4	符合标准要求	
4	GX-B1310/21-5-23111	2023. 5. 4	符合标准要求	
5	GX-B1310/21-5-23112	2023. 5. 4	符合标准要求	

6	GX-B1310/21-5-23113	2023. 5. 4	符合标准要求	
7	GX-B1321/20-5-23411~23419	2023. 5. 4	<p>本次共检电力电缆9条，9条电力电缆所检项目合格。</p>	
8	GX-B1321/20-5-23420~23426	2023. 5. 4	<p>本次共检电力电缆7条，7条电力电缆所检项目合格。</p>	


9	GX-B1321/20-5-23427~23434	2023. 5. 4	本次共检电力电缆8条，8条电力电缆所检项目合格。	
10	GX-B1321/20-5-23435~23438	2023. 5. 4	本次共检电力电缆4条，4条电力电缆所检项目合格。	
11	GX-B1321/20-5-23439~23448	2023. 5. 4	本次共检电力电缆10条，10条电力电缆所检项目合格。	

12	GX-B1321/20-5-23449~23459	2023. 5. 4	本次共检电力电缆11条，11条电力电缆所检项目合格。	
13	GX-B1321/20-5-23460~23463	2023. 5. 4	本次共检电力电缆4条，4条电力电缆所检项目合格。	
14	GX-B1321/20-5-23464~23465	2023. 5. 4	本次共检电力电缆2条，2条电力电缆所检项目合格。	

15	GX-B1321/20-5-23468~23477	2023. 5. 4	本次共检电力电缆10条，10条电力电缆所检项目合格。	
16	GX-B1321/20-5-23478~23481	2023. 5. 4	本次共检电力电缆4条，4条电力电缆所检项目合格。	
17	GX-B1321/20-5-23482~23487	2023. 5. 4	本次共检电力电缆6条，6条电力电缆所检项目合格。	

18	GX-B1321/20-5-23488~23493	2023. 5. 4	本次共检电力电缆6条，6条电力电缆所检项目合格。	
19	GX-B1321/20-5-23494~23510	2023. 5. 4	本次共检电力电缆17条，17条电力电缆所检项目合格。	
20	GX-B1321/20-5-23511~23515	2023. 5. 4	本次共检电力电缆5条，5条电力电缆所检项目合格。	

21	GX-B1321/20-5-23516	2023. 5. 4	所检项目合格。	 <p>2023/04/05</p>
22	GX-B1324/21-3-23021	2023. 5. 4	所检项目合格	 <p>2023.4.25</p>
23	GX-B1310/21-5-23040	2023. 5. 5	符合标准要求	 <p>2023.02.24</p>

24	GX-B1310/21-5-23041	2023. 5. 5	符合标准要求	
25	GX-B1310/21-5-23042	2023. 5. 5	符合标准要求	
26	GX-B1310/21-5-23047	2023. 5. 5	未发现超过Φ2mm当量直径的缺陷	

27	GX-B1310/21-5-23048	2023. 5. 5	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
28	GX-B1310/21-5-23092	2023. 5. 5	符合标准要求。	
29	GX-B1310/21-5-23093	2023. 5. 5	符合标准要求。	




30	GX-B1310/21-5-23100	2023. 5. 5	符合标准要求。	
31	GX-B1310/21-5-23094	2023. 5. 5	符合标准要求。	
32	GX-B1310/21-5-23101	2023. 5. 5	符合标准要求。	

33	GX-B1310/21-5-23107	2023. 5. 5	符合标准要求。	
34	GX-B1310/21-5-23091	2023. 5. 5	符合标准要求。	
35	GX-B1310/21-5-23097	2023. 5. 5	符合标准要求。	

36	GX-B1310/21-5-23098	2023. 5. 5	符合标准要求。	
37	GX-B1310/21-5-23099	2023. 5. 5	符合标准要求。	
38	GX-B1310/21-5-23090	2023. 5. 5	符合标准要求。	



39	GX-B1515/22-5-23010	2023. 5. 5	所检项目合格。	
40	GX-B1515/22-5-23011	2023. 5. 5	所检项目合格。	
41	GX-B1417/22-5-23015	2023/5/5	综合判定：合格。	

42	GX-B1417/22-5-23016	2023/5/5	综合判定：合格。	
43	GX-B1417/22-5-23013	2023/5/5	综合判定：合格。	
44	GX-B1417/22-5-23014	2023/5/5	综合判定：合格。	

45	GX-B1416/22-5-23024	2023/5/1	综合判定：合格。	 A worker in a blue uniform and red helmet is working on a large industrial structure, possibly a boiler or heat exchanger, in a dimly lit environment. The worker is standing on a platform and appears to be inspecting or working on a component. A timestamp '2023/4/11' is visible in the bottom right corner of the photo.
46	GX-B1416/22-5-23025	2023/5/1	综合判定：合格。	 A worker in a blue uniform and red helmet is inspecting a large industrial structure, possibly a boiler or heat exchanger, in a dimly lit environment. The worker is standing on a platform and appears to be inspecting a component. A timestamp '2023/4/11' is visible in the bottom right corner of the photo.
47	GX-B1416/22-5-23026	2023/5/1	综合判定：合格。	 A worker in a blue uniform and red helmet is inspecting a large industrial structure, possibly a boiler or heat exchanger, in a dimly lit environment. The worker is standing on a platform and appears to be inspecting a component. A timestamp '2023/4/11' is visible in the bottom right corner of the photo.

48	GX-B1416/22-5-23027	2023/5/1	综合判定：合格。	
49	GX-B1416/22-5-23028	2023/5/1	综合判定：合格。	
50	GX-B1306/21-5-23028	2023/5/1	所检项目合格	

51	GX-B1306/21-5-23029	2023/5/1	所检项目合格	
52	GX-B1306/21-5-23030	2023/5/1	所检项目合格	
53	GX-B1300/20-5-23006	2023/5/1	综合判定：合格	

54	GX-B1415/22-5-23008	2023/5/1	综合判定：合格	
55	GX-B1308/21-5-23015	2023/5/1	所检项目合格	
56	GX-B1499/21-5-23040	2023/5/1	所检项目合格	

57	GX-B1499/21-5-23041	2023/5/1	所检项目合格	
58	GX-B1499/21-5-23042	2023/5/1	所检项目合格	
59	GX-B1495/20-5-23803~23814	2023/5/1	<p>本次共检高压防爆开关12台，12台高压防爆开关所检项目合格。</p>	

60	GX-B1495/20-5-23815~23824	2023/5/1	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
61	GX-B1495/20-5-23832~23851	2023/5/1	本次共检高压开关柜20台，20台高压开关柜所检项目合格。	
62	GX-B1312/20-5-23226~23227	2023/5/5	本次共检电力变压器2台，2台电力变压器所检项目合格。	

63	GX-B1321/20-5-23398~23401	2023/5/5	本次共检电力电缆4条，4条电力电缆所检项目合格。	 <p>2023/4/13</p>
64	GX-B1350/21-5-23030	2023/5/1	所检项目合格。	 <p>2023/4/13</p>
65	GX-B1310/21-5-23104	2023/5/5	符合标准要求。	 <p>2023/4/11</p>

66	GX-B1428/21-5-23012	2023/5/5	无缺陷迹痕显示。	
67	GX-B1310/21-5-23105	2023/5/5	符合标准要求。	
68	GX-B1428/21-5-23013	2023/5/5	无缺陷迹痕显示。	

69	GX-B1328/20-5-23079	2023/5/5	本次共检绝缘手套30只，30只绝缘手套合格。	
70	GX-B1328/20-5-23080	2023/5/5	本次共检绝缘鞋30只，30只绝缘鞋合格。	
71	GX-B1328/20-5-23081	2023/5/5	本次共检验电器10支，10支验电器合格。	

72	GX-B1328/20-5-23082	2023/5/5	本次共检携带式接地和接地短路装置10套，10套携带式接地和接地短路装置合格。	
73	GX-B1310/21-5-23102	2023/5/5	符合标准要求。	
74	GX-B1495/20-5-23852~23856	2023/5/5	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	

75	GX-B1310/21-5-23103	2023/5/5	符合标准要求。	
76	GX-B1495/20-5-23825~23831	2023/5/5	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
77	GX-B1495/20-5-23794~23802	2023/5/1	本次共检高压开关柜9台，9台高压开关柜所检项目合格。	

78	GX-B1350/21-5-23029	2023/5/1	<p>本次共检接地装置2处，2处接地装置所检项目合格。</p>	
79	GX-B1321/20-5-23394~23397	2023/5/1	<p>本次共检电力电缆4条，4条电力电缆所检项目合格。</p>	
80	GX-B1424/20-5-23014	2023/5/1	<p>依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。</p>	

81	GX-B1424/20-5-23015	2023/5/1	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。	
82	GX-B1322/21-5-23033~23037	2023/5/5	本次共检电力电缆5条，5条电力电缆所检项目合格。	
83	GX-B1322/21-5-23038~23057	2023/5/5	本次共检电力电缆20条，20条电力电缆所检项目合格。	

84	GX-B1515/22-5-23003	2023/5/5	所检项目合格	
----	---------------------	----------	--------	---