

序号	报告编号	发布日期	结论	影像资料
177	GX-B1332/21-2-23001~23015	2023. 5. 19	本次共检电力电容器 15台，15台所检项目合格。 。	 <p>A photograph showing three workers in grey uniforms and red hard hats inspecting electrical equipment in a control room. One worker is kneeling while another stands nearby. The date '2023/05/05' is visible in the bottom right corner of the image.</p>
178	GX-B1332/21-2-23016~23030	2023. 5. 19	本次共检电力电容器 15台，15台所检项目合格。 。	 <p>A photograph showing three workers in grey uniforms and red hard hats inspecting electrical equipment in a control room. One worker is kneeling while another stands nearby. The date '2023/05/05' is visible in the bottom right corner of the image.</p>
179	GX-B1547/20-2-23001~23006	2023. 5. 19	本次共检继电保护装置 6台，6台所检项目合格。	 <p>A photograph showing a worker in a grey uniform and red hard hat inspecting a relay protection device in a control room. The worker is standing next to a rack of equipment. The date '2023/05/05' is visible in the bottom right corner of the image.</p>

180	GX-B1547/20-2-23007~23010	2023. 5. 19	本次共检继电保护装置4台，4台所检项目合格。	
181	GX-B1495/20-2-23214	2023. 5. 18	所检项目合格。	
182	GX-B1328/20-2-23076	2023. 5. 19	本次共检绝缘手套1副，1副所检项目合格。	

183	GX-B1328/20-2-23077	2023. 5. 19	本次共检绝缘鞋1双, 1双 所检项目合格。		
184	GX-B1328/20-2-23078	2023. 5. 19	所检项目合格。		
185	GX-B1328/20-2-23079	2023. 5. 19	所检项目合格。		

186	GX-B1495/20-2-23267~23270	2023. 5. 19	本次共检高压交流断路器4台，4台所检项目合格。	
187	GX-B1495/20-2-23271~23272	2023. 5. 19	本次共检高压交流断路器2台，2台所检项目合格。	
188	GX-B1329/21-2-23109~23110	2023. 5. 19	本次共检氧化锌避雷器2组，2组所检项目合格。	

189	GX-B1329/21-2-23111	2023. 5. 19	所检项目合格。	
190	GX-B1329/21-2-23112~23113	2023. 5. 19	本次共检氧化锌避雷器2组，2组所检项目合格。	
191	GX-B1423/20-2-23049	2023. 5. 22	综合判定：合格	


192	GX-B1423/20-2-23050	2023. 5. 22	综合判定：合格	
193	GX-B1423/20-2-23051	2023. 5. 22	综合判定：合格	
194	GX-B1423/20-2-23052	2023. 5. 22	综合判定：合格	


195	GX-B1423/20-2-23053	2023. 5. 22	综合判定：合格	
196	GX-B1423/20-2-23054	2023. 5. 22	综合判定：合格	
197	GX-B1423/20-2-23055	2023. 5. 22	综合判定：合格	


198	GX-B1423/20-2-23056	2023. 5. 22	综合判定：合格	
199	GX-B1423/20-2-23057	2023. 5. 22	综合判定：合格	
200	GX-B1423/20-2-23058	2023. 5. 22	综合判定：合格	

201	GX-B1423/20-2-23059	2023. 5. 22	综合判定：合格	
202	GX-B1423/20-2-23060	2023. 5. 22	综合判定：合格	
203	GX-B1423/20-2-23061	2023. 5. 22	综合判定：合格	

204	GX-B1423/20-2-23062	2023. 5. 22	综合判定：合格	
205	GX-B1423/20-2-23063	2023. 5. 22	综合判定：合格	
206	GX-B1423/20-2-23064	2023. 5. 22	综合判定：合格	

207	GX-B1423/20-2-23065	2023. 5. 22	综合判定：合格			
208	GX-B1329/21-2-23116~23117	2023. 5. 22	2组氧化锌避雷器所检项目合格。			
209	GX-B1312/20-2-23150~23151	2023. 5. 22	本次共检电力变压器2台，2台所检项目合格。			

210	GX-B1321/20-2-23186~23187	2023. 5. 22	本次共检电力电缆2条，2条所检项目合格。	
211	GX-B1310/21-2-23047	2023. 5. 22	未发现超过Φ2mm当量直径的缺陷。	
212	GX-B1310/21-2-23048	2023. 5. 22	符合标准要求	

213	GX-B1428/21-2-23049	2023. 5. 22	无缺陷迹痕显示		
214	GX-B1310/21-2-23050	2023. 5. 22	符合标准要求		
215	GX-B1310/21-2-23081	2023. 5. 19	符合标准要求		

216	GX-B1310/21-2-23082	2023. 5. 19	符合标准要求		
217	GX-B1310/21-2-23083	2023. 5. 19	符合标准要求		
218	GX-B1310/21-2-23084	2023. 5. 22	符合标准要求		

219	GX-B1321/16-2-23112~23113	2023. 5. 22	本次共检电力电缆2条，2条所检项目合格	
220	GX-B1312/20-2-23117~23118	2023. 5. 22	本次共检电力变压器2台，2台电力变压器所检项目合格	
221	GX-B1312/20-2-23119	2023. 5. 22	所检项目合格	

222	GX-B1312/20-2-23120	2023. 5. 22	所检项目合格	 <p>2023/05/06</p>
223	GX-B1312/20-2-23121	2023. 5. 22	所检项目合格	 <p>2023/05/11</p>
224	GX-B1321/20-2-23114	2023. 5. 22	所检项目合格	 <p>2023/05/11</p>

225	GX-B1530/21-2-23021	2023. 5. 22	所检项目合格。	
226	GX-B1424/20-2-23005	2023. 5. 22	依据NB/T 10176-2019单轨吊车所检项目合格。	
227	GX-B1536/20-2-23001	2023. 5. 24	综合判定：合格。	

228	GX-B1301/21-2-23001	2023. 5. 24	综合判定:合格。	
229	GX-B1306/21-2-23030	2023. 5. 24	所检项目合格。	
230	GX-B1306/21-2-23031	2023. 5. 24	所检项目合格。	

231	GX-B1306/21-2-23032	2023. 5. 24	所检项目合格。			
232	GX-B1306/21-2-23033	2023. 5. 24	所检项目合格。			
233	GX-B1306/21-2-23034	2023. 5. 24	所检项目合格。			

234	GX-B1306/21-2-23038	2023. 5. 24	所检项目合格。			
235	GX-B1306/21-2-23039	2023. 5. 24	所检项目合格。			
236	GX-B1306/21-2-23040	2023. 5. 24	所检项目合格。			

237	GX-B1534/20-2-23009	2023. 5. 22	所检项目合格。	
-----	---------------------	-------------	---------	---