

序号	报告编号	发布日期	结论	影像资料
131	GX-B1301/21-3-23004	2023年5月19日	综合判定:合格。	
132	GX-B1301/21-3-23005	2023年5月19日	综合判定:合格。	

133	GX-B1350/21-3-23006	2023. 5. 19	本次共检验接地装置5处，5处所检项目合格。 。	 <p>2023.04.28</p>
134	GX-B1301/21-3-23006	2023. 5. 19	综合判定:合格。	 <p>OPPO Reno5 Pro 5G 2023.4.20</p>

135	GX-B1300/20-3-23002	2023年5月22日	综合判定：合格。	
136	GX-B1300/20-3-23003	2023年5月22日	综合判定：合格。	

137	GX-B1300/20-3-23004	2023年5月22日	综合判定：合格。	
138	GX-B1499/21-3-23083	2023年5月19日	所检项目合格。	

139	GX-B1499/21-3-23084	2023年5月19日	所检项目合格。	
140	GX-B1499/21-3-23085	2023年5月19日	所检项目合格。	

141	GX-B1499/21-3-23089	2023年5月19日	所检项目合格。	
142	GX-B1499/21-3-23090	2023年5月19日	所检项目合格。	

143	GX-B1499/21-3-23091	2023年5月19日	所检项目合格。	 A photograph showing a worker in a red uniform and helmet, wearing a face mask, inspecting equipment in a dark industrial setting. The worker is holding a flashlight. The date stamp in the bottom right corner of the photo is 2023.4.17.
144	GX-B1499/21-3-23092	2023年5月19日	所检项目合格。	 A photograph showing a worker in a red uniform and helmet standing on a red and green walkway in a bright industrial setting. The worker is holding a flashlight. The date stamp in the bottom right corner of the photo is 2023.4.16.

145	GX-B1499/21-3-23093	2023年5月19日	所检项目合格。	
146	GX-B1499/21-3-23094	2023年5月19日	所检项目合格。	

147	GX-B1499/21-3-23095	2023年5月19日	所检项目合格。	
148	GX-B1499/21-3-23096	2023年5月19日	所检项目合格。	

149	GX-B1499/21-3-23097	2023年5月19日	所检项目合格。	
150	GX-B1499/21-3-23098	2023年5月19日	所检项目合格。	

151	GX-B1499/21-3-23099	2023年5月19日	所检项目合格。	
152	GX-B1499/21-3-23100	2023年5月19日	所检项目合格。	

153	GX-B1499/21-3-23101	2023年5月19日	所检项目合格。	
154	GX-B1499/21-3-23102	2023年5月19日	所检项目合格。	

155	GX-B1499/21-3-23103	2023年5月19日	所检项目合格。	
156	GX-B1308/21-3-23019	2023年5月19日	所检项目合格。	

157	GX-B1499/21-3-23133	2023年5月19日	所检项目合格。	
158	GX-B1499/21-3-23134	2023年5月19日	所检项目合格。	

159	GX-B1499/21-3-23135	2023年5月19日	所检项目合格。	
160	GX-B1499/21-3-23136	2023年5月19日	所检项目合格。	

161	GX-B1499/21-3-23137	2023年5月19日	所检项目合格。	
162	GX-B1308/21-3-23018	2023年5月19日	所检项目合格。	

163	GX-B1499/21-3-23138	2023年5月19日	所检项目合格。	
164	GX-B1499/21-3-23139	2023年5月19日	所检项目合格。	

165	GX-B1499/21-3-23140	2023年5月19日	所检项目合格。	
166	GX-B1499/21-3-23141	2023年5月19日	所检项目合格。	

167	GX-B1499/21-3-23142	2023年5月19日	所检项目合格。	
168	GX-B1308/21-3-23015	2023年5月19日	所检项目合格。	

169	GX-B1499/21-3-23122	2023年5月19日	所检项目合格。	
170	GX-B1499/21-3-23123	2023年5月19日	所检项目合格。	


171	GX-B1499/21-3-23124	2023年5月19日	所检项目合格。	
172	GX-B1308/21-3-23016	2023年5月19日	所检项目合格。	

173	GX-B1499/21-3-23125	2023年5月19日	所检项目合格。	
174	GX-B1499/21-3-23126	2023年5月19日	所检项目合格。	

175	GX-B1499/21-3-23127	2023年5月19日	所检项目合格。	
176	GX-B1499/21-3-23128	2023年5月19日	流量145.2m ³ /h, 泵的起 动时间11s	

177	GX-B1499/21-3-23129	2023年5月19日	流量143.8m ³ /h, 泵的启动时间12s	
178	GX-B1383/21-3-23001	2023. 5. 23	所检项目合格。	



179	GX-B1383/21-3-23002	2023. 5. 23	所检项目合格。	
180	GX-B1329/21-3-23108~23117	2023. 5. 25	本次共检氧化锌避雷器10组，10组所检项目合格。	

181	GX-B1310/21-3-23036	2023. 5. 26	符合标准要求。	 <p>2023.04.28</p>
182	GX-B1310/21-3-23037	2023. 5. 26	符合标准要求。	 <p>2023.04.28</p>

183	GX-B1310/21-3-23038	2023. 5. 26	符合标准要求。	
184	GX-B1310/21-3-23039	2023. 5. 26	符合标准要求。	

185	GX-B1310/21-3-23040	2023. 5. 26	符合标准要求。	 <p>2023.04.28</p>
186	GX-B1310/21-3-23041	2023. 5. 26	符合标准要求。	 <p>2023.04.28</p>

187	GX-B1310/21-3-23042	2023. 5. 26	符合标准要求。		
188	GX-B1310/21-3-23043	2023. 5. 26	符合标准要求。		

189	GX-B1310/21-3-23044	2023. 5. 26	符合标准要求。	
190	GX-B1310/21-3-23045	2023. 5. 26	符合标准要求。	

191	GX-B1380/20-3-23010	2023. 5. 26	所检项目合格。	 A worker wearing a white jacket with a logo, a red helmet, and glasses is standing in an industrial environment. He is holding and looking at a white document. The background shows large metal structures and pipes. A yellow date stamp '2023.05.13' is visible in the bottom right corner of the photo.
192	GX-B1380/20-3-23011	2023. 5. 26	所检项目合格。	 A worker wearing a white jacket with the '中检公信' logo, a red helmet, and blue pants is inspecting a large, dark industrial component. He is standing on a metal platform or scaffolding. The background shows other workers and industrial equipment. A yellow date stamp '2023.05.13' is visible in the bottom right corner of the photo.

193	GX-B1380/20-3-23012	2023. 5. 26	所检项目合格。	
194	GX-B1380/20-3-23013	2023. 5. 26	所检项目合格。	

195	GX-B1380/20-3-23014	2023. 5. 26	所检项目合格。	
-----	---------------------	-------------	---------	---