

序号	报告编号	发布日期	结论	影像资料
156	GX-B1423/20-4-23026	2023. 5. 19	综合判定：合格	
157	GX-B1423/20-4-23027	2023. 5. 19	综合判定：合格	


158	GX-B1423/20-4-23028	2023. 5. 19	综合判定：合格	
159	GX-B1423/20-4-23029	2023. 5. 19	综合判定：合格	
160	GX-B1323/21-4-23097~23098	2023. 5. 19	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。 。	

161	GX-B1323/21-4-23100~23101	2023. 5. 19	<p>本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。</p> <p>。</p>	
162	GX-B1323/21-4-23099	2023. 5. 19	<p>本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。</p> <p>。</p>	
163	GX-B1323/21-4-23102~23106	2023. 5. 19	<p>本次共检三相交流电动机5台，5台三相交流电动机所检项目合格。</p> <p>。</p>	

164	GX-B1323/21-4-23107~23108	2023. 5. 19	<p>本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。</p> <p>。</p>	
165	GX-B1323/21-4-23109~23111	2023. 5. 19	<p>本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。</p> <p>。</p>	
166	GX-B1323/21-4-23112~23113	2023. 5. 19	<p>本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。</p> <p>。</p>	

167	GX-B1323/21-4-23114~23116	2023. 5. 19	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。 。	
168	GX-B1323/21-4-23117~23118	2023. 5. 19	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。 。	
169	GX-B1323/21-4-23119~23121	2023. 5. 19	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。 。	

170	GX-B1359/21-4-23170~23177	2023. 5. 19	<p>本次共检矿用隔爆型照明信号综合保护装置8台，8台所检项目合格。</p>	
171	GX-B1328/20-4-23103	2023. 5. 19	<p>本次共检绝缘手套2只，2只所检项目合格</p>	
172	GX-B1328/20-4-23104	2023. 5. 19	<p>本次共检绝缘鞋2只，2只所检项目合格</p>	

173	GX-B1328/20-4-23105	2023. 5. 19	本次共检绝缘手套2只，2只所检项目合格	
174	GX-B1328/20-4-23106	2023. 5. 19	本次共检绝缘鞋2只，2只所检项目合格	
175	GX-B1328/20-4-23107	2023. 5. 19	所检项目合格	

176	GX-B1328/20-4-23108	2023. 5. 19	本次共检绝缘手套2只，2只所检项目合格	
177	GX-B1328/20-4-23109	2023. 5. 19	本次共检绝缘鞋2只，2只所检项目合格	
178	GX-B1328/20-4-23110	2023. 5. 19	本次共检绝缘手套10只，10只所检项目合格	

179	GX-B1328/20-4-23111	2023. 5. 19	本次共检绝缘鞋 10只，10只所检 项目合格	
180	GX-B1328/20-4-23112	2023. 5. 19	所检项目合格	
181	GX-B1328/20-4-23113	2023. 5. 19	所检项目合格	

182	GX-B1358/21-4-23005	2023. 5. 19	所检项目合格	 A worker in a dark environment, possibly a tunnel or underground facility, is performing maintenance or inspection on a track or rail system. The worker is wearing a dark uniform and a headlamp. The scene is dimly lit, with some equipment visible in the background. A red timestamp "2023.5.19" is visible in the bottom right corner of the image.
183	GX-B1495/20-4-231415~231452	2023. 5. 19	本次共检高压开关柜38台，38台所检项目合格。	 Two workers in white protective suits and hard hats are inspecting a high-voltage switchgear cabinet. The workers are wearing reflective safety gear. The scene is dimly lit, with the workers' headlamps illuminating the equipment. A white timestamp "2023/4/27" is visible in the bottom right corner of the image.
184	GX-B1495/20-4-231453~231458	2023. 5. 19	本次共检高压防爆开关6台，6台所检项目合格。	 A worker in a white protective suit and hard hat is inspecting a high-voltage explosion-proof switch. The worker is wearing reflective safety gear. The scene is dimly lit, with the worker's headlamp illuminating the equipment. A white timestamp "2023/4/28" is visible in the bottom right corner of the image.

185	GX-B1495/20-4-231471~231473	2023. 5. 19	本次共检高压开关柜3台，3台所检项目合格。	
186	GX-B1314/21-4-23017~23019	2023. 5. 19	本次共检验干式电抗器3台，3台所检项目合格。	
187	GX-B1301/21-4-23004	2023. 5. 22	综合判定:合格。	

188	GX-B1301/21-4-23005	2023. 5. 22	综合判定:合格。	
189	GX-B1301/21-4-23006	2023. 5. 22	综合判定:合格。	
190	GX-B1416/22-4-23006	2023. 5. 22	综合判定: 合格。 。	

191	GX-B1416/22-4-23007	2023. 5. 22	综合判定：合格。 。	
192	GX-B1416/22-4-23008	2023. 5. 22	综合判定：合格。 。	
193	GX-B1416/22-4-23009	2023. 5. 22	综合判定：合格。 。	

194	GX-B1416/22-4-23010	2023. 5. 22	综合判定：合格。 。			
195	GX-B1416/22-4-23011	2023. 5. 22	综合判定：合格。 。			
196	GX-B1416/22-4-23012	2023. 5. 22	综合判定：合格。 。			


197	GX-B1323/21-4-23140~23142	2023. 5. 22	<p>本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。</p> <p>。</p>			
198	GX-B1323/21-4-23249~23251	2023. 5. 23	<p>本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。</p>			
199	GX-B1312/20-4-23343~23347	2023. 5. 23	<p>本次共检电力变压器5台，5台所检项目合格。</p>			

200	GX-B1312/20-4-23348~23349	2023. 5. 23	本次共检电力变压器2台，2台所检项目合格。	
201	GX-B1321/20-4-23569~23578	2023. 5. 23	本次共检验电力电缆10条，10条所检项目合格。	
202	GX-B1328/20-4-23057	2023. 5. 23	本次共检绝缘手套44只，44只所检项目合格。	

203	GX-B1328/20-4-23058	2023. 5. 23	本次共检绝缘鞋 44只，44只所检 项目合格。	
204	GX-B1328/20-4-23059	2023. 5. 23	本次共检验电器 22只，22只所检 项目合格。	
205	GX-B1328/20-4-23060	2023. 5. 23	本次共检短路接 地线22套，22套 所检项目合格。	

206	GX-B1359/21-4-23142~23143	2023. 5. 25	<p>本次共检矿用隔爆型照明信号综合保护装置2台, 2台所检项目合格。</p> <p>。</p>	
207	GX-B1359/21-4-23144~23161	2023. 5. 25	<p>本次共检矿用隔爆型照明信号综合保护装置18台, 18台所检项目合格。</p>	
208	GX-B1359/21-4-23162~23163	2023. 5. 25	<p>本次共检矿用隔爆型照明信号综合保护装置2台, 2台所检项目合格。</p> <p>。</p>	

209	GX-B1359/21-4-23164~23165	2023. 5. 25	<p>本次共检矿用隔爆型照明信号综合保护装置2台,2台所检项目合格。</p> <p>。</p>	
210	GX-B1359/21-4-23166	2023. 5. 25	<p>所检项目合格。</p>	
211	GX-B1359/21-4-23167~23169	2023. 5. 25	<p>本次共检矿用隔爆型照明信号综合保护装置3台,3台所检项目合格。</p> <p>。</p>	

212	GX-B1321/20-4-23366~23367	2023. 5. 25	<p>本次共检电力电缆2条, 2条电力电缆所检项目合格。</p> <p>。</p>	
213	GX-B1321/20-4-23368~23378	2023. 5. 25	<p>本次共检电力电缆11条, 11条电力电缆所检项目合格。</p>	
214	GX-B1321/20-4-23379~23386	2023. 5. 25	<p>本次共检电力电缆8条, 8条电力电缆所检项目合格。</p> <p>。</p>	

215	GX-B1321/20-4-23387~23392	2023. 5. 25	<p>本次共检电力电缆6条,6条电力电缆所检项目合格。</p>	
216	GX-B1321/20-4-23393~23402	2023. 5. 25	<p>本次共检电力电缆10条,10条电力电缆所检项目合格。</p>	
217	GX-B1321/20-4-23403~23413	2023. 5. 25	<p>本次共检电力电缆11条,11条电力电缆所检项目合格。</p>	

218	GX-B1321/20-4-23414~23422	2023. 5. 25	本次共检电力电缆9条, 9条电力电缆所检项目合格。 。		
219	GX-B1321/20-4-23423~23432	2023. 5. 25	本次共检电力电缆10条, 10条电力电缆所检项目合格。		
220	GX-B1321/20-4-23433~23444	2023. 5. 25	本次共检电力电缆12条, 12条电力电缆所检项目合格。		

221	GX-B1321/20-4-23445~23455	2023. 5. 25	本次共检电力电缆11条, 11条电力电缆所检项目合格。		
222	GX-B1321/20-4-23456~23463	2023. 5. 25	本次共检电力电缆8条, 8条电力电缆所检项目合格。		
223	GX-B1321/20-4-23464~23474	2023. 5. 25	本次共检电力电缆11条, 11条电力电缆所检项目合格。		

224	GX-B1321/20-4-23475~23483	2023. 5. 25	<p>本次共检电力电缆9条, 9条电力电缆所检项目合格。</p>	
225	GX-B1321/20-4-23484~23488	2023. 5. 25	<p>本次共检电力电缆5条, 5条电力电缆所检项目合格。</p>	
226	GX-B1321/20-4-23489~23491	2023. 5. 25	<p>本次共检电力电缆3条, 3条电力电缆所检项目合格。</p>	

227	GX-B1312/20-4-23227	2023. 5. 25	所检项目合格	
228	GX-B1312/20-4-23228~23231	2023. 5. 25	本次共检电力变压器4台，4台所检项目合格	
229	GX-B1312/20-4-23232~23233	2023. 5. 25	本次共检电力变压器2台，2台所检项目合格	

230	GX-B1312/20-4-23234~23236	2023. 5. 25	本次共检电力变压器3台，3台所检项目合格	
231	GX-B1312/20-4-23237~23239	2023. 5. 25	本次共检电力变压器3台，3台所检项目合格	
232	GX-B1312/20-4-23240~23243	2023. 5. 25	本次共检电力变压器4台，4台所检项目合格	

233	GX-B1312/20-4-23244~23245	2023. 5. 25	本次共检电力变压器2台，2台所检项目合格	
234	GX-B1312/20-4-23246~23247	2023. 5. 25	本次共检电力变压器2台，2台所检项目合格	
235	GX-B1312/20-4-23248	2023. 5. 25	所检项目合格	

236	GX-B1312/20-4-23249~23253	2023. 5. 25	本次共检电力变压器5台，5台所检项目合格		
237	GX-B1312/20-4-23254~23260	2023. 5. 25	本次共检电力变压器7台，7台所检项目合格		
238	GX-B1312/20-4-23261~23270	2023. 5. 25	本次共检电力变压器10台，10台所检项目合格		

239	GX-B1312/20-4-23271	2023. 5. 25	所检项目合格	
240	GX-B1312/20-4-23272	2023. 5. 25	所检项目合格	
241	GX-B1312/20-4-23273~23276	2023. 5. 25	本次共检电力变压器4台，4台所检项目合格	

242	GX-B1428/21-4-23066	2023. 5. 26	无缺陷痕迹显示	
243	GX-B1428/21-4-23067	2023. 5. 26	无缺陷痕迹显示	
244	GX-B1310/21-4-23057	2023. 5. 26	符合标准要求	

245	GX-B1310/21-4-23059	2023. 5. 26	符合标准要求	
246	GX-B1310/21-4-23060	2023. 5. 26	符合标准要求	
247	GX-B1310/21-4-23061	2023. 5. 26	符合标准要求	

248	GX-B1310/21-4-23063	2023. 5. 26	符合标准要求	
249	GX-B1310/21-4-23064	2023. 5. 26	符合标准要求	
250	GX-B1310/21-4-23065	2023. 5. 26	符合标准要求	

251	GX-B1424/20-4-23016	2023. 5. 26	依据NB/T 10176-2019单轨吊车综合判定合格。依据MT/T220-1990尾气所检项目合格	
252	GX-B1352/21-4-23374~23378	2023. 5. 26	本次共检矿用防爆低压交流真空馈电开关5台, 5台所检项目合格。	
253	GX-B1352/21-4-23379~23393	2023. 5. 26	本次共检矿用防爆低压交流真空馈电开关15台, 15台所检项目合格。 。	

254	GX-B1352/21-4-23394~23404	2023. 5. 26	<p>本次共检矿用防爆低压交流真空馈电开关11台, 11台所检项目合格。</p> <p>。</p>	
255	GX-B1352/21-4-23405~23410	2023. 5. 26	<p>本次共检矿用防爆低压交流真空馈电开关6台, 6台所检项目合格。</p>	
256	GX-B1352/21-4-23411~23425	2023. 5. 26	<p>本次共检矿用防爆低压交流真空馈电开关15台, 15台所检项目合格。</p> <p>。</p>	

257	GX-B1352/21-4-23426~23431	2023. 5. 26	本次共检矿用防爆低压交流真空馈电开关6台,6台所检项目合格。	
258	GX-B1352/21-4-23432~23438	2023. 5. 26	本次共检矿用防爆低压交流真空馈电开关7台,7台所检项目合格。	
259	GX-B1350/21-4-23025	2023. 5. 26	所检项目合格	

260	GX-B1350/21-4-23026	2023. 5. 26	本次共检验接地装置8处，8处所检项目合格。	
261	GX-B1350/21-4-23027	2023. 5. 26	本次共检验接地装置2处，2处所检项目合格。	
262	GX-B1350/21-4-23028	2023. 5. 26	本次共检验接地装置6处，6处所检项目合格。	

263	GX-B1350/21-4-23029	2023. 5. 26	本次共检验接地装置5处，5处所检项目合格。	
-----	---------------------	-------------	-----------------------	---