

序号	报告编号	发布日期	结论	影像资料
163	GX-B1598/21-5-23017	2023/5/18	实测钢丝绳有效截面积损失百分比最大为2.28%，小于5%为正常。	
164	GX-B1598/21-5-23018	2023/5/18	实测钢丝绳有效截面积损失百分比最大为2.41%，小于5%为正常。	
165	GX-B1598/21-5-23019	2023/5/18	实测钢丝绳有效截面积损失百分比最大为3.37%，小于5%为正常。	

166	GX-B1598/21-5-23020	2023/5/18	实测钢丝绳有效截面积损失百分比最大为0.36%，小于5%为正常。			
167	GX-B1598/21-5-23021	2023/5/18	实测钢丝绳有效截面积损失百分比最大为2.73%，小于5%为正常。			
168	GX-B1424/20-5-23004	2023.05.19	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。			2023.02.24

169	GX-B1310/21-5-23133	2023/5/19	符合标准要求。	
170	GX-B1310/21-5-23134	2023/5/19	符合标准要求。	
171	GX-B1428/21-5-23014	2023/5/19	无缺陷迹痕显示。	

172	GX-B1428/21-5-23015	2023/5/19	无缺陷迹痕显示。			
173	GX-B1328/20-5-23089	2023/5/19	本次共检绝缘手套120只，120只绝缘手套合格。			
174	GX-B1328/20-5-23090	2023/5/19	本次共检绝缘鞋80只，80只绝缘鞋合格。			

175	GX-B1328/20-5-23091	2023/5/19	本次共检绝缘杆6支，6支绝缘杆合格。		
176	GX-B1328/20-5-23092	2023/5/19	本次共检携带式接地和接地短路装置25套，25套携带式接地和接地短路装置合格。		
177	GX-B1328/20-5-23093	2023/5/19	本次共检验电器30支，30支验电器合格。		

178	GX-B1499/21-5-23070	2023/5/20	所检项目合格。	
179	GX-B1499/21-5-23071	2023/5/20	所检项目合格。	

180	GX-B1499/21-5-23072	2023/5/20	所检项目合格。	
181	GX-B1499/21-5-23073	2023/5/20	所检项目合格。	

182	GX-B1499/21-5-23074	2023/5/20	所检项目合格。	 <p>2023/05/12</p>
183	GX-B1499/21-5-23075	2023/5/20	所检项目合格。	 <p>2023/05/12</p>

184	GX-B1499/21-5-23076	2023/5/20	所检项目合格。	
185	GX-B1499/21-5-23077	2023/5/20	所检项目合格。	

186	GX-B1308/21-5-23021	2023/5/20	所检项目合格。	
187	GX-B1308/21-5-23022	2023/5/20	所检项目合格。	
188	GX-B1499/21-5-23043	2023. 5. 22	合格	

189	GX-B1499/21-5-23044	2023. 5. 22	合格	
190	GX-B1499/21-5-23045	2023. 5. 22	合格	
191	GX-B1308/21-5-23016	2023. 5. 22	合格	

192	GX-B1499/21-5-23046	2023. 5. 22	所检项目合格	
193	GX-B1499/21-5-23047	2023. 5. 22	所检项目合格	
194	GX-B1499/21-5-23048	2023. 5. 22	所检项目合格	

195	GX-B1308/21-5-23017	2023. 5. 22	所检项目合格	
196	GX-B1329/21-5-23117~23123	2023. 5. 22	本次共检氧化锌避雷器7组，7组氧化锌避雷器所检项目合格。	
197	GX-B1495/20-5-23943~23951	2023. 5. 22	本次共检高压开关柜9台，9台高压开关柜所检项目合格。	

198	GX-B1495/20-5-23976~23990	2023. 5. 22	本次共检高压开关柜15台，15台高压开关柜所检项目合格。	
199	GX-B1495/20-5-23963~23968	2023. 5. 22	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	
200	GX-B1495/20-5-23952~23962	2023. 5. 22	本次共检高压开关柜11台，11台高压开关柜所检项目合格。	

201	GX-B1495/20-5-231045~231055	2023. 5. 22	本次共检高压开关柜11台，11台高压开关柜所检项目合格。	
202	GX-B1312/20-5-23260~23261	2023. 5. 22	本次共检电力变压器2台，2台电力变压器所检项目合格。	
203	GX-B1323/21-5-23122~23124	2023. 5. 22	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。	

204	GX-B1323/21-5-23118~23119	2023. 5. 22	<p>本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。</p> <p>。</p>	
205	GX-B1323/21-5-23113~23115	2023. 5. 22	<p>本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。</p> <p>。</p>	
206	GX-B1323/21-5-23110~23112	2023. 5. 22	<p>本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。</p> <p>。</p>	

207	:GX-B1323/21-5-23120~23121	2023. 5. 22	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。	
208	GX-B1312/20-5-23284~23285	2023. 5. 22	本次共检电力变压器2台，2台电力变压器所检项目合格。	
209	GX-B1323/21-5-23125~23127	2023. 5. 22	本次共检交流电动机3台，3台交流电动机所检项目合格。	

210	GX-B1323/21-5-23116~23117	2023. 5. 22	<p>本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。</p> <p>。</p>	
211	GX-B1312/20-5-23247~23248	2023. 5. 22	<p>本次共检电力变压器2台，2台电力变压器所检项目合格。</p>	
212	GX-B1312/20-5-23249~23252	2023. 5. 22	<p>本次共检电力变压器4台，4台电力变压器所检项目合格。</p>	

213	GX-B1312/20-5-23282~23283	2023. 5. 22	本次共检电力变压器2台，2台电力变压器所检项目合格。	
214	GX-B1495/20-5-231245~231250	2023. 5. 22	本次共检高压防爆开关6台，6台高压防爆开关所检项目合格。	
215	GX-B1354/20-5-23006	2023/5/22	电网接地电容电流符合规定。	

216	GX-B1354/20-5-23007	2023/5/22	电网接地电容电流符合规定。	
217	GX-B1352/21-5-23812~23828	2023/5/22	本次共检矿用防爆低压交流真空馈电开关漏电保护17台, 17台所检项目合格。	

218	GX-B1352/21-5-23242~23268	2023/5/22	<p>本次共检矿用防爆低压交流真空馈电开关27台,27台所检项目合格。</p>	
219	GX-B1309/21-5-23018	2023. 5. 22	<p>综合判定：合格。</p>	

220	GX-B1500/21-5-23076	2023. 5. 22	综合判定：合格。 。	
221	GX-B1500/21-5-23077	2023. 5. 22	综合判定：合格。 。	

222	GX-B1500/21-5-23078	2023. 5. 22	综合判定：合格。 。	
223	GX-B1500/21-5-23079	2023. 5. 22	综合判定：合格。 。	

224	GX-B1500/21-5-23080	2023. 5. 22	综合判定：合格。 。	 A worker wearing a blue uniform and a red hard hat is standing in an industrial environment, possibly a tunnel or underground facility. The worker is looking down at a device or piece of equipment. The background shows concrete walls and some machinery. A yellow timestamp '2023-4-25' is visible in the bottom right corner of the photo.
225	GX-B1309/21-5-23015	2023. 5. 22	综合判定：合格。 。	 A worker wearing a blue uniform and a red hard hat is working on a large, light-colored pipe in a tunnel. The worker is positioned on a wooden structure, possibly a ladder or scaffolding, and is focused on the pipe. The tunnel walls are rough and rocky. A yellow timestamp '2023-4-24' is visible in the bottom right corner of the photo.

226	GX-B1500/21-5-23064	2023. 5. 22	综合判定：合格。 。	
227	GX-B1500/21-5-23065	2023. 5. 22	综合判定：合格。 。	

228	GX-B1500/21-5-23066	2023. 5. 22	综合判定：合格。 。	
229	GX-B1500/21-5-23067	2023. 5. 22	综合判定：合格。 。	

230	GX-B1500/21-5-23068	2023. 5. 22	综合判定：合格。 。	 <p>2023/4/24</p>
231	GX-B1309/21-5-23019	2023. 5. 22	综合判定：合格。 。	 <p>2023/4/25</p>

232	GX-B1500/21-5-23081	2023. 5. 22	综合判定：合格。 。	
233	GX-B1500/21-5-23082	2023. 5. 22	综合判定：合格。 。	

234	GX-B1500/21-5-23083	2023. 5. 22	综合判定：合格。 。	
235	GX-B1500/21-5-23084	2023. 5. 22	综合判定：合格。 。	

236	GX-B1309/21-5-23016	2023. 5. 22	综合判定：合格。 。	
237	GX-B1500/21-5-23069	2023. 5. 22	综合判定：合格。 。	

238	GX-B1500/21-5-23070	2023. 5. 22	综合判定：合格。 。	
239	GX-B1500/21-5-23071	2023. 5. 22	综合判定：合格。 。	

240	GX-B1309/21-5-23017	2023. 5. 22	综合判定：合格。 。	
241	GX-B1500/21-5-23072	2023. 5. 22	综合判定：合格。 。	

242	GX-B1500/21-5-23073	2023. 5. 22	综合判定：合格。 。	
243	GX-B1500/21-5-23074	2023. 5. 22	综合判定：合格。 。	

244	GX-B1500/21-5-23075	2023. 5. 22	综合判定：合格。 。	
245	GX-B1309/21-5-23021	2023. 5. 22	综合判定：合格。 。	

246	GX-B1500/21-5-23089	2023. 5. 22	综合判定：合格。 。	
247	GX-B1500/21-5-23090	2023. 5. 22	综合判定：合格。 。	

248	GX-B1500/21-5-23091	2023. 5. 22	综合判定：合格。 。	
249	GX-B1500/21-5-23092	2023. 5. 22	综合判定：合格。 。	
250	GX-B1416/22-5-23019	2023年5月23日	合格	

251	GX-B1416/22-5-23020	2023年5月23日	合格	
252	GX-B1416/22-5-23021	2023年5月23日	合格	
253	GX-B1404/20-5-23013	2023. 5. 23	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	

254	GX-B1404/20-5-23014	2023. 5. 23	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		
255	GX-B1404/20-5-23015	2023. 5. 23	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		
256	GX-B1404/20-5-23020	2023/5/23	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		


257	GX-B1404/20-5-23021	2023/5/23	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	
258	GX-B1309/21-5-23020	2023/5/23	<p>综合判定：合格。</p>	
259	GX-B1500/21-5-23085	2023/5/23	<p>综合判定：合格。</p>	

260	GX-B1500/21-5-23086	2023/5/23	综合判定：合格。 。	
261	GX-B1500/21-5-23087	2023/5/23	综合判定：合格。 。	
262	GX-B1500/21-5-23088	2023/5/23	综合判定：合格。 。	

263	GX-B1350/21-5-23051	2023/5/23	本次共检接地装置4处，4处接地装置所检项目合格。			
264	GX-B1306/21-5-23034	2023/5/23	所检项目合格。			
265	GX-B1306/21-5-23035	2023/5/23	所检项目合格。			

266	GX-B1306/21-5-23036	2023/5/23	所检项目合格。			
267	GX-B1306/21-5-23037	2023/5/23	所检项目合格。			
268	GX-B1306/21-5-23038	2023/5/23	所检项目合格。			

269	GX-B1328/20-5-23072	2023/5/23	本次共检绝缘手套120只，120只绝缘手套合格。		
270	GX-B1328/20-5-23073	2023/5/23	本次共检绝缘鞋80只，80只绝缘鞋合格。		
271	GX-B1328/20-5-23074	2023/5/23	本次共检携带式接地和接地短路装置25套，25套携带式接地和接地短路装置合格。		

272	GX-B1328/20-5-23075	2023/5/23	本次共检验电器 30支，30支验电 器合格。		
273	GX-B1328/20-5-23076	2023/5/23	本次共检绝缘杆 6支，6支绝缘杆 合格。		
274	GX-B1495/20-5-231251	2023. 5. 23	所检项目合格。		

275	GX-B1312/20-5-23350~23352	2023. 5. 23	本次共检电力变压器3台，3台电力变压器所检项目合格。	
276	GX-B1312/20-5-23353~23355	2023. 5. 23	本次共检电力变压器3台，3台电力变压器所检项目合格。	
277	GX-B1324/21-5-23128	2023. 5. 23	本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。	

278	GX-B1312/20-5-23266~23268	2023. 5. 23	本次共检电力变压器3台，3台电力变压器所检项目合格。	
279	GX-B1312/20-5-23265	2023. 5. 23	所检项目合格。	
280	GX-B1312/20-5-23276~23281	2023. 5. 23	本次共检电力变压器6台，6台电力变压器所检项目合格。	

281	GX-B1495/20-5-231056~231057	2023. 5. 23	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
282	GX-B1495/20-5-23969~23975	2023. 5. 23	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
283	GX-B1495/20-5-23935~23942	2023. 5. 23	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	 

284	GX-B1495/20-5-231029~231044	2023. 5. 23	本次共检高压开关柜16台，16台高压开关柜所检项目合格。	
285	GX-B1495/20-5-231058~231066	2023. 5. 23	本次共检高压开关柜9台，9台高压开关柜所检项目合格。	
286	GX-B1312/20-5-23262	2023. 5. 23	所检项目合格。	

287	GX-B1328/20-5-23083	2023/5/23	本次共检绝缘手套4只，4只绝缘手套合格。			
288	GX-B1328/20-5-23084	2023/5/23	本次共检绝缘鞋4只，4只绝缘鞋合格。			
289	GX-B1328/20-5-23085	2023/5/23	所检项目合格。			

290	GX-B1328/20-5-23086	2023/5/23	所检项目合格。		
291	GX-B1328/20-5-23087	2023/5/23	本次共检携带式接地和接地短路装置2套，2套携带式接地和接地短路装置合格。		
292	GX-B1417/22-5-23021	2023. 5. 24	综合判定：合格。		

293	GX-B1417/22-5-23022	2023. 5. 24	综合判定：合格。 。	
294	GX-B1417/22-5-23023	2023. 5. 24	综合判定：合格。 。	
295	GX-B1417/22-5-23024	2023. 5. 24	综合判定：合格。 。	

296	GX-B1417/22-5-23025	2023. 5. 24	综合判定：合格。 。	
297	GX-B1428/21-5-23016	2023. 5. 24	无缺陷迹痕显示。 。	
298	GX-B1428/21-5-23017	2023. 5. 24	无缺陷迹痕显示。 。	

299	GX-B1427/21-5-23011	2023. 5. 24	符合标准要求。	
300	GX-B1427/21-5-23012	2023. 5. 24	符合标准要求。	
301	GX-B1352/21-5-23220~23241	2023. 5. 24	<p>本次共检矿用防爆低压交流真空馈电开关 22台, 22台矿用防爆低压交流真空馈电开关所检项目合格。</p>	

302	GX-B1306/21-5-23031	2023. 5. 24	所检项目合格	
303	GX-B1306/21-5-23032	2023. 5. 24	所检项目合格	
304	GX-B1306/21-5-23033	2023. 5. 24	所检项目合格	

305	GX-B1352/21-5-23269~23283	45071	<p>本次共检矿用防爆低压交流真空馈电开关15台，15台所检项目合格。</p>	
306	GX-B1352/21-5-23284~23286	45071	<p>本次共检矿用防爆低压交流真空馈电开关3台，3台所检项目合格。</p>	
307	GX-B1352/21-5-23829~23833	45071	<p>本次共检矿用防爆低压交流真空馈电开关漏电保护5台，5台所检项目合格。</p>	

308	GX-B1354/20-5-23010	2023. 5. 25	电网接地电容电流符合规定。	
309	GX-B1351/21-5-23001~23002	2023. 5. 25	本次共检矿用隔爆型检漏继电器2台,2台矿用隔爆型检漏继电器所检项目合格。	
310	GX-B1351/21-5-23003~23004	2023. 5. 25	本次共检矿用隔爆型检漏继电器2台,2台矿用隔爆型检漏继电器所检项目合格。	

311	GX-B1350/21-5-23053	2023. 5. 25	本次共检验接地装置10处，10处所检项目全部合格。	
312	GX-B1350/21-5-23054	2023. 5. 25	本次共检验接地装置12处，12处所检项目全部合格。	
313	GX-B1358/21-5-23002	2023. 5. 25	所检项目合格。	

