




序号	报告编号	发布日期	结论	影像资料
314	GX-B1310/21-5-23114	2023. 5. 25	符合标准要求。	
315	GX-B1310/21-5-23115	2023. 5. 25	符合标准要求。	

316	GX-B1310/21-5-23116	2023. 5. 25	符合标准要求。	
317	GX-B1310/21-5-23117	2023. 5. 25	符合标准要求。	
318	GX-B1321/20-5-23583~23590	2023. 5. 25	本次共检电力电缆 8条，8条电力电缆所 检项目合格。	 

319	GX-B1312/20-5-23368~23369	2023. 5. 25	本次共检电力变压器2台，2台电力变压器所检项目合格。	
320	GX-B1328/20-5-23099	2023/5/25	本次共检绝缘手套12只，12只绝缘手套合格。	
321	GX-B1328/20-5-23100	2023/5/25	本次共检绝缘鞋12只，12只绝缘鞋合格。	

322	GX-B1310/21-5-23135	2023/5/25	符合标准要求。	 <p>The top row of images shows two workers in red hard hats and dark clothing. The left image shows a worker in a dark jacket and red helmet operating a green industrial machine. The right image shows a worker in a red helmet inside a glass-enclosed industrial machine. The bottom image shows a worker in a red helmet and dark jacket operating a large blue industrial machine with a red control panel.</p>
-----	---------------------	-----------	---------	---

323	GX-B1310/21-5-23136	2023/5/25	符合标准要求。	 
324	GX-B1310/21-5-23137	2023/5/25	符合标准要求。	

325	GX-B1310/21-5-23138	2023/5/25	符合标准要求。		 2023年4月20日	
326	GX-B1310/21-5-23139	2023/5/25	符合标准要求。		 2023年4月20日	
327	GX-B1310/21-5-23140	2023/5/25	符合标准要求。		 2023年4月20日	

328	GX-B1310/21-5-23141	2023/5/25	符合标准要求。	 <p>2023年4月20日</p>
329	GX-B1310/21-5-23142	2023/5/25	符合标准要求。	 <p>2023年4月20日</p>
330	GX-B1495/20-5-231275~231276	2023. 5. 25	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	 <p>2023.5.12</p>




331	GX-B1310/21-5-23147	2023/5/25	符合标准要求。		
332	GX-B1310/21-5-23148	2023/5/25	符合标准要求。		
333	GX-B1310/21-5-23149	2023/5/25	符合标准要求。		



334	GX-B1310/21-5-23150	2023/5/25	符合标准要求。			
335	GX-B1310/21-5-23151	2023/5/25	符合标准要求。			
336	GX-B1310/21-5-23152	2023/5/25	符合标准要求。			



337	GX-B1359/21-5-23092~23125	2023/5/25	<p>本次共检矿用隔爆型照明信号综合保护装置34台，34台所检项目合格。</p>	
338	GX-B1359/21-5-23126~23132	2023/5/25	<p>本次共检矿用隔爆型照明信号综合保护装置7台，7台所检项目合格。</p>	

339	GX-B1359/21-5-23136~23138	2023/5/25	<p>本次共检矿用隔爆型照明信号综合保护装置3台，3台所检项目合格。</p>	
340	GX-B1310/21-5-23143	2023/5/25	符合标准要求。	
341	GX-B1310/21-5-23144	2023/5/25	符合标准要求。	

342	GX-B1310/21-5-23145	2023/5/25	符合标准要求。	 A photograph showing a worker in a red hard hat and black clothing inspecting a large, teal-colored industrial fan component. The fan has multiple blades and a central hub. A date stamp '2023/4/4' is visible in the bottom right corner of the image.
343	GX-B1310/21-5-23146	2023/5/25	符合标准要求。	 A photograph showing a worker in a red hard hat and black clothing inspecting a large, teal-colored industrial fan component. The fan has multiple blades and a central hub. A date stamp '2023/4/4' is visible in the bottom right corner of the image.
344	GX-B1428/21-5-23020	2023/5/25	无缺陷迹痕显示。	 A photograph showing a worker in a red hard hat and black clothing inspecting a large, teal-colored industrial fan component. The fan has multiple blades and a central hub. A date stamp '2023/4/4' is visible in the bottom right corner of the image.

345	GX-B1428/21-5-23021	2023/5/25	无缺陷迹痕显示。	
346	GX-B1499/21-5-23067	2023. 5. 26	所检项目合格。	
347	GX-B1499/21-5-23068	2023. 5. 26	所检项目合格。	

348	GX-B1499/21-5-23069	2023. 5. 26	除吨水百米电耗不经济外，其余所检项目合格。	
349	GX-B1321/20-5-23573~23581	2023/5/26	本次共检电力电缆9条，9条电力电缆所检项目合格。	
350	GX-B1312/20-5-23234~23239	2023/5/26	本次共检电力变压器6台，6台电力变压器所检项目合格。	

351	GX-B1312/20-5-23349	2023/5/26	所检项目合格。	 <p>2023/4/3</p>
352	GX-B1321/20-5-23566~23572	2023/5/26	本次共检电力电缆7条，7条电力电缆所检项目合格。	 <p>2023/4/3</p>
353	GX-B1499/21-5-23049	2023. 5. 26	所检项目合格	 <p>2023. 4. 30</p>

354	GX-B1499/21-5-23050	2023. 5. 26	所检项目合格	
355	GX-B1499/21-5-23051	2023. 5. 26	所检项目合格	
356	GX-B1499/21-5-23052	2023. 5. 26	所检项目合格	



357	GX-B1499/21-5-23053	2023. 5. 26	所检项目合格	
358	GX-B1499/21-5-23054	2023. 5. 26	所检项目合格	
359	GX-B1499/21-5-23055	2023. 5. 26	所检项目合格	

360	GX-B1499/21-5-23056	2023. 5. 26	所检项目合格	
361	GX-B1499/21-5-23057	2023. 5. 26	所检项目合格	
362	GX-B1308/21-5-23009、23010、23011	2023. 5. 26	所检项目合格	  