

序号	报告编号	发布日期	结论	影像资料
305	GX-B1382/21-6-23013	2023/5/14	合格	
306	GX-B1382/21-6-23015	2023/5/14	合格	
307	GX-B1517/20-6-23002	2023/5/16	综合判定合格	

308	GX-B1517/20-6-23003	2023/5/16	综合判定合格		
309	GX-B1548/20-6-23008	2023/5/16	所检项目合格		
310	GX-B1423/20-6-23369	2023/5/19	合格		

311	GX-B1423/20-6-23370	2023/5/19	合格		
312	GX-B1423/20-6-23371	2023/5/19	合格		
313	GX-B1423/20-6-23372	2023/5/19	合格		

314	GX-B1423/20-6-23373	2023/5/19	合格		
315	GX-B1423/20-6-23374	2023/5/19	合格		
316	GX-B1423/20-6-23375	2023/5/19	合格		

317	GX-B1423/20-6-23376	2023/5/19	合格			
318	GX-B1423/20-6-23377	2023/5/19	合格			
319	GX-B1423/20-6-23378	2023/5/19	合格			

320	GX-B1423/20-6-23379	2023/5/19	合格			
321	GX-B1423/20-6-23380	2023/5/19	合格			
322	GX-B1423/20-6-23381	2023/5/19	合格			

323	GX-B1423/20-6-23382	2023/5/19	合格			
324	GX-B1423/20-6-23383	2023/5/19	合格			
325	GX-B1423/20-6-23384	2023/5/19	合格			

326	GX-B1423/20-6-23385	2023/5/19	合格			
327	GX-B1423/20-6-23386	2023/5/19	合格			
328	GX-B1423/20-6-23387	2023/5/19	合格			

329	GX-B1423/20-6-23388	2023/5/19	合格			
330	GX-B1423/20-6-23389	2023/5/19	合格			
331	GX-B1423/20-6-23390	2023/5/19	合格			

332	GX-B1423/20-6-23391	2023/5/19	合格			
333	GX-B1423/20-6-23392	2023/5/19	合格			
334	GX-B1423/20-6-23393	2023/5/19	合格			

335	GX-B1423/20-6-23394	2023/5/19	合格	
336	GX-B1423/20-6-23395	2023/5/19	合格	
337	GX-B1423/20-6-23396	2023/5/19	合格	

338	GX-B1423/20-6-23397	2023/5/19	合格			
339	GX-B1423/20-6-23398	2023/5/19	合格			
340	GX-B1423/20-6-23399	2023/5/19	合格			

341	GX-B1423/20-6-23400	2023/5/19	合格	 A photograph of a green truck with a white grille and a logo. Two workers in red hard hats and work clothes stand in front of the truck. The license plate is yellow and partially visible. A timestamp '2023-4-24' is in the bottom right corner.
342	GX-B1423/20-6-23401	2023/5/19	合格	 A photograph of a red truck with a white grille and a logo. Two workers in red hard hats and work clothes stand in front of the truck. The license plate is yellow and reads '桂G 34794H'. A timestamp '2023-4-24' is in the bottom right corner.
343	GX-B1423/20-6-23402	2023/5/19	合格	 A photograph of a green truck with a white grille and a logo. Two workers in red hard hats and work clothes stand in front of the truck. The license plate is yellow and reads '桂D 01528'. A timestamp '2023-4-24' is in the bottom right corner.

344	GX-B1423/20-6-23403	2023/5/19	合格			
345	GX-B1423/20-6-23404	2023/5/19	合格			
346	GX-B1423/20-6-23405	2023/5/19	合格			

347	GX-B1423/20-6-23406	2023/5/19	合格		
348	GX-B1423/20-6-23407	2023/5/19	合格		
349	GX-B1423/20-6-23408	2023/5/19	合格		

350	GX-B1423/20-6-23409	2023/5/19	合格		
351	GX-B1423/20-6-23410	2023/5/19	合格		
352	GX-B1423/20-6-23411	2023/5/19	合格		

353	GX-B1423/20-6-23412	2023/5/19	合格		
354	GX-B1423/20-6-23413	2023/5/19	合格		
355	GX-B1423/20-6-23414	2023/5/19	合格		

356	GX-B1423/20-6-23415	2023/5/19	合格		
357	GX-B1423/20-6-23416	2023/5/19	合格		
358	GX-B1423/20-6-23417	2023/5/19	合格		

359	GX-B1423/20-6-23418	2023/5/19	合格			
360	GX-B1423/20-6-23419	2023/5/19	合格			
361	GX-B1423/20-6-23420	2023/5/19	合格			

362	GX-B1423/20-6-23421	2023/5/19	合格			
363	GX-B1423/20-6-23422	2023/5/19	合格			
364	GX-B1423/20-6-23423	2023/5/19	合格			

365	GX-B1423/20-6-23424	2023/5/19	合格		
366	GX-B1423/20-6-23425	2023/5/19	合格		
367	GX-B1423/20-6-23426	2023/5/19	合格		

368	GX-B1423/20-6-23446	2023/5/19	综合判定：合格	
369	GX-B1423/20-6-23447	2023/5/19	综合判定：合格	
370	GX-B1423/20-6-23448	2023/5/19	综合判定：合格	

371	GX-B1423/20-6-23449	2023/5/19	综合判定：合格			
372	GX-B1520/20-6-23048	2023/5/19	综合判定合格			
373	GX-B1520/20-6-23049	2023/5/19	综合判定合格			

374	GX-B1520/20-6-23050	2023/5/19	综合判定合格			
375	GX-B1520/20-6-23051	2023/5/19	综合判定合格			
376	GX-B1520/20-6-23052	2023/5/19	综合判定合格			

377	GX-B1303/21-6-23007	2023/5/22	综合判定：合格。	
378	GX-B1350/21-6-23026	2023/5/22	本次共检接地装置2处，2处接地装置所检项目合格。	
379	GX-B1310/21-6-23057	2023/5/17	符合标准要求	

380	GX-B1427/21-6-23042	2023/5/17	符合标准要求	
381	GX-B1324/21-6-23034~ 23035	2023/5/22	所检项目合格	
382	GX-B1352/21-6-23311~ 23331	2023/5/22	本次共检矿用防 爆低压交流真空 馈电开关21台,21 台所检项目合格 。	

383	GX-B1350/21-6-23030	2023/5/23	所检项目合格	 <p>2023.05.04</p>
384	GX-B1310/21-6-23056	2023/5/19	符合标准要求	 <p>2023.04.21</p>
385	GX-B1427/21-6-23041	2023/5/19	符合标准要求	 <p>2023.04.21</p>

386	GX-B1495/20-6-23611~ 23616	2023/5/18	本次共检高压 防爆开关6台，6 台高压防爆开关 所检项目合格。		
387	GX-B1495/20-6-23617~ 23627	2023/5/18	本次共检高压防 爆开关11台，11 台高压防爆开关 所检项目合格。		
388	GX-B1495/20-6-23628~ 23629	2023/5/18	本次共检高压防 爆开关2台，2台 高压防爆开关所 检项目合格。		

389	GX-B1495/20-6-23630~ 23638	2023/5/22	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	
390	GX-B1495/20-6-23639~ 23642	2023/5/22	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	
391	GX-B1495/20-6-23643~ 23652	2023/5/22	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	

392	GX-B1495/20-6-23653~ 23672	2023/5/22	本次共检高压防爆开关20台，20台高压防爆开关所检项目合格。		 <span data-bbox="1825 470 1892 486">2023 04 06</span>
393	GX-B1495/20-6-23673~ 23680	2023/5/18	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。		 <span data-bbox="1825 805 1892 821">2023 04 07</span>
394	GX-B1495/20-6-23681~ 23684	2023/5/22	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。		 <span data-bbox="1825 1141 1892 1157">2023 04 08</span>

395	GX-B1495/20-6-23685~ 23692	2023/5/22	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	
396	GX-B1495/20-6-23693~ 23700	2023/5/22	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
397	GX-B1495/20-6-23701~ 23723	2023/5/22	本次共检高压开关柜23台，23台高压开关柜所检项目合格。	

398	GX-B1495/20-6-23724~23726	2023/5/19	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	
399	GX-B1495/20-6-23727~23736	2023/5/19	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
400	GX-B1323/21-6-23128~23136	2023/5/24	所检项目合格	

401	GX-B1381/20-6-23004	2023/5/24	所检项目合格	
402	GX-B1328/20-6-23073	2023/5/23	<p>本次共检绝缘手套6只，6只绝缘手套所检项目合格。</p>	
403	GX-B1328/20-6-23074	2023/5/23	<p>本次共检全橡胶绝缘胶靴4只，4只全橡胶绝缘胶靴所检项目合格。</p>	

404	GX-B1328/20-6-23075	2023/5/23	本次共检验电器3支，3支验电器所检项目合格。	
405	GX-B1328/20-6-23076	2023/5/23	所检项目合格	
406	GX-B1313/21-6-23079-23081	2023/5/23	本次共检电力变压器3台，3台电力变压器所检项目合格。	

407	GX-B1322/21-6-23146~ 23151	2023/5/23	本次共检验电力 电缆6条，6条电 力电缆所检项目 合格。			
408	GX-B1322/21-6-23152~ 23156	2023/5/25	本次共检验电力 电缆5条，5条电 力电缆所检项目 合格。			
409	GX-B1313/21-6-23148~ 23149	2023/5/23	本次共检电力变 压器2台，2台变 压器所检项目合 格。			

410	GX-B1451/20-6-23509~ 23516	2023/5/25	所检项目合格		 <p>2023 05 04</p>
411	GX-B1313/21-6-23172~ 23174	2023/5/25	所检项目合格		 <p>2023 05 04</p>
412	GX-B1451/20-6-23231~ 23239	2023/5/25	所检项目合格		 <p>2023 04 26</p>

413	GX-B1312/20-6-23181~23187	2023/5/25	本次共检电力变压器7台，7台电力变压器所检项目合格。	
414	GX-B1312/20-6-23188~23193	2023/5/25	本次共检电力变压器6台，6台电力变压器所检项目合格。	
415	GX-B1354/20-6-23006	2023/5/26	电网接地电容电流符合规定。	

416	GX-B1354/20-6-23007	2023/5/26	电网接地电容电流符合规定。			
417	GX-B1423/20-6-23274	2023/5/18	综合判定：合格			
418	GX-B1423/20-6-23275	2023/5/18	综合判定：合格			

419	GX-B1423/20-6-23276	2023/5/18	综合判定：合格			
420	GX-B1423/20-6-23277	2023/5/18	综合判定：合格			
421	GX-B1423/20-6-23278	2023/5/18	综合判定：合格			

422	GX-B1423/20-6-23279	2023/5/18	综合判定：合格		
423	GX-B1423/20-6-23280	2023/5/18	综合判定：合格		
424	GX-B1423/20-6-23281	2023/5/18	综合判定：合格		

425	GX-B1423/20-6-23282	2023/5/18	综合判定：合格			
426	GX-B1423/20-6-23283	2023/5/18	综合判定：合格			
427	GX-B1423/20-6-23284	2023/5/18	综合判定：合格			

428	GX-B1423/20-6-23285	2023/5/18	综合判定：合格			
429	GX-B1423/20-6-23286	2023/5/18	综合判定：合格			
430	GX-B1423/20-6-23287	2023/5/18	综合判定：合格			

431	GX-B1423/20-6-23288	2023/5/18	综合判定：合格		
432	GX-B1423/20-6-23450	2023/5/26	综合判定：合格		
433	GX-B1423/20-6-23451	2023/5/26	综合判定：合格		

434	GX-B1423/20-6-23452	2023/5/26	综合判定：合格		
435	GX-B1423/20-6-23453	2023/5/26	综合判定：合格		
436	GX-B1423/20-6-23454	2023/5/26	综合判定：合格		

437	GX-B1423/20-6-23455	2023/5/26	综合判定：合格	
438	GX-B1423/20-6-23456	2023/5/26	综合判定：合格	
439	GX-B1423/20-6-23457	2023/5/26	综合判定：合格	

440	GX-B1423/20-6-23458	2023/5/26	综合判定：合格	
441	GX-B1423/20-6-23459	2023/5/26	综合判定：合格	
442	GX-B1423/20-6-23460	2023/5/26	综合判定：合格	

443	GX-B1423/20-6-23461	2023/5/26	综合判定：合格		
444	GX-B1423/20-6-23462	2023/5/26	综合判定：合格		
445	GX-B1423/20-6-23463	2023/5/26	综合判定：合格		

446	GX-B1423/20-6-23464	2023/5/26	综合判定：合格			
447	GX-B1423/20-6-23465	2023/5/26	综合判定：合格			
448	GX-B1423/20-6-23466	2023/5/26	综合判定：合格			

449	GX-B1423/20-6-23467	2023/5/26	综合判定：合格	
450	GX-B1423/20-6-23468	2023/5/26	综合判定：合格	
451	GX-B1423/20-6-23469	2023/5/26	综合判定：合格	

452	GX-B1424/20-6-23010	2023/5/26	依据NB/T 10176-2019单轨吊车综合判定合格。		 <p>2023 04 23</p>
453	GX-B1424/20-6-23011	2023/5/26	依据NB/T 10176-2019单轨吊车综合判定合格。		 <p>2023 04 23</p>
454	GX-B1423/20-6-23502	2023/5/26	综合判定：合格		 <p>2023 5 20</p>

455	GX-B1423/20-6-23503	2023/5/26	综合判定：合格	 A yellow truck is parked in a large industrial building. Two workers wearing hard hats and work clothes stand in front of the truck. The date '2023 5 20' is visible in the bottom right corner of the photo.
456	GX-B1423/20-6-23504	2023/5/26	综合判定：合格	 A yellow truck is parked in a large industrial building. Two workers wearing hard hats and work clothes stand in front of the truck. The date '2023 5 20' is visible in the bottom right corner of the photo.
457	GX-B1423/20-6-23505	2023/5/26	综合判定：合格	 A yellow truck is parked in a large industrial building. Two workers wearing hard hats and work clothes stand in front of the truck. The date '2023 5 20' is visible in the bottom right corner of the photo.

458	GX-B1423/20-6-23506	2023/5/26	综合判定：合格		
459	GX-B1423/20-6-23507	2023/5/26	综合判定：合格		
460	GX-B1423/20-6-23508	2023/5/26	综合判定：合格		

461	GX-B1423/20-6-23509	2023/5/26	综合判定：合格		
462	GX-B1423/20-6-23510	2023/5/26	综合判定：合格		
463	GX-B1423/20-6-23511	2023/5/26	综合判定：合格		

464	GX-B1423/20-6-23512	2023/5/26	综合判定：合格	
465	GX-B1499/21-6-23016	2023/5/26	所检项目合格	
466	GX-B1499/21-6-23017	2023/5/26	所检项目合格	

467	GX-B1308/21-6-23004	2023/5/26	所检项目合格	
468	GX-B1499/21-6-23018	2023/5/26	所检项目合格	
469	GX-B1499/21-6-23019	2023/5/26	所检项目合格	
470	GX-B1499/21-6-23020	2023/5/26	所检项目合格	

471	GX-B1308/21-6-23006	2023/5/26	所检项目合格	 <p>2023 05 11</p>
472	GX-B1499/21-6-23024	2023/5/26	所检项目合格	 <p>2023 05 11</p>
473	GX-B1499/21-6-23025	2023/5/26	所检项目合格	 <p>2023 05 11</p>

474	GX-B1499/21-6-23026	2023/5/26	所检项目合格	 <p>2023 05 11</p>
475	GX-B1308/21-6-23005	2023/5/26	所检项目合格	 <p>2023 05 11</p>
476	GX-B1499/21-6-23021	2023/5/26	所检项目合格	 <p>2023 05 11</p>

477	GX-B1499/21-6-23022	2023/5/26	所检项目合格			
478	GX-B1499/21-6-23023	2023/5/26	所检项目合格			



















































































































