

序号	报告编号	发布日期	结论	影像资料
230	GX-B1362/20-A-23199	2023/5/18	安全系数结果7.60, 其余所检项目合格	
231	GX-B1362/20-A-23200	2023/5/18	安全系数结果7.61, 其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
232	GX-B1362/20-A-23201	2023/5/18	安全系数结果7.72, 其余所检项目合格	
233	GX-B1362/20-A-23202	2023/5/18	合格	

序号	报告编号	发布日期	结论	影像资料
234	GX-B1362/20-A-23203	2023/5/18	合格	
235	GX-B1362/20-A-23204	2023/5/18	合格	

序号	报告编号	发布日期	结论	影像资料
236	GX-B1362/20-A-23205	2023/5/18	合格	
237	GX-B1362/20-A-23206	2023/5/18	合格	

序号	报告编号	发布日期	结论	影像资料
238	GX-B1362/20-A-23207	2023/5/18	合格	
239	GX-B1362/20-A-23209	2023/5/18	安全系数结果7.86, 其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
240	GX-B1361/22-A-23423	2023/5/19	合格	
241	GX-B1361/22-A-23384	2023/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
242	GX-B1361/22-A-23385	2023/5/22	所检项目合格	
243	GX-B1361/22-A-23386	2023/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
244	GX-B1361/22-A-23387	2023/5/22	所检项目合格	
245	GX-B1362/20-A-23210	2023/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
246	GX-B1362/20-A-23211	2023/5/22	所检项目合格	
247	GX-B1362/20-A-23212	2023/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
248	GX-B1362/20-A-23213	2023/5/22	所检项目合格	
249	GX-B1361/22-A-23404	2023/5/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1361/22-A-23405	2023/5/23	不合格	
251	GX-B1361/22-A-23427	2023/5/23	合格	

序号	报告编号	发布日期	结论	影像资料
252	GX-B1361/22-A-23428	2023/5/23	合格	
253	GX-B1361/22-A-23429	2023/5/23	合格	

序号	报告编号	发布日期	结论	影像资料
254	GX-B1361/22-A-23388	2023/5/23	不合格	 A photograph showing a worker in a grey jacket operating a large industrial machine in a factory. The worker is focused on the task, and the machine has a yellow warning sign. The date '2023/5/4' is visible in the bottom right corner of the image.
255	GX-B1361/22-A-23389	2023/5/23	所检项目合格	 A photograph showing two workers in grey jackets operating a large industrial machine in a factory. The workers are focused on their tasks, and the machine has a yellow warning sign. The date '2023/5/4' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
256	GX-B1361/22-A-23390	2023/5/23	所检项目合格	
257	GX-B1361/22-A-23393	2023/5/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
258	GX-B1361/22-A-23394	2023/5/23	所检项目合格	
259	GX-B1361/22-A-23444	2023/5/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1361/22-A-23445	2023/5/24	所检项目合格	
261	GX-B1361/22-A-23446	2023/5/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
262	GX-B1361/22-A-23395	2023/5/26	所检项目合格	
263	GX-B1361/22-A-23396	2023/5/26	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
264	GX-B1361/22-A-23397	2023/5/26	所检项目合格	
265	GX-B1361/22-A-23398	2023/5/26	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
266	GX-B1361/22-A-23399	2023/5/26	所检项目合格	 A photograph showing two workers in a workshop. One worker is operating a large piece of machinery, possibly a lathe or mill, while the other is working on a different piece of equipment. The date '2023/5/6' is visible in the bottom right corner of the image.
267	GX-B1361/22-A-23400	2023/5/26	所检项目合格	 A photograph showing two workers in a workshop. One worker is operating a large piece of machinery, possibly a lathe or mill, while the other is working on a different piece of equipment. The date '2023/5/6' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
268	GX-B1361/22-A-23401	2023/5/26	所检项目合格	
269	GX-B1361/22-A-23403	2023/5/26	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
270	GX-B1361/22-A-23406	2023/5/25	所检项目合格	 A photograph showing a worker in a grey uniform operating a large industrial machine in a factory. Another worker is visible in the background. A yellow timestamp '2023/5/7' is in the bottom right corner.
271	GX-B1361/22-A-23407	2023/5/25	不合格	 A photograph showing a worker in a grey uniform inspecting a large, perforated metal plate. Another worker is visible in the background. A yellow timestamp '2023/5/7' is in the bottom right corner.

序号	报告编号	发布日期	结论	影像资料
272	GX-B1361/22-A-23408	2023/5/25	合格	
273	GX-B1361/22-A-23412	2023/5/25	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1361/22-A-23413	2023/5/25	所检项目合格	 A photograph showing two men in light-colored work jackets in a workshop. One man is operating a large, light-colored machine, while the other stands next to a large, rectangular metal tray with a grid of small holes. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the image.
275	GX-B1361/22-A-23414	2023/5/25	所检项目合格	 A photograph showing two men in light-colored work jackets in a workshop. They are operating a machine with a large circular dial gauge. One man is adjusting the machine, while the other stands nearby. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
276	GX-B1361/22-A-23415	2023/5/25	所检项目合格	
277	GX-B1361/22-A-23416	2023/5/25	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1361/22-A-23417	2023/5/25	所检项目合格	
279	GX-B1361/22-A-23453	2023/5/26	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1361/22-A-23454	2023/5/26	所检项目合格	
281	GX-B1361/22-A-23455	2023/5/26	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1361/22-A-23456	2023/5/26	所检项目合格	