



序号	报告编号	发布日期	结论	影像资料
238	GX-B1354/20-2-23005	2023. 5. 29	电网接地电容电流符合规定。 。	
239	GX-B1354/20-2-23006	2023. 5. 29	电网接地电容电流符合规定。 。	
240	GX-B1354/20-2-23007	2023. 5. 29	电网接地电容电流符合规定。 。	

241	GX-B1354/20-2-23008	2023. 5. 29	电网接地电容电流符合规定。 。			
242	GX-B1354/20-2-23009	2023. 5. 29	电网接地电容电流符合规定。 。			
243	GX-B1404/20-2-23008	2023. 5. 29	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。			

244	GX-B1404/20-2-23009	2023. 5. 29	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。			
245	GX-B1404/20-2-23010	2023. 5. 29	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。			
246	GX-B1404/20-2-23011	2023. 5. 29	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。			

247	GX-B1404/20-2-23012	2023. 5. 29	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
248	GX-B1323/21-2-23048~23049	2023. 5. 31	2台三相交流电动机所检项目合格。	
249	GX-B1306/21-2-23028	2023. 5. 31	所检项目合格。	

250	GX-B1499/21-2-23053	2023. 5. 31	所检项目合格。	
251	GX-B1499/21-2-23054	2023. 5. 31	所检项目合格。	
252	GX-B1499/21-2-23055	2023. 5. 31	所检项目合格。	

253	GX-B1499/21-2-23056	2023. 5. 31	所检项目合格。	
254	GX-B1499/21-2-23057	2023. 5. 31	所检项目合格。	
255	GX-B1499/21-2-23058	2023. 5. 31	所检项目合格。	

256	GX-B1499/21-2-23059	2023. 5. 31	所检项目合格。	 A photograph showing two workers in orange safety suits and hard hats standing in an industrial setting. They are positioned next to a large, complex piece of machinery, possibly a CNC machine or a robotic arm. The workers are holding flashlights, and the scene is dimly lit with some overhead lights. A small date stamp '2023/05/18' is visible in the bottom right corner of the image.
257				