

序号	报告编号	发布日期	结论	影像资料
1	GX-B1354/20-3-23010	2023. 6. 2	电网接地电容电流符合规定。	 <p>2023.5.24</p>

2	GX-B1520/20-3-23021	2023. 6. 5	综合判定： 合格。	
3	GX-B1520/20-3-23022	2023. 6. 5	综合判定： 合格。	

4	GX-B1520/20-3-23023	2023. 6. 5	综合判定： 合格。	
5	GX-B1495/20-3-232184~232188	2023. 6. 5	本次共检高 压开关柜 5台，5台高 压开关柜所 检项目合格 。	

6	GX-B1495/20-3-232189~232198	2023. 6. 5	<p>本次共检高压开关柜10台，10台高压开关柜所检项目合格。</p> <p>。</p>	
7	GX-B1418/22-3-23001	2023. 6. 5	所检项目合格。	
8	GX-B1418/22-3-23002	2023. 6. 5	所检项目合格。	
9	GX-B1418/22-3-23003	2023. 6. 5	所检项目合格。	
10	GX-B1418/22-3-23004	2023. 6. 5	所检项目合格。	
11	GX-B1418/22-3-23005	2023. 6. 5	所检项目合格。	

12	GX-B1328/20-3-23081	2023. 6. 2	本次共检绝缘手套4只，4只绝缘手套合格	
13	GX-B1328/20-3-23082	2023. 6. 2	本次共检绝缘鞋4只，4只绝缘鞋合格。	
14	GX-B1308/21-3-23020	1×1	所检项目合格。	

15	GX-B1499/21-3-23147	1×1	所检项目合格。	
16	GX-B1499/21-3-23148	1×1	所检项目合格。	

17	GX-B1499/21-3-23149	1×1	所检项目合格。	
18	GX-B1534/20-3-23001	2023. 6. 2	所检项目合格。	

19	GX-B1534/20-3-23002	2023. 6. 2	所检项目合格。	 <p>A photograph showing a yellow dump truck with its bed raised. Several people are standing around the truck, and a black hose is connected to the front. The date stamp '2023/6/11' is visible in the bottom right corner.</p>
20	GX-B1534/20-3-23003	2023. 6. 2	所检项目合格。	 <p>A photograph of a worker wearing a red helmet and safety vest, holding a device, standing in front of a yellow dump truck. Another worker is visible in the background near the truck's rear. The date stamp '2023/6/11' is visible in the bottom right corner.</p>

21	GX-B1534/20-3-23004	2023. 6. 2	所检项目合格。	 <p>A photograph showing a worker wearing a red hard hat and a grey work jacket. He is holding a handheld electronic device, possibly a PDA or a specialized tool, and looking at the screen. He is standing outdoors next to a large yellow truck. The background shows other vehicles and a clear sky. A yellow timestamp '2023/6/11' is visible in the bottom right corner of the photo.</p>
22	GX-B1423/20-3-23001	2023. 6. 8	综合判定： 合格。	 <p>A photograph showing a worker wearing a red hard hat and a light blue shirt, sitting in the operator's seat of a yellow vehicle, possibly a forklift or a small truck. He is holding a white object, possibly a clipboard or a piece of paper, and looking towards the camera. The vehicle's steering wheel and control levers are visible. A white timestamp '2023.5.29' is visible in the bottom right corner of the photo.</p>

23	GX-B1423/20-3-23002	2023. 6. 8	综合判定： 合格。	
24	GX-B1423/20-3-23003	2023. 6. 8	综合判定： 合格。	

25	GX-B1423/20-3-23004	2023. 6. 8	综合判定： 合格。	
26	GX-B1423/20-3-23005	2023. 6. 8	综合判定： 合格。	

27	GX-B1423/20-3-23006	2023. 6. 8	综合判定： 合格。	 <p>2023.5.29</p>
28	GX-B1423/20-3-23007	2023. 6. 8	综合判定： 合格。	 <p>2023.5.29</p>

29	GX-B1423/20-3-23008	2023. 6. 8	综合判定： 合格。	
30	GX-B1423/20-3-23009	2023. 6. 8	综合判定： 合格。	

31	GX-B1423/20-3-23010	2023. 6. 8	综合判定： 合格。	
32	GX-B1423/20-3-23011	2023. 6. 8	综合判定： 合格。	

33	GX-B1423/20-3-23012	2023. 6. 8	综合判定： 合格。	
----	---------------------	------------	--------------	---