



序号	报告编号	发布日期	结论	影像资料
1	GX-B1600/21-F-23013	2023. 6. 1	可不注水煤层	
2	GX-B1600/21-F-23014	2023. 6. 1	可不注水煤层	
3	GX-B1377/22-F-23225	2023. 6. 7	所检项目合格	
4	GX-B1377/22-F-23226	2023. 6. 7	所检项目合格	

5	GX-B1489/21-F-23035	2023. 6. 7	所检项目合格	
6	GX-B1377/22-F-23167	2023. 6. 5	所检项目合格	
7	GX-B1377/22-F-23168	2023. 6. 5	所检项目合格	



8	GX-B1377/22-F-23169	2023. 6. 5	所检项目合格	
9	GX-B1377/22-F-23182	2023. 6. 5	所检项目合格	
10	GX-B1377/22-F-23183	2023. 6. 5	所检项目合格	



11	GX-B1377/22-F-23184	2023. 6. 5	所检项目合格	
12	GX-B1377/22-F-23185	2023. 6. 5	所检项目合格	
13	GX-B1377/22-F-23186	2023. 6. 5	所检项目合格	

14	GX-B1377/22-F-23187	2023. 6. 5	所检项目合格	
15	GX-B1377/22-F-23188	2023. 6. 5	所检项目合格	
16	GX-B1377/22-F-23189	2023. 6. 5	所检项目合格	

17	GX-B1378/22-F-23138~F-23139	2023. 6. 8	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing light blue lab coats and face masks. One technician is standing and looking at a piece of equipment on a table, while the other is leaning over it, possibly adjusting or operating it. The equipment appears to be a testing or measurement device. The background shows a window with yellow curtains and other lab equipment.
18	GX-B1378/22-F-23140	2023. 6. 8	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing light blue lab coats and face masks. One technician is standing and looking at a piece of equipment on a table, while the other is leaning over it, possibly adjusting or operating it. The equipment appears to be a testing or measurement device. The background shows a window with yellow curtains and other lab equipment.
19	GX-B1377/22-F-23221	2023. 6. 8	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing light blue lab coats and face masks. They are standing in a room with various pieces of equipment and a table. One technician is looking at a piece of equipment on the table, while the other is standing next to it. The room has white walls and a window in the background.

20	GX-B1377/22-F-23222	2023. 6. 8	所检项目合格	
21	GX-B1377/22-F-23223	2023. 6. 8	所检项目合格	
22	GX-B1377/22-F-23224	2023. 6. 8	所检项目合格	

23	GX-B1377/22-F-23217	2023. 6. 8	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing light blue lab coats and face masks. They are standing at a workstation with a large, light blue piece of equipment that has a red lid. One technician is looking at a document while the other is near the equipment. The background shows other lab equipment and a clean, professional environment. A small date stamp '2023/5/29' is visible in the bottom right corner of the photo.
24	GX-B1377/22-F-23218	2023. 6. 8	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing light blue lab coats and face masks. They are standing at a workstation with a large, light blue piece of equipment that has a red lid. One technician is looking at a document while the other is near the equipment. The background shows other lab equipment and a clean, professional environment. A small date stamp '2023/5/29' is visible in the bottom right corner of the photo.
25	GX-B1377/22-F-23219	2023. 6. 8	所检项目合格	 A photograph showing two female technicians in a laboratory. They are wearing light blue lab coats and face masks. They are standing at a workstation with a large, light blue piece of equipment that has a red lid. One technician is looking at a document while the other is near the equipment. The background shows other lab equipment and a clean, professional environment. A small date stamp '2023/5/29' is visible in the bottom right corner of the photo.

26	GX-B1377/22-F-23220	2023. 6. 8	所检项目合格	
27	GX-B1377/22-F-23212	2023. 6. 8	所检项目合格	
28	GX-B1377/22-F-23213	2023. 6. 8	所检项目合格	

29	GX-B1377/22-F-23214	2023. 6. 8	所检项目合格	
30	GX-B1377/22-F-23215	2023. 6. 8	所检项目合格	