

| 序号  | 报告编号                | 发布日期         | 结论                    | 影像资料  |
|-----|---------------------|--------------|-----------------------|---|
| 106 | GX-B1548/20-1-23015 | 2023. 6. 12  | 所检项目合格。               |    |
| 107 | GX-B1548/20-1-23015 | 2023. 6. 12  | 所检项目合格。               |    |
| 108 | GX-B1328/20-1-23059 | 2023. 06. 13 | 本次共检绝缘手套60只，60只所检项目合格 |   |
| 109 | GX-B1328/20-1-23060 | 2023. 06. 13 | 本次共检绝缘鞋26只，26只所检项目合格  |  |

|     |                           |            |                                   |  |
|-----|---------------------------|------------|-----------------------------------|--|
| 110 | GX-B1451/20-1-23358~23375 | 2023.06.13 | 本次共检高压开关设备18台，<br>18台高压开关设备所检项目合格 |   |
| 111 | GX-B1451/20-1-23376~23386 | 2023.06.13 | 本次共检高压开关设备11台，<br>11台高压开关设备所检项目合格 |   |
| 112 | GX-B1350/21-1-23023       | 2023.06.13 | 本次共检验接地装置6处，6所<br>检项目合格           |   |
| 113 | GX-B1308/21-1-23024       | 2023.6.13  | 所检项目合格                            |  |

|     |                     |             |        |  |
|-----|---------------------|-------------|--------|--|
| 114 | GX-B1308/21-1-23025 | 2023. 6. 13 | 所检项目合格 |   |
| 115 | GX-B1308/21-1-23026 | 2023. 6. 13 | 所检项目合格 |   |
| 116 | GX-B1499/21-1-23058 | 2023. 6. 13 | 所检项目合格 |   |
| 117 | GX-B1499/21-1-23059 | 2023. 6. 13 | 所检项目合格 |  |

|     |                     |             |        |   |  |
|-----|---------------------|-------------|--------|---|--|
| 118 | GX-B1499/21-1-23060 | 2023. 6. 13 | 所检项目合格 |    |  |
| 119 | GX-B1499/21-1-23061 | 2023. 6. 13 | 所检项目合格 |    |  |
| 120 | GX-B1499/21-1-23062 | 2023. 6. 13 | 所检项目合格 |   |  |
| 121 | GX-B1499/21-1-23063 | 2023. 6. 13 | 所检项目合格 |  |  |

|     |                     |             |         |   |  |
|-----|---------------------|-------------|---------|---|--|
| 122 | GX-B1499/21-1-23064 | 2023. 6. 13 | 所检项目合格  |    |  |
| 123 | GX-B1499/21-1-23065 | 2023. 6. 13 | 所检项目合格  |    |  |
| 124 | GX-B1499/21-1-23066 | 2023. 6. 13 | 所检项目合格  |   |  |
| 125 | GX-B1423/20-1-23241 | 2023. 6. 13 | 综合判定：合格 |  |  |

|     |                     |             |         |   |
|-----|---------------------|-------------|---------|---|
| 126 | GX-B1423/20-1-23242 | 2023. 6. 13 | 综合判定：合格 |    |
| 127 | GX-B1423/20-1-23243 | 2023. 6. 13 | 综合判定：合格 |    |
| 128 | GX-B1423/20-1-23244 | 2023. 6. 13 | 综合判定：合格 |   |
| 129 | GX-B1423/20-1-23245 | 2023. 6. 13 | 综合判定：合格 |  |

|     |                     |             |         |   |
|-----|---------------------|-------------|---------|---|
| 130 | GX-B1423/20-1-23246 | 2023. 6. 13 | 综合判定：合格 |    |
| 131 | GX-B1423/20-1-23247 | 2023. 6. 13 | 综合判定：合格 |    |
| 132 | GX-B1423/20-1-23248 | 2023. 6. 13 | 综合判定：合格 |   |
| 133 | GX-B1423/20-1-23249 | 2023. 6. 13 | 综合判定：合格 |  |

|     |                     |             |         |   |
|-----|---------------------|-------------|---------|---|
| 134 | GX-B1423/20-1-23250 | 2023. 6. 13 | 综合判定：合格 |    |
| 135 | GX-B1423/20-1-23251 | 2023. 6. 13 | 综合判定：合格 |    |
| 136 | GX-B1423/20-1-23252 | 2023. 6. 13 | 综合判定：合格 |   |
| 137 | GX-B1423/20-1-23253 | 2023. 6. 13 | 综合判定：合格 |  |

|     |                     |             |         |   |
|-----|---------------------|-------------|---------|---|
| 138 | GX-B1423/20-1-23254 | 2023. 6. 13 | 综合判定：合格 |    |
| 139 | GX-B1423/20-1-23255 | 2023. 6. 13 | 综合判定：合格 |    |
| 140 | GX-B1423/20-1-23256 | 2023. 6. 13 | 综合判定：合格 |   |
| 141 | GX-B1423/20-1-23257 | 2023. 6. 13 | 综合判定：合格 |  |

|     |                     |             |         |   |
|-----|---------------------|-------------|---------|---|
| 142 | GX-B1423/20-1-23258 | 2023. 6. 13 | 综合判定：合格 |    |
| 143 | GX-B1423/20-1-23259 | 2023. 6. 13 | 综合判定：合格 |    |
| 144 | GX-B1423/20-1-23260 | 2023. 6. 13 | 综合判定：合格 |   |
| 145 | GX-B1423/20-1-23261 | 2023. 6. 13 | 综合判定：合格 |  |

|     |                     |             |         |   |
|-----|---------------------|-------------|---------|---|
| 146 | GX-B1423/20-1-23262 | 2023. 6. 13 | 综合判定：合格 |    |
| 147 | GX-B1423/20-1-23263 | 2023. 6. 13 | 综合判定：合格 |    |
| 148 | GX-B1423/20-1-23264 | 2023. 6. 13 | 综合判定：合格 |   |
| 149 | GX-B1423/20-1-23265 | 2023. 6. 13 | 综合判定：合格 |  |

|     |                     |             |         |  |
|-----|---------------------|-------------|---------|--|
| 150 | GX-B1423/20-1-23266 | 2023. 6. 13 | 综合判定：合格 |  A yellow truck with the number '3' on its front. Two workers in hard hats and work clothes stand in front of it. A yellow date stamp '2023.5.14' is at the bottom right.   |
| 151 | GX-B1423/20-1-23267 | 2023. 6. 13 | 综合判定：合格 |  A yellow truck with the number '5' on its front. Two workers in hard hats and work clothes stand in front of it. A yellow date stamp '2023.5.14' is at the bottom right.   |
| 152 | GX-B1423/20-1-23268 | 2023. 6. 13 | 综合判定：合格 |  A yellow truck with the number '6' on its front. Two workers in hard hats and work clothes stand in front of it. A yellow date stamp '2023.5.14' is at the bottom right.  |
| 153 | GX-B1423/20-1-23269 | 2023. 6. 13 | 综合判定：合格 |  A yellow truck with the number '7' on its front. Two workers in hard hats and work clothes stand in front of it. A yellow date stamp '2023.5.14' is at the bottom right. |

|     |                     |             |         |   |
|-----|---------------------|-------------|---------|---|
| 154 | GX-B1423/20-1-23270 | 2023. 6. 13 | 综合判定：合格 |    |
| 155 | GX-B1423/20-1-23271 | 2023. 6. 13 | 综合判定：合格 |    |
| 156 | GX-B1423/20-1-23272 | 2023. 6. 13 | 综合判定：合格 |   |
| 157 | GX-B1381/20-1-23003 | 2023/6/10   | 所检项目合格  |  |

|     |                     |             |         |  |
|-----|---------------------|-------------|---------|--|
| 158 | GX-B1381/20-1-23004 | 2023/6/10   | 所检项目合格  |  A worker in orange protective gear is working on a structure, possibly a staircase or platform, in an industrial setting. The date 2023/06/14 is visible in the bottom left corner of the photo. |
| 159 | GX-B1381/20-1-23005 | 2023/6/10   | 所检项目合格  |  A worker in orange protective gear is standing in an industrial area, possibly a control room or a monitoring station. The date 2023/06/10 is visible in the bottom left corner of the photo.    |
| 160 | GX-B1381/20-1-23006 | 2023/6/10   | 所检项目合格  |  A worker in dark clothing with a headlamp is working in a dark environment, possibly a tunnel or a confined space. The date 2023/05/25 is visible in the bottom left corner of the photo.       |
| 161 | GX-B1307/20-1-23065 | 2023. 6. 13 | 综合判定：合格 |  A worker in a red hard hat and grey shirt is working on a green machine, possibly a conveyor belt or a storage unit. The date 2023.05.18 is visible in the bottom right corner of the photo.   |

|     |                           |             |  |  |
|-----|---------------------------|-------------|--|--|
| 162 | GX-B1307/20-1-23066       | 2023. 6. 13 | 综合判定：合格                                    |   |
| 163 | GX-B1313/21-1-23066~23073 | 2023. 6. 14 | <p>本次共检电力变压器8台，8台电力变压器所检项目合格。</p> <p>。</p> |   |
| 164 | GX-B1313/21-1-23074~23076 | 2023. 6. 14 | <p>本次共检电力变压器3台，3台所检项目合格。</p>               |  |