

序号	报告编号	发布日期	结论	影像资料	
37	GX-B1499/21-P-23100	2023. 6. 18	所检项目合格		 <p data-bbox="1536 647 1621 667">2023. 6. 8</p>
38	GX-B1499/21-P-23101	2023. 6. 18	所检项目合格		 <p data-bbox="1536 1035 1621 1054">2023. 6. 8</p>

39	GX-B1499/21-P-23102	2023. 6. 18	所检项目合格	 <p>2023.6.8</p>
40	GX-B1548/20-P-23004	2023. 6. 19	所检项目合格	 <p>2023.5.6</p>
41	GX-B1451/20-P-23002	2023. 6. 18	所检项目合格	 <p>2023.5.7</p>


42	GX-B1534/20-P-23031	6.18	所检项目合格		
43	GX-B1534/20-P-23032	6.18	所检项目合格		
44	GX-B1534/20-P-23033	6.18	所检项目合格		

45	GX-B1534/20-P-23034	6.18	所检项目合格	
46	GX-B1534/20-P-23035	6.18	所检项目合格	
47	GX-B1534/20-P-23036	6.18	所检项目合格	

48	GX-B1534/20-P-23052	6.18	所检项目合格		
49	GX-B1534/20-P-23053	6.18	所检项目合格		
50	GX-B1534/20-P-23044	6.18	所检项目合格		

51	GX-B1534/20-P-23045	6.18	所检项目合格		
52	GX-B1534/20-P-23046	6.18	所检项目合格		
53	GX-B1534/20-P-23047	6.18	所检项目合格		

54	GX-B1534/20-P-23048	6.18	所检项目合格			
55	GX-B1534/20-P-23049	6.18	所检项目合格			
56	GX-B1534/20-P-23050	6.18	所检项目合格			

57	GX-B1534/20-P-23051	6. 18	所检项目合格	
58	GX-B1495/20-P-23220~23231	2023. 6. 18	<p>本次共检高压开关设备12台，12台高压开关设备所检项目合格。</p>	
59	GX-B1495/20-P-23241~23244	2023. 6. 18	<p>本次共检高压交流断路器4台，4台所检项目合格。</p>	

60	GX-B1495/20-P-23245~23247	2023. 6. 18	本次共检高压交流断路器3台，3台所检项目合格。			
61	GX-B1495/20-P-23232~23240	2023. 6. 18	本次共检高压开关设备9台，9台高压开关设备所检项目合格			
62	GX-B1547/20-P-23007~23010	2023. 6. 18	本次共检继电保护装置4台，4台继电保护装置所检项目合格。			

63	GX-B1547/20-P-23011~23014	2023. 6. 18	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	
64	GX-B1312/20-P-23004~23005	2023. 6. 19	本次共检电力变压器2台，2台电力变压器所检项目合格。	
65	GX-B1321/20-P-23011~23016	2023. 6. 19	本次共检电力电缆6条，6条电力电缆所检项目合格。	

66	GX-B1321/20-P-23027~23029	2023. 6. 19	本次共检电力电缆3条，3条电力电缆所检项目合格。			
67	GX-B1350/21-P-23003	2023. 6. 19	所检项目合格			
68	GX-B1350/21-P-23004	2023. 6. 19	所检项目合格			

69	GX-B1350/21-P-23005	2023. 6. 19	所检项目合格	
70	GX-B1350/21-P-23006	2023. 6. 19	所检项目合格	
71	GX-B1329/21-P-23016~23017	2023. 6. 18	本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格。	

72	GX-B1329/21-P-23018~23019	2023.6.18	本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格。	
73	GX-B1534/20-P-23037	2023.6.18	所检项目合格	
74	GX-B1534/20-P-23038	2023.6.18	所检项目合格	

75	GX-B1534/20-P-23039	2023. 6. 18	所检项目合格		
76	GX-B1534/20-P-23040	2023. 6. 18	所检项目合格		
77	GX-B1534/20-P-23041	2023. 6. 18	所检项目合格		

78	GX-B1534/20-P-23042	2023. 6. 18	所检项目合格		
79	GX-B1534/20-P-23043	2023. 6. 18	所检项目合格		
80	GX-B1534/20-P-23054	2023. 6. 18	所检项目合格		

81	GX-B1534/20-P-23055	2023. 6. 18	所检项目合格	 <p>A worker in a blue denim jacket and red safety helmet is inspecting a piece of machinery. Another worker in a grey jacket is visible in the background. The date '2023.5.8' is visible in the bottom right corner of the photo.</p>
82	GX-B1534/20-P-23056	2023. 6. 18	所检项目合格	 <p>A worker in a blue denim jacket and red safety helmet is inspecting a piece of machinery. The number '16' is visible on the machinery. The date '2023.5.8' is visible in the bottom right corner of the photo.</p>
83	GX-B1308/21-P-23008	2023. 5. 18	所检项目合格	 <p>A worker in a red jacket and red safety helmet is inspecting a piece of machinery. The date '2023.4.24' is visible in the bottom right corner of the photo.</p>

84	GX-B1499/21-P-23047	2023. 5. 18	所检项目合格	 <p>2023.4</p>
85	GX-B1499/21-P-23048	2023. 5. 18	所检项目合格	 <p>2023.4.24</p>
86	GX-B1499/21-P-23049	2023. 5. 18	所检项目合格	 <p>2023.4.24</p>

87	GX-B1308/21-P-23009	2023. 5. 18	所检项目合格	
88	GX-B1499/21-P-23050	2023. 5. 18	所检项目合格	
89	GX-B1499/21-P-23051	2023. 5. 18	所检项目合格	

90	GX-B1499/21-P-23052	2023. 5. 18	所检项目合格	
91	GX-B1306/21-P-23030	2023. 6. 21	所检项目合格	
92	GX-B1306/21-P-23031	2023. 6. 21	所检项目合格	

93	GX-B1306/21-P-23032	2023. 6. 21	所检项目合格	
94	GX-B1306/21-P-23033	2023. 6. 21	所检项目合格	
95	GX-B1416/22-P-23063	2023. 6. 23	综合判定：合格	

96	GX-B1416/22-P-23064	2023. 6. 23	综合判定：合格	 A worker in a red helmet and safety gear is working on a structure at night. The worker is wearing a red helmet, a dark jacket, and safety harness. The background shows some industrial equipment and a dark sky. A timestamp '2023.6.5' is visible in the bottom right corner of the image.
97	GX-B1416/22-P-23065	2023. 6. 23	综合判定：合格	 A worker in a red helmet and safety gear is standing near a large red cylindrical object. The worker is wearing a red helmet, a dark jacket, and safety harness. The background shows some industrial equipment and a dark sky. A timestamp '2023.6.5' is visible in the bottom right corner of the image.
98	GX-B1416/22-P-23066	2023. 6. 23	综合判定：合格	 A worker in a red helmet and safety gear is working on a structure. The worker is wearing a red helmet, a dark jacket, and safety harness. The background shows some industrial equipment and a dark sky. A timestamp '2023.6.4' is visible in the bottom right corner of the image.

99	GX-B1416/22-P-23067	2023. 6. 23	综合判定：合格	
100	GX-B1416/22-P-23068	2023. 6. 23	综合判定：合格	