

序号	报告编号	发布日期	结论	影像资料
165	GX-B1305/21-1-23005	2023. 6. 17	综合判定：合格	
166	GX-B1305/21-1-23006	2023. 6. 17	综合判定：合格	
167	GX-B1307/20-1-23059	2023. 6. 17	综合判定：合格	

168	GX-B1307/20-1-23060	2023. 6. 17	综合判定：合格	
169	GX-B1307/20-1-23061	2023. 6. 17	综合判定：合格	 2023/6/24
170	GX-B1307/20-1-23062	2023. 6. 17	综合判定：合格	 2023/6/23

171	GX-B1307/20-1-23063	2023. 6. 17	综合判定：合格	
172	GX-B1307/20-1-23064	2023. 6. 17	综合判定：合格	
173	GX-B1310/21-1-23053	2023/6/17	符合标准要求	

174	GX-B1310/21-1-23054	2023/6/17	符合标准要求		
175	GX-B1310/21-1-23055	2023/6/17	符合标准要求		
176	GX-B1310/21-1-23056	2023/6/17	符合标准要求		

177	GX-B1310/21-1-23057	2023/6/17	符合标准要求		
178	GX-B1310/21-1-23058	2023/6/17	符合标准要求		
179	GX-B1310/21-1-23059	2023/6/17	符合标准要求		

180	GX-B1310/21-1-23060	2023/6/17	符合标准要求	
181	GX-B1310/21-1-23061	2023/6/17	符合标准要求	
182	GX-B1427/21-1-23057	2023/6/17	符合标准要求	

183	GX-B1305/21-1-23009	2023/6/17	综合判定：合格。	 A worker wearing a blue hard hat and a white t-shirt is operating a large industrial machine. The machine has a prominent blue component. The worker is positioned to the right of the machine, which is partially open. A yellow timestamp '2023.5.25' is visible in the bottom right corner of the image.
184	GX-B1304/21-1-23003	2023/6/17	综合判定：合格。	 A worker wearing a blue hard hat and a grey uniform is operating a large industrial machine. The machine has a prominent green component. The worker is positioned to the right of the machine, which is partially open. A yellow timestamp '2023.05.2' is visible in the bottom right corner of the image.
185	GX-B1305/21-1-23005	2023/6/17	综合判定：合格。	 A worker wearing a blue hard hat is operating a large industrial machine. The machine has a prominent green component. The worker is positioned to the right of the machine, which is partially open. A yellow timestamp '2023/05/23' is visible in the bottom left corner of the image.

186	GX-B1305/21-1-23006	2023/6/17	综合判定：合格。	
187	GX-B1305/21-1-23007	2023/6/17	综合判定：合格。	
188	GX-B1305/21-1-23008	2023/6/17	综合判定：合格。	

189	GX-B1305/21-1-23009	2023/6/17	综合判定：合格。	 <p>2023.5.25</p>
190	GX-B1305/21-1-23010	2023/6/17	综合判定：合格。	 <p>2023/5/24</p>
191	GX-B1305/21-1-23011	2023/6/17	综合判定：合格。	 <p>2023 05 25</p>


192	GX-B1303/21-1-23006	2023/6/17	综合判定：合格。	
193	GX-B1382/21-1-23017	2023. 6. 17	综合判定：合格	
194	GX-B1382/21-1-23018	2023. 6. 17	综合判定：合格	

195	GX-B1382/21-1-23019	2023. 6. 17	综合判定:合格	
196	GX-B1382/21-1-23020	2023. 6. 17	综合判定:合格	
197	GX-B1382/21-1-23021	2023. 6. 17	综合判定:合格	

198	GX-B1382/21-1-23022	2023. 6. 17	综合判定:合格	
199	GX-B1382/21-1-23023	2023. 6. 17	综合判定:合格	
200	GX-B1382/21-1-23024	2023. 6. 17	综合判定:合格	

201	GX-B1382/21-1-23025	2023. 6. 17	综合判定:合格		
202	GX-B1382/21-1-23026	2023. 6. 17	综合判定:合格		
203	GX-B1359/21-1-23093~23098	2023. 6. 19	本次共检矿用隔爆型照明信号综合保护装置6台,6台所检项目合格		

204	GX-B1359/21-1-23099~23113	2023. 6. 19	本次共检矿用隔爆型照明信号综合保护装置15台, 15台所检项目合格	
205	GX-B1352/21-1-23266~23288	2023. 6. 19	本次共检矿用防爆低压交流真空馈电开关23台, 23台所检项目合格	
206	GX-B1352/21-1-23289~23312	2023. 6. 19	本次共检矿用防爆低压交流真空馈电开关24台, 24台所检项目合格	

207	GX-B1354/20-1-23004	2023. 6. 19	电网接地电容电流符合规定	
208	GX-B1351/21-1-23011~23016	2023. 6. 19	本次共检矿用隔爆型检漏继电器6台, 6台所检项目合格	
209	GX-B1352/21-1-235018~235025	2023. 6. 19	本次共检矿用防爆低压交流真空馈电开关漏电保护8台, 8台所检项目合格	

210	GX-B1352/21-1-235026~235033	2023. 6. 19	本次共检矿用防爆低压交流真空馈电开关漏电保护8台，8台所检项目合格	
211	GX-B1352/21-1-23324~23332	2023. 6. 19	本次共检矿用防爆低压交流真空馈电开关9台，9台所检项目合格	
212	GX-B1352/21-1-23313~23323	2023. 6. 19	本次共检矿用防爆低压交流真空馈电开关11台，11台所检项目合格	

213	GX-B1359/21-1-23114~23124	2023. 6. 19	本次共检矿用隔爆型照明信号综合保护装置11台, 11台所检项目合格	
214	GX-B1359/21-1-23125~23134	2023. 6. 19	本次共检矿用隔爆型照明信号综合保护装置10台, 10台所检项目合格	
215	GX-B1381/20-1-23002	2023/6/22	所检项目合格	

216	GX-B1423/20-1-23292	2023. 6. 21	综合判定：合格	
217	GX-B1423/20-1-23293	2023. 6. 21	综合判定：合格	
218	GX-B1423/20-1-23294	2023. 6. 21	综合判定：合格	

219	GX-B1423/20-1-23295	2023. 6. 21	综合判定：合格	
220	GX-B1423/20-1-23296	2023. 6. 21	综合判定：合格	
221	GX-B1423/20-1-23297	2023. 6. 21	综合判定：合格	

222	GX-B1423/20-1-23298	2023. 6. 21	综合判定：合格	
223	GX-B1423/20-1-23299	2023. 6. 21	综合判定：合格	
224	GX-B1423/20-1-23300	2023. 6. 21	综合判定：合格	

225	GX-B1423/20-1-23301	2023. 6. 21	综合判定：合格	
226	GX-B1423/20-1-23302	2023. 6. 21	综合判定：合格	
227	GX-B1423/20-1-23303	2023. 6. 21	综合判定：合格	

228	GX-B1423/20-1-23304	2023. 6. 21	综合判定：合格	
229	GX-B1423/20-1-23305	2023. 6. 21	综合判定：合格	
230	GX-B1423/20-1-23306	2023. 6. 21	综合判定：合格	

231	GX-B1423/20-1-23307	2023. 6. 21	综合判定：合格		
232	GX-B1423/20-1-23308	2023. 6. 21	综合判定：合格		
233	GX-B1423/20-1-23309	2023. 6. 21	综合判定：合格		

234	GX-B1423/20-1-23310	2023. 6. 21	综合判定：合格		
235	GX-B1423/20-1-23311	2023. 6. 21	综合判定：合格		
236	GX-B1423/20-1-23312	2023. 6. 21	综合判定：合格		

237	GX-B1423/20-1-23313	2023. 6. 21	综合判定：合格		
238	GX-B1423/20-1-23314	2023. 6. 21	综合判定：合格		
239	GX-B1423/20-1-23315	2023. 6. 21	综合判定：合格		

240	GX-B1423/20-1-23316	2023. 6. 21	综合判定：合格	
241	GX-B1423/20-1-23317	2023. 6. 21	综合判定：合格	
242	GX-B1423/20-1-23318	2023. 6. 21	综合判定：合格	

243	GX-B1358/21-1-23006	2023. 6. 21	所检项目合格	 <p>2023/5/5</p>
244	GX-B1517/20-1-23036	2023. 6. 22	综合判定：合格	 <p>2023/5/5</p>
245	GX-B1517/20-1-23037	2023. 6. 22	综合判定：合格	 <p>2023/5/5</p>

246	GX-B1517/20-1-23038	2023. 6. 22	综合判定：合格	 A black and white photograph of a worker wearing a hard hat and a safety vest with reflective stripes. The worker is holding a clipboard and looking at it. The background shows an industrial environment with some equipment and a concrete floor. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the image.
247	GX-B1517/20-1-23039	2023. 6. 22	综合判定：合格	 A black and white photograph of a worker wearing a hard hat and safety glasses, focused on operating a piece of industrial machinery. The worker's hands are near a control panel or a specific part of the machine. The lighting is somewhat dim, highlighting the worker's face and the machine. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the image.