

序号	报告编号	发布日期	结论	影像资料
215	GX-B1306/21-4-23039	2023. 6. 27	所检项目合格。	
216	GX-B1306/21-4-23040	2023. 6. 27	所检项目合格。	
217	GX-B1306/21-4-23041	2023. 6. 27	所检项目合格。	
218	GX-B1306/21-4-23042	2023. 6. 27	所检项目合格。	

219	GX-B1306/21-4-23043	2023. 6. 27	所检项目合格。	
220	GX-B1306/21-4-23044	2023. 6. 27	所检项目合格。	
221	GX-B1306/21-4-23045	2023. 6. 27	所检项目合格。	
222	GX-B1515/22-4-23003	2023. 6. 27	所检项目合格。	

223	GX-B1359/21-4-23290~23291	2023. 6. 28	本次共检矿用隔爆型照明信号综合保护装置2台, 2台所检项目合格。	
224	GX-B1359/21-4-23292~23298	2023. 6. 28	本次共检矿用隔爆型照明信号综合保护装置7台, 7台所检项目合格。	
225	GX-B1301/21-4-23007	2023. 6. 26	综合判定:合格。	
226	GX-B1310/21-4-23068	2023. 6. 28	符合标准要求	

227	GX-B1310/21-4-23069	2023. 6. 28	符合标准要求		
228	GX-B1310/21-4-23070	2023. 6. 28	符合标准要求		