

序号	报告编号	发布日期	结论	影像资料
1	GX-B1500/21-1-23074	2023/7/2	综合判定：合格	
2	GX-B1500/21-1-23075	2023/7/2	综合判定：合格	
3	GX-B1500/21-1-23076	2023/7/2	综合判定：合格	
4	GX-B1500/21-1-23077	2023/7/2	综合判定：合格	

5	GX-B1309/21-1-23019	2023/7/2	所检项目合格	
6	GX-B1382/21-1-23027	2023/7/2	综合判定:合格	
7	GX-B1306/21-1-23027	2023. 7. 2	所检项目合格	
8	GX-B1306/21-1-23028	2023. 7. 2	所检项目合格	

9	GX-B1306/21-1-23029	2023. 7. 2	所检项目合格	
10	GX-B1359/21-1-23135~23138	2023. 7. 3	本次共检矿用隔爆型照明信号综合保护装置4台,4台所检项目合格。	
11	GX-B1321/20-1-23901~23902	2023. 7. 3	本次共检电力电缆2条, 2条电力电缆所检项目合格。	
12	GX-B1495/20-1-231446~231447	2023. 7. 3	本次共检高压防爆开关设备2台, 2台高压防爆开关设备所检项目合格。	

13	GX-B1312/20-1-23460	2023. 7. 3	所检项目合格。	
14	GX-B1328/20-1-23061	2023. 7. 3	本次共检绝缘手套30只，30只所检项目合格。	
15	GX-B1328/20-1-23062	2023. 7. 3	本次共检绝缘鞋30只，30只所检项目合格。	
16	GX-B1328/20-1-23063	2023. 7. 3	本次共检携带式短路接地线8套，8套所检项目合格。	

17	GX-B1328/20-1-23064	2023. 7. 3	本次共检验电器 17支，17支所检项目 合格。	
18	GX-B1328/20-1-23065	2023. 7. 3	本次共检携带式短路 接地线10套，10套所 检项目合格。	
19	GX-B1520/20-1-23024	2023/7/3	合格	
20	GX-B1520/20-1-23025	2023/7/3	合格	


21	GX-B1423/20-1-23364	2023/7/3	合格	
22	GX-B1423/20-1-23365	2023/7/3	合格	
23	GX-B1423/20-1-23366	2023/7/3	合格	
24	GX-B1423/20-1-23367	2023/7/3	合格	

25	GX-B1423/20-1-23368	2023/7/3	合格	
26	GX-B1423/20-1-23369	2023/7/3	合格	
27	GX-B1423/20-1-23370	2023/7/3	合格	
28	GX-B1423/20-1-23371	2023/7/3	合格	

29	GX-B1310/21-1-23067	2023. 7. 3	符合标准要求		
30	GX-B1310/21-1-23050	2023. 7. 3	符合标准要求		
31	GX-B1310/21-1-23051	2023. 7. 3	符合标准要求		
32	GX-B1310/21-1-23052	2023. 7. 3	符合标准要求		

33	GX-B1385/21-1-23008	2023/7/3	所检项目合格	
34	GX-B1385/21-1-23009	2023/7/3	所检项目合格	
35	GX-B1385/21-1-23010	2023/7/3	所检项目合格	
36	GX-B1385/21-1-23011	2023/7/3	所检项目合格	

37	GX-B1385/21-1-23012	2023/7/3	所检项目合格	
38	GX-B1385/21-1-23013	2023/7/3	所检项目合格	
39	GX-B1385/21-1-23014	2023/7/3	所检项目合格	
40	GX-B1310/21-1-23063	2023/7/3	符合标准要求	

41	GX-B1427/21-1-23063	2023/7/3	符合标准要求	
42	GX-B1310/21-1-23064	2023/7/3	符合标准要求	
43	GX-B1310/21-1-23065	2023/7/3	符合标准要求	
44	GX-B1310/21-1-23066	2023/7/3	符合标准要求	

45	GX-B1310/21-1-23068	2023/7/3	符合标准要求	
46	GX-B1428/21-1-23068	2023/7/3	无缺陷痕迹显示	
47	GX-B1310/21-1-23069	2023/7/3	符合标准要求	
48	GX-B1428/21-1-23069	2023/7/3	无缺陷痕迹显示	

49	GX-B1310/21-1-23072	2023/7/3	符合标准要求	
50	GX-B1423/20-1-23340	2023/7/4	综合判定：合格	
51	GX-B1423/20-1-23341	2023/7/4	综合判定：合格	
52	GX-B1423/20-1-23342	2023/7/4	综合判定：合格	

53	GX-B1423/20-1-23343	2023/7/4	综合判定：合格	 A yellow truck with a white cab and a yellow body, parked on a dirt road. Two people are standing in front of it. The date stamp '2023.06.15' is visible at the bottom.
54	GX-B1423/20-1-23344	2023/7/4	综合判定：合格	 A red truck with a white cab and a red body, parked on a dirt road. Two people are standing in front of it. The date stamp '2023.06.15' is visible at the bottom.
55	GX-B1423/20-1-23345	2023/7/4	综合判定：合格	 A red truck with a white cab and a red body, parked on a dirt road. Two people are standing in front of it. The date stamp '2023.06.15' is visible at the bottom.
56	GX-B1423/20-1-23346	2023/7/4	综合判定：合格	 A red truck with a white cab and a red body, parked on a dirt road. Two people are standing in front of it. The date stamp '2023.06.15' is visible at the bottom.

57	GX-B1423/20-1-23347	2023/7/4	综合判定：合格	
58	GX-B1423/20-1-23348	2023/7/4	综合判定：合格	
59	GX-B1423/20-1-23349	2023/7/4	综合判定：合格	
60	GX-B1423/20-1-23350	2023/7/4	综合判定：合格	

61	GX-B1423/20-1-23351	2023/7/4	综合判定：合格	
62	GX-B1423/20-1-23352	2023/7/4	综合判定：合格	
63	GX-B1423/20-1-23353	2023/7/4	综合判定：合格	
64	GX-B1499/21-1-23068	2023. 7. 2	所检项目合格	

65	GX-B1499/21-1-23069	2023. 7. 2	所检项目合格	
66	GX-B1499/21-1-23070	2023. 7. 2	所检项目合格	
67	GX-B1308/21-1-23027	2023. 7. 2	所检项目合格	
68	GX-B1308/21-1-23028	2023. 7. 2	所检项目合格	

69	GX-B1308/21-1-23029	2023. 7. 2	所检项目合格	
70	GX-B1302/21-1-23005	2023/7/5	合格	