

序号	报告编号	发布日期	结论	影像资料
1	GX-B1385/21-Y-23066	2023年7月3日	所检项目合格。 。	
2	GX-B1385/21-Y-23067	2023年7月3日	所检项目合格。 。	

3	GX-B1385/21-Y-23068	2023年7月3日	所检项目合格。 。	
4	GX-B1385/21-Y-23069	2023年7月3日	所检项目合格。 。	
5	GX-B1385/21-Y-23070	2023年7月3日	所检项目合格。 。	

6	GX-B1385/21-Y-23071	2023年7月3日	所检项目合格。 。	 A worker in a blue uniform and red helmet is working on a piece of machinery. The worker is standing on a platform and appears to be inspecting or adjusting a component. The date stamp '2023/6/3' is visible in the bottom right corner of the image.
7	GX-B1385/21-Y-23073	2023年7月3日	所检项目合格。 。	 A worker in a white uniform and red helmet is working on a large industrial machine. The worker is standing on a platform and appears to be inspecting or adjusting a component. The date stamp '2023/6/3' is visible in the bottom right corner of the image.
8	GX-B1517/20-Y-23014	2023年7月3日	综合判定：合格。 。	 A worker in a blue uniform and red helmet is standing in front of a large industrial machine. The worker is wearing a headlamp and appears to be inspecting or adjusting a component. The date stamp '2023/6/24' is visible in the bottom right corner of the image.

9	GX-B1517/20-Y-23015	2023年7月3日	综合判定：合格。	
10	GX-B1517/20-Y-23016	2023年7月3日	综合判定：合格。	
11	GX-B1517/20-Y-23017	2023年7月3日	综合判定：合格。	

12	GX-B1559/22-Y-23012	2023年7月3日	所检项目合格。	 <p>2023/6/7</p>
13	GX-B1423/20-Y-233601	2023年7月2日	综合判定：合格	 <p>2023/6/7</p>

14	GX-B1423/20-Y-233602	2023年7月2日	综合判定：合格	
15	GX-B1423/20-Y-233603	2023年7月2日	综合判定：合格	

16	GX-B1423/20-Y-233604	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow MT106 dump truck parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The truck's model number 'MT106' is visible on the top of the dump body. A yellow timestamp '2023/6/7' is located in the bottom right corner of the image.</p>
17	GX-B1423/20-Y-233605	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow MT106 dump truck parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The truck's model number 'MT106' is visible on the side of the dump body. A yellow timestamp '2023/6/7' is located in the bottom right corner of the image.</p>

18	GX-B1423/20-Y-233606	2023年7月2日	综合判定：合格	
19	GX-B1423/20-Y-233607	2023年7月2日	综合判定：合格	

20	GX-B1423/20-Y-233608	2023年7月2日	综合判定：合格	
21	GX-B1423/20-Y-233609	2023年7月2日	综合判定：合格	

22	GX-B1423/20-Y-233610	2023年7月2日	综合判定：合格	
23	GX-B1423/20-Y-233611	2023年7月2日	综合判定：合格	

24	GX-B1423/20-Y-233612	2023年7月2日	综合判定：合格	
25	GX-B1423/20-Y-233613	2023年7月2日	综合判定：合格	

26	GX-B1423/20-Y-233614	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow MT106 dump truck parked on a gravel surface. Three workers wearing red hard hats and high-visibility vests are standing in front of the truck. The truck has 'MT106' and '40' printed on its side. A yellow timestamp '2023/6/8' is visible in the bottom right corner of the image.</p>
27	GX-B1423/20-Y-233615	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow MT106 dump truck from a front-three-quarter view. Two workers in red hard hats and safety vests are standing in front of the truck. The truck has 'MT106' on the top of the dump body and '40' on the front. A yellow timestamp '2023/6/8' is visible in the bottom right corner of the image.</p>

28	GX-B1423/20-Y-233616	2023年7月2日	综合判定：合格	
29	GX-B1423/20-Y-233617	2023年7月2日	综合判定：合格	

30	GX-B1423/20-Y-233618	2023年7月2日	综合判定：合格	 A yellow MT1000 dump truck with the number 35 on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. A date stamp '2023/6/8' is visible in the bottom right corner of the photo.
31	GX-B1423/20-Y-233619	2023年7月2日	综合判定：合格	 A yellow MT1000 dump truck with the number 31 on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. A date stamp '2023/6/8' is visible in the bottom right corner of the photo.

32	GX-B1423/20-Y-233620	2023年7月2日	综合判定：合格	
33	GX-B1423/20-Y-233621	2023年7月2日	综合判定：合格	

34	GX-B1423/20-Y-233622	2023年7月2日	综合判定：合格	
35	GX-B1423/20-Y-233623	2023年7月2日	综合判定：合格	

36	GX-B1423/20-Y-233624	2023年7月2日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Three workers in high-visibility vests are standing near the front of the truck. A yellow date stamp '2023/6/8' is visible in the bottom right corner of the photo.
37	GX-B1423/20-Y-233625	2023年7月2日	综合判定：合格	 A red dump truck is parked on a dirt surface under a clear blue sky. Three workers in high-visibility vests are standing near the front of the truck. A red date stamp '2023/6/9' is visible in the bottom right corner of the photo.

38	GX-B1423/20-Y-233626	2023年7月2日	综合判定：合格	 A yellow MT100 dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has "MT100" written on its side. A yellow timestamp "2023/6/9" is visible in the bottom right corner of the photo.
39	GX-B1423/20-Y-233627	2023年7月2日	综合判定：合格	 A yellow MT100 dump truck is parked on a dirt surface. One worker in a high-visibility vest and hard hat stands in front of the truck. The truck has "MT100" and the number "6" written on its side. A yellow timestamp "2023/6/9" is visible in the bottom right corner of the photo.

40	GX-B1423/20-Y-233628	2023年7月2日	综合判定：合格	
41	GX-B1423/20-Y-233629	2023年7月2日	综合判定：合格	

42	GX-B1423/20-Y-233630	2023年7月2日	综合判定：合格	 <p>A yellow MT1000 dump truck is shown from a side-rear perspective. Three workers in high-visibility vests and hard hats are standing around the truck, inspecting the rear wheel area. The truck is parked on a dirt surface under a clear blue sky. A yellow date stamp '2023/6/9' is visible in the bottom right corner of the photo.</p>
43	GX-B1423/20-Y-233631	2023年7月2日	综合判定：合格	 <p>A yellow MT1000 dump truck is shown from a side-front perspective. Three workers in high-visibility vests and hard hats are standing around the truck, inspecting the front wheel area. The truck is parked on a dirt surface under a clear blue sky. A yellow date stamp '2023/6/9' is visible in the bottom right corner of the photo.</p>

44	GX-B1423/20-Y-233632	2023年7月2日	综合判定：合格	
45	GX-B1423/20-Y-233633	2023年7月2日	综合判定：合格	

46	GX-B1423/20-Y-233634	2023年7月2日	综合判定：合格	 A yellow MT1000 dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing near the front of the truck. The truck's bed is slightly raised. A yellow date stamp '2023/7/2' is visible in the bottom right corner of the photo.
47	GX-B1423/20-Y-233635	2023年7月2日	综合判定：合格	 A yellow MT1000 dump truck is parked on a dirt surface. Three workers in high-visibility vests and hard hats are standing near the front of the truck. A traffic cone and some equipment are on the ground in the foreground. The truck's bed is slightly raised. A yellow date stamp '2023/7/2' is visible in the bottom right corner of the photo.

48	GX-B1423/20-Y-233636	2023年7月2日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Four workers in high-visibility vests and hard hats are standing around the truck, inspecting it. The truck has the number '30' on its side. A yellow timestamp '2023/6/10' is visible in the bottom right corner of the photo.
49	GX-B1423/20-Y-233637	2023年7月2日	综合判定：合格	 A red dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing near the front of the truck. The truck has the number '71' on its side. A yellow timestamp '2023/6/10' is visible in the bottom right corner of the photo.

50	GX-B1423/20-Y-233638	2023年7月2日	综合判定：合格	
51	GX-B1423/20-Y-233639	2023年7月2日	综合判定：合格	

52	GX-B1423/20-Y-233640	2023年7月2日	综合判定：合格	
53	GX-B1423/20-Y-233641	2023年7月2日	综合判定：合格	

54	GX-B1423/20-Y-233642	2023年7月2日	综合判定：合格	
55	GX-B1423/20-Y-233643	2023年7月2日	综合判定：合格	

56	GX-B1423/20-Y-233644	2023年7月2日	综合判定：合格	 A yellow MT100 dump truck is parked on a dirt surface under a clear blue sky. Three workers in high-visibility vests and hard hats are standing near the truck. A traffic cone and some equipment are on the ground in front of the truck. A yellow timestamp '2023/6/10' is visible in the bottom right corner of the photo.
57	GX-B1423/20-Y-233645	2023年7月2日	综合判定：合格	 A yellow MT100 dump truck is parked on a dirt surface under a clear blue sky. Three workers in high-visibility vests and hard hats are standing near the truck. A traffic cone and some equipment are on the ground in front of the truck. A yellow timestamp '2023/6/10' is visible in the bottom right corner of the photo.

58	GX-B1423/20-Y-233646	2023年7月2日	综合判定：合格	 A yellow MT108 dump truck is parked on a dirt surface. Two workers in high-visibility vests are standing near the front. A traffic cone and other equipment are visible in the foreground. A yellow timestamp '2023/6/10' is in the bottom right corner.
59	GX-B1423/20-Y-233647	2023年7月2日	综合判定：合格	 A red dump truck is parked on a dirt surface. Two workers in high-visibility vests are standing near the front. A traffic cone and other equipment are visible in the foreground. A yellow timestamp '2023/6/10' is in the bottom right corner.

60	GX-B1423/20-Y-233648	2023年7月2日	综合判定：合格	
61	GX-B1423/20-Y-233649	2023年7月2日	综合判定：合格	

62	GX-B1423/20-Y-233650	2023年7月2日	综合判定：合格	
63	GX-B1423/20-Y-233651	2023年7月2日	综合判定：合格	

64	GX-B1423/20-Y-233652	2023年7月2日	综合判定：合格	
65	GX-B1423/20-Y-233653	2023年7月2日	综合判定：合格	

66	GX-B1423/20-Y-233654	2023年7月2日	综合判定：合格	
67	GX-B1423/20-Y-233655	2023年7月2日	综合判定：合格	

68	GX-B1423/20-Y-233656	2023年7月2日	综合判定：合格	 A yellow MT108 dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck has 'MT108' written on its side. A yellow timestamp '2023/8/11' is visible in the bottom right corner of the image.
69	GX-B1423/20-Y-233657	2023年7月2日	综合判定：合格	 A yellow MT800 dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck has 'MT800' written on its side. A yellow timestamp '2023/8/11' is visible in the bottom right corner of the image.

70	GX-B1423/20-Y-233658	2023年7月2日	综合判定：合格	
71	GX-B1423/20-Y-233659	2023年7月2日	综合判定：合格	

72	GX-B1423/20-Y-233660	2023年7月2日	综合判定：合格	
73	GX-B1423/20-Y-233661	2023年7月2日	综合判定：合格	

74	GX-B1423/20-Y-233662	2023年7月2日	综合判定：合格	 A yellow dump truck is parked on a dirt road at a construction or mining site. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's bed is raised. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the photo.
75	GX-B1423/20-Y-233663	2023年7月2日	综合判定：合格	 A yellow dump truck is parked on a dirt road at a construction or mining site. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's bed is raised. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the photo.

76	GX-B1423/20-Y-233664	2023年7月2日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '69' on its side. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the photo.
77	GX-B1423/20-Y-233665	2023年7月2日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '69' on its side. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the photo.

78	GX-B1423/20-Y-233666	2023年7月2日	综合判定：合格	 A yellow LTM dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has 'LTM' and 'MT100' visible on its side. A yellow timestamp '2023/6/12' is in the bottom right corner.
79	GX-B1423/20-Y-233667	2023年7月2日	综合判定：合格	 A red LMG dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has 'LMG' and 'MY20' visible on its side. A yellow timestamp '2023/6/12' is in the bottom right corner.

80	GX-B1423/20-Y-233668	2023年7月2日	综合判定：合格	
81	GX-B1423/20-Y-233669	2023年7月2日	综合判定：合格	

82	GX-B1423/20-Y-233670	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow MT106 dump truck parked on a dirt surface. Two workers wearing red hard hats and high-visibility yellow vests are standing in front of the truck. The truck's bed is raised. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the image.</p>
83	GX-B1423/20-Y-233671	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow MT106 dump truck parked on a dirt surface. One worker wearing a red hard hat and a high-visibility yellow vest is standing in front of the truck. The truck's bed is raised. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the image.</p>

84	GX-B1423/20-Y-233672	2023年7月2日	综合判定：合格	 <p>A photograph showing the front view of a yellow MT106 dump truck. A worker wearing a red hard hat and a high-visibility yellow vest stands in front of the truck. The truck has 'MT106' written on the top of the dump body. A yellow timestamp '2023/6/12' is visible in the bottom right corner of the image.</p>
85	GX-B1423/20-Y-233673	2023年7月2日	综合判定：合格	 <p>A photograph showing the side view of a yellow MT106 dump truck. Two workers wearing red hard hats and high-visibility yellow vests stand next to the truck. The truck has 'MT106' written on the side of the dump body. A yellow timestamp '2023/6/13' is visible in the bottom right corner of the image.</p>

86	GX-B1423/20-Y-233674	2023年7月2日	综合判定：合格	 A yellow MT108 dump truck is shown from a front-three-quarter view. The truck is parked on a dirt surface. Several workers in high-visibility vests and hard hats are standing around the truck. The date stamp '2023/6/13' is visible in the bottom right corner of the image.
87	GX-B1423/20-Y-233675	2023年7月2日	综合判定：合格	 A yellow MT108 dump truck is shown from a rear-three-quarter view. The truck is parked on a dirt surface. Several workers in high-visibility vests and hard hats are standing around the truck. The date stamp '2023/6/13' is visible in the bottom right corner of the image.

88	GX-B1423/20-Y-233676	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow MT106 dump truck parked on a dirt surface. Two workers wearing high-visibility vests and hard hats are standing in front of the truck. The truck's model number 'MT106' is visible on the top of the dump body. A yellow date stamp '2023/6/13' is located in the bottom left corner of the image.</p>
89	GX-B1423/20-Y-233677	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow dump truck with its bed raised, parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A yellow date stamp '2023/6/13' is visible in the bottom right corner of the image.</p>

90	GX-B1423/20-Y-233678	2023年7月2日	综合判定：合格	 <p>A close-up photograph of a yellow dump truck's rear section, focusing on the large, treaded tires. Two workers in high-visibility yellow vests and hard hats are standing near the truck, appearing to be inspecting or working on it. The background shows a construction or industrial site with some structures and a clear sky. A yellow timestamp '2023/6/13' is visible in the bottom right corner of the image.</p>
91	GX-B1423/20-Y-233679	2023年7月2日	综合判定：合格	 <p>A photograph of a yellow dump truck parked in an open, dusty area under a clear blue sky. The truck is viewed from a side-rear angle. Two workers in high-visibility yellow vests and hard hats are standing near the truck. One worker in the foreground is holding a clipboard and looking towards the truck. The background shows a flat, open landscape. A yellow timestamp '2023/6/13' is visible in the bottom right corner of the image.</p>

92	GX-B1423/20-Y-233680	2023年7月2日	综合判定：合格	 <p>A photograph showing a person wearing a red hard hat, a white long-sleeved shirt, and a yellow high-visibility safety vest standing in front of a yellow MT108 dump truck. The truck is parked on a dirt surface. A yellow timestamp '2023/6/13' is visible in the bottom left corner of the photo.</p>
93	GX-B1423/20-Y-233681	2023年7月2日	综合判定：合格	 <p>A photograph showing two people wearing red hard hats and yellow safety vests standing in front of a yellow truck. The truck has a red flag on its roof. The scene is outdoors on a dirt surface. A yellow timestamp '2023/6/13' is visible in the bottom right corner of the photo.</p>

94	GX-B1423/20-Y-233682	2023年7月2日	综合判定：合格	
95	GX-B1423/20-Y-233683	2023年7月2日	综合判定：合格	

96	GX-B1423/20-Y-233684	2023年7月2日	综合判定：合格	
----	----------------------	-----------	---------	---