

序号	报告编号	发布日期	结论	影像资料
97	GX-B1423/20-Y-233363	2023年7月4日	综合判定：合格	
98	GX-B1423/20-Y-233364	2023年7月4日	综合判定：合格	

99	GX-B1423/20-Y-233365	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing next to the truck. A traffic cone is visible in the foreground. A yellow timestamp '2023/6/1' is in the bottom right corner.
100	GX-B1423/20-Y-233366	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing next to the truck. A traffic cone is visible in the foreground. A yellow timestamp '2023/6/1' is in the bottom right corner.

101	GX-B1423/20-Y-233367	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a sandy surface. Two workers wearing safety gear (hard hats and high-visibility vests) stand in front of the truck. A small red and white traffic cone is visible in the foreground. A yellow timestamp '2023/7/4' is present in the bottom right corner of the image.
102	GX-B1423/20-Y-233368	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a sandy surface. Two workers wearing safety gear (hard hats and high-visibility vests) stand in front of the truck. A small red and white traffic cone is visible in the foreground. A yellow timestamp '2023/7/4' is present in the bottom right corner of the image.

103	GX-B1423/20-Y-233369	2023年7月4日	综合判定：合格	
104	GX-B1423/20-Y-233370	2023年7月4日	综合判定：合格	

105	GX-B1423/20-Y-233371	2023年7月4日	综合判定：合格	 A yellow dump truck with the model number DW105A is shown. Two workers in safety gear are standing in front of it. A date stamp '2023/6/1' is visible in the bottom right corner of the photo.
106	GX-B1423/20-Y-233372	2023年7月4日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. Two workers in safety gear are standing in front of it. A date stamp '2023/6/1' is visible in the bottom right corner of the photo.

107	GX-B1423/20-Y-233373	2023年7月4日	综合判定：合格	 A photograph of a yellow construction vehicle, possibly a loader or truck, with a worker on top. In the foreground, another worker wearing a red hard hat and a light-colored shirt is standing. The vehicle has the number '2488' on its front. A yellow timestamp '2023/6/1' is visible in the bottom right corner of the photo.
108	GX-B1423/20-Y-233374	2023年7月4日	综合判定：合格	 A photograph of a yellow construction vehicle with its bucket raised. Two workers wearing hard hats and safety vests are standing in the foreground. The vehicle has the number 'M-245' on its side. A yellow timestamp '2023/6/1' is visible in the bottom right corner of the photo.

109	GX-B1423/20-Y-233375	2023年7月4日	综合判定：合格	
110	GX-B1423/20-Y-233376	2023年7月4日	综合判定：合格	

111	GX-B1423/20-Y-233377	2023年7月4日	综合判定：合格	 A close-up photograph of a yellow dump truck. Two workers in safety gear are standing near the front of the truck. A yellow timestamp '2023/6/4' is visible in the bottom right corner of the image.
112	GX-B1423/20-Y-233378	2023年7月4日	综合判定：合格	 A photograph of a yellow dump truck with its bed raised. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/1' is visible in the bottom right corner of the image.

113	GX-B1423/20-Y-233379	2023年7月4日	综合判定：合格	
114	GX-B1423/20-Y-233380	2023年7月4日	综合判定：合格	

115	GX-B1423/20-Y-233381	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, with license plate M-2782, is parked on a dirt surface. Two workers in safety gear stand in front of the truck. A date stamp '2023/6/4' is visible in the bottom right corner of the photo.
116	GX-B1423/20-Y-233382	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, with license plate M-2775, is parked on a dirt surface. Two workers in safety gear stand in front of the truck. A date stamp '2023/6/1' is visible in the bottom right corner of the photo.

117	GX-B1423/20-Y-233383	2023年7月4日	综合判定：合格	
118	GX-B1423/20-Y-233384	2023年7月4日	综合判定：合格	

119	GX-B1423/20-Y-233385	2023年7月4日	综合判定：合格	
120	GX-B1423/20-Y-233386	2023年7月4日	综合判定：合格	

121	GX-B1423/20-Y-233387	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers are standing in front of the truck. One worker is wearing a yellow high-visibility vest and a yellow hard hat, while the other is wearing a grey uniform and a red hard hat. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/6/2' is in the bottom right corner of the photo.
122	GX-B1423/20-Y-233388	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers are standing in front of the truck. One worker is wearing a yellow high-visibility vest and a yellow hard hat, while the other is wearing a grey uniform and a red hard hat. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/6/2' is in the bottom right corner of the photo.

123	GX-B1423/20-Y-233389	2023年7月4日	综合判定：合格	 A yellow dump truck with 'DW105A' on the side is parked on a dirt surface. Two workers in safety gear stand in front of it. A traffic cone is visible in the foreground. A yellow timestamp '2023/6/2' is in the bottom right corner.
124	GX-B1423/20-Y-233390	2023年7月4日	综合判定：合格	 A yellow dump truck with 'DW105A' on the side is parked on a dirt surface. Two workers in safety gear stand in front of it. A traffic cone is visible in the foreground. A yellow timestamp '2023/6/2' is in the bottom right corner.

125	GX-B1423/20-Y-233391	2023年7月4日	综合判定：合格	
126	GX-B1423/20-Y-233392	2023年7月4日	综合判定：合格	

127	GX-B1423/20-Y-233393	2023年7月4日	综合判定：合格	 <p>A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers wearing safety vests and hard hats are standing in front of the truck. The truck has 'DW105A' and 'M-2185' visible on its side. A date stamp '2023/6/2' is in the bottom right corner of the photo.</p>
128	GX-B1423/20-Y-233394	2023年7月4日	综合判定：合格	 <p>A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers wearing safety vests and hard hats are standing in front of the truck. The truck has 'DW105A' and 'M-2185' visible on its side. A date stamp '2023/6/2' is in the bottom right corner of the photo.</p>

129	GX-B1423/20-Y-233395	2023年7月4日	综合判定：合格	
130	GX-B1423/20-Y-233396	2023年7月4日	综合判定：合格	

131	GX-B1423/20-Y-233397	2023年7月4日	综合判定：合格	
132	GX-B1423/20-Y-233398	2023年7月4日	综合判定：合格	

133	GX-B1423/20-Y-233399	2023年7月4日	综合判定：合格	
134	GX-B1423/20-Y-233400	2023年7月4日	综合判定：合格	

135	GX-B1423/20-Y-233401	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW10SA, is parked on a sandy surface. Two workers in safety gear are standing in front of the truck. The truck has '柳工' (LiuGong) and 'DW10SA' written on its side. A date stamp '2023/6/2' is visible in the bottom right corner of the photo.
136	GX-B1423/20-Y-233402	2023年7月4日	综合判定：合格	 A yellow dump truck, model DW10SA, is parked on a sandy surface. Two workers in safety gear are standing in front of the truck. The truck has '柳工' (LiuGong) and 'DW10SA' written on its side. A date stamp '2023/6/2' is visible in the bottom right corner of the photo.

137	GX-B1423/20-Y-233403	2023年7月4日	综合判定：合格	
138	GX-B1423/20-Y-233404	2023年7月4日	综合判定：合格	

139	GX-B1423/20-Y-233405	2023年7月4日	综合判定：合格	
140	GX-B1423/20-Y-233406	2023年7月4日	综合判定：合格	

141	GX-B1423/20-Y-233407	2023年7月4日	综合判定：合格	
142	GX-B1423/20-Y-233408	2023年7月4日	综合判定：合格	

143	GX-B1423/20-Y-233409	2023年7月4日	综合判定：合格	
144	GX-B1423/20-Y-233410	2023年7月4日	综合判定：合格	

145	GX-B1423/20-Y-233411	2023年7月4日	综合判定：合格	
146	GX-B1423/20-Y-233414	2023年7月4日	综合判定：合格	

147	GX-B1423/20-Y-233415	2023年7月4日	综合判定：合格	
148	GX-B1423/20-Y-233416	2023年7月4日	综合判定：合格	

149	GX-B1423/20-Y-233417	2023年7月4日	综合判定：合格	
150	GX-B1423/20-Y-233418	2023年7月4日	综合判定：合格	

151	GX-B1423/20-Y-233419	2023年7月4日	综合判定：合格	
152	GX-B1423/20-Y-233420	2023年7月4日	综合判定：合格	

153	GX-B1423/20-Y-233421	2023年7月4日	综合判定：合格	
154	GX-B1423/20-Y-233422	2023年7月4日	综合判定：合格	

155	GX-B1423/20-Y-233423	2023年7月4日	综合判定：合格	
156	GX-B1423/20-Y-233424	2023年7月4日	综合判定：合格	

157	GX-B1423/20-Y-233425	2023年7月4日	综合判定：合格	
158	GX-B1423/20-Y-233426	2023年7月4日	综合判定：合格	

159	GX-B1423/20-Y-233427	2023年7月4日	综合判定：合格	
160	GX-B1423/20-Y-233428	2023年7月4日	综合判定：合格	

161	GX-B1423/20-Y-233429	2023年7月4日	综合判定：合格	
162	GX-B1423/20-Y-233430	2023年7月4日	综合判定：合格	

163	GX-B1423/20-Y-233431	2023年7月4日	综合判定：合格	
164	GX-B1423/20-Y-233432	2023年7月4日	综合判定：合格	

165	GX-B1423/20-Y-233433	2023年7月4日	综合判定：合格	
166	GX-B1423/20-Y-233434	2023年7月4日	综合判定：合格	

167	GX-B1423/20-Y-233435	2023年7月4日	综合判定：合格	
168	GX-B1423/20-Y-233436	2023年7月4日	综合判定：合格	

169	GX-B1423/20-Y-233437	2023年7月4日	综合判定：合格	
170	GX-B1423/20-Y-233438	2023年7月4日	综合判定：合格	

171	GX-B1423/20-Y-233439	2023年7月4日	综合判定：合格	
172	GX-B1423/20-Y-233440	2023年7月4日	综合判定：合格	

173	GX-B1423/20-Y-233441	2023年7月4日	综合判定：合格	
174	GX-B1423/20-Y-233442	2023年7月4日	综合判定：合格	

175	GX-B1423/20-Y-233443	2023年7月4日	综合判定：合格	
176	GX-B1423/20-Y-233444	2023年7月4日	综合判定：合格	

177	GX-B1423/20-Y-233445	2023年7月4日	综合判定：合格	
178	GX-B1423/20-Y-233446	2023年7月4日	综合判定：合格	

179	GX-B1423/20-Y-233447	2023年7月4日	综合判定：合格	
180	GX-B1423/20-Y-233448	2023年7月4日	综合判定：合格	

181	GX-B1423/20-Y-233449	2023年7月4日	综合判定：合格	
182	GX-B1423/20-Y-233450	2023年7月4日	综合判定：合格	

183	GX-B1423/20-Y-233451	2023年7月4日	综合判定：合格	
184	GX-B1423/20-Y-233452	2023年7月4日	综合判定：合格	

185	GX-B1423/20-Y-233453	2023年7月4日	综合判定：合格	 A yellow dump truck with the number '2415' on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/6/5' is visible in the bottom right corner of the photo.
186	GX-B1423/20-Y-233454	2023年7月4日	综合判定：合格	 A yellow dump truck with the number '2417' on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/6/5' is visible in the bottom right corner of the photo.

187

GX-B1423/20-Y-233455

2023年7月4日

综合判定：合格

