

序号	报告编号	发布日期	结论	影像资料
51	GX-B1322/21-4-23068~23073	2023. 7. 4	本次共检验电力电缆6条，6条所检项目合格。	
52	GX-B1416/22-4-23017	2023. 7. 5	综合判定：合格	
53	GX-B1416/22-4-23018	2023. 7. 5	综合判定：合格	

54	GX-B1416/22-4-23019	2023. 7. 5	综合判定：合格	
55	GX-B1416/22-4-23020	2023. 7. 5	综合判定：合格	
56	GX-B1416/22-4-23021	2023. 7. 5	综合判定：合格	

57	GX-B1321/20-4-23916~23917	2023. 7. 6	本次共检电力电缆2条，2条所检项目合格。	
58	GX-B1306/21-4-23046	2023. 7. 7	所检项目合格。	
59	GX-B1423/20-4-23030	2023. 7. 7	综合判定：合格	


60	GX-B1423/20-4-23031	2023. 7. 7	综合判定：合格	 <p>2023. 6. 16</p>
61	GX-B1423/20-4-23032	2023. 7. 7	综合判定：合格	 <p>2023. 6. 16</p>
62	GX-B1423/20-4-23033	2023. 7. 7	综合判定：合格	 <p>2023. 6. 16</p>

63	GX-B1423/20-4-23034	2023. 7. 7	综合判定：合格	 A yellow truck with 'K049' on the side is parked. Three workers in blue uniforms and red hard hats are standing next to it. A red date stamp '2023. 6. 16' is at the bottom right.
64	GX-B1423/20-4-23035	2023. 7. 7	综合判定：合格	 A yellow truck is parked. One worker in a blue uniform and red hard hat is kneeling on the ground in front of the truck, while another worker stands nearby. A red date stamp '2023. 6. 16' is at the bottom right.
65	GX-B1423/20-4-23036	2023. 7. 7	综合判定：合格	 A yellow truck is parked. One worker in a blue uniform and red hard hat is kneeling on the ground in front of the truck, while two other workers stand nearby. A red date stamp '2023. 6. 16' is at the bottom right.

66	GX-B1423/20-4-23037	2023. 7. 7	综合判定：合格	 A yellow truck with license plate K053 is parked. Three workers in blue and grey uniforms and hard hats stand in front of it. The truck has '陕汽重卡' (Shaanxi Heavy Truck) written on the side. A red date stamp '2023. 7. 16' is visible in the bottom right corner of the photo.
67	GX-B1423/20-4-23038	2023. 7. 7	综合判定：合格	 A yellow truck with license plate K057 is parked in an open area. Three workers in blue and grey uniforms and hard hats stand in front of it. The truck has '陕汽重卡' (Shaanxi Heavy Truck) written on the side. A red date stamp '2023. 6. 16' is visible in the bottom right corner of the photo.
68	GX-B1423/20-4-23039	2023. 7. 7	综合判定：合格	 A yellow truck with license plate K058 is parked. Four workers in blue and grey uniforms and hard hats stand in front of it. The truck has '陕汽重卡' (Shaanxi Heavy Truck) written on the side. A red date stamp '2023. 6. 16' is visible in the bottom right corner of the photo.

69	GX-B1300/20-4-23008	2023. 7. 7	综合判定：合格。	
70	GX-B1310/21-4-23103	2023. 7. 7	符合标准要求	
71	GX-B1424/20-4-23022	2023. 7. 7	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。	

72	GX-B1548/20-4-23001	2023. 7. 7	所检项目合格	
73	GX-B1415/22-4-23009	2023. 7. 10	综合判定：合格。	
74	GX-B1415/22-4-23010	2023. 7. 10	综合判定：合格。	

75	GX-B1415/22-4-23011	2023. 7. 10	综合判定：合格。	
76	GX-B1310/21-4-23093	2023. 7. 10	符合标准要求	
77	GX-B1310/21-4-23076	2023. 7. 10	符合标准要求	

78	GX-B1310/21-4-23077	2023. 7. 10	符合标准要求		 <p>2023/5/10</p>	
79	GX-B1310/21-4-23078	2023. 7. 10	符合标准要求		 <p>2023/5/10</p>	
80	GX-B1310/21-4-23079	2023. 7. 10	符合标准要求		 <p>2023/5/10</p>	

81	GX-B1310/21-4-23080	2023. 7. 10	符合标准要求			
82	GX-B1310/21-4-23081	2023. 7. 10	符合标准要求			
83	GX-B1310/21-4-23082	2023. 7. 10	符合标准要求			

84	GX-B1428/21-4-23084	2023. 7. 10	无缺陷痕迹显示			
85	GX-B1428/21-4-23083	2023. 7. 10	无缺陷痕迹显示			
86	GX-B1451/20-4-23094~23095	2023. 7. 10	本次共检高压开关柜2面，2面高压开关柜所检项目合格。			

87	GX-B1324/21-4-23022~23023	2023. 7. 10	<p>本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。</p> <p>。</p>	
88	GX-B1328/20-4-23136	2023. 7. 10	<p>本次共检绝缘手套2只，2只所检项目合格。</p>	
89	GX-B1328/20-4-23137	2023. 7. 10	<p>本次共检绝缘鞋2只，2只所检项目合格。</p>	

90	GX-B1328/20-4-23138	2023. 7. 10	所检项目合格。	
91	GX-B1328/20-4-23123	2023. 7. 10	本次共检绝缘手套2只，2只所检项目合格。	
92	GX-B1328/20-4-23124	2023. 7. 10	本次共检绝缘鞋2只，2只所检项目合格。	

93	GX-B1328/20-4-23131	2023. 7. 10	所检项目合格	
94	GX-B1328/20-4-23132	2023. 7. 10	所检项目合格	
95	GX-B1350/21-4-23063	2023. 7. 11	本次共检接地装置4处，4处所检项目合格。	

96	GX-B1517/20-4-23024	2023. 7. 11	综合判定：合格	 <p>2023. 7. 4</p>	
97	GX-B1517/20-4-23025	2023. 7. 11	综合判定：合格	 <p>2023. 7. 4</p>	
98	GX-B1303/21-4-23008	2023. 7. 11	综合判定：合格。 。	 <p>2023. 6. 14</p>	


99	GX-B1303/21-4-23007	2023. 7. 11	综合判定：合格。 。	
100	GX-B1328/20-4-23134	2023. 7. 12	本次共检绝缘手套2只，2只所检项目合格。	
101	GX-B1328/20-4-23135	2023. 7. 12	本次共检绝缘鞋2只，2只所检项目合格。	

102	GX-B1313/21-4-23044~23046	2023. 7. 12	本次共检电力变压器3台，3台所检项目合格。			
103	GX-B1322/21-4-23074~23078	2023. 7. 12	本次共检电力电缆5条，5条所检项目合格。			
104	GX-B1329/21-4-23120~23124	2023. 7. 12	本次共检氧化锌避雷器5组，5组氧化锌避雷器所检项目合格。			

105	GX-B1328/20-4-23139	2023. 7. 12	本次共检绝缘手套4只，4只所检项目合格。	
106	GX-B1328/20-4-23140	2023. 7. 12	本次共检绝缘鞋4只，4只所检项目合格。	
107	GX-B1328/20-4-23141	2023. 7. 12	本次共检绝缘杆2支，2支所检项目合格。	

108	GX-B1328/20-4-23142	2023. 7. 12	所检项目合格。	
109	GX-B1328/20-4-23143	2023. 7. 12	本次共检携带式短路接地线2组，2组所检项目合格。	
110	GX-B1313/21-4-23027~23035	2023. 7. 12	本次共检电力变压器9台，9台电力变压器所检项目合格。	

111	GX-B1313/21-4-23036	2023. 7. 12	所检项目合格。	
112	GX-B1313/21-4-23037~23038	2023. 7. 12	本次共检电力变压器2台，2台电力变压器所检项目合格。	
113	GX-B1313/21-4-23039	2023. 7. 12	所检项目合格。	

114	GX-B1313/21-4-23040~23043	2023. 7. 12	本次共检电力变压器4台，4台电力变压器所检项目合格。	
115	GX-B1416/22-4-23013	2023. 7. 13	综合判定：合格	
116	GX-B1416/22-4-23014	2023. 7. 13	综合判定：合格	

117	GX-B1416/22-4-23015	2023. 7. 13	综合判定：合格		 A black and white photograph showing a worker in a high-visibility safety jacket and a hard hat. The worker is positioned in front of a metal grid or railing, possibly performing maintenance or inspection. The scene is dimly lit, with the worker's jacket reflecting light. In the bottom right corner of the image, the date '2023/6/9' is printed.	
-----	---------------------	-------------	---------	--	---	--