

序号	报告编号	发布日期	结论	影像资料
78	GX-B1495/20-6-231298~231299	2023/7/6	所检项目合格	
79	GX-B1495/20-6-231300~231301	2023/7/6	所检项目合格	
80	GX-B1321/20-6-23761~23769	2023/7/3	所检项目合格	

81	GX-B1312/20-6-23341~23343	2023/7/3	所检项目合格	
82	GX-B1495/20-6-231046~231052	2023/7/6	所检项目合格	
83	GX-B1495/20-6-231053~231054	2023/7/6	所检项目合格	

84	GX-B1495/20-6-231055~231065	2023/7/6	所检项目合格	 A worker in a blue uniform and helmet is kneeling on a yellow safety line in a factory setting, using a handheld device to inspect equipment. A red control panel is visible in the background. The timestamp in the bottom right corner of the image is 2023 05 09.
85	GX-B1495/20-6-231066~231075	2023/7/6	所检项目合格	 A worker in a blue uniform and helmet is kneeling on a yellow safety line, using a handheld device to inspect equipment. The worker is wearing orange gloves. The timestamp in the bottom right corner of the image is 2023 05 10.
86	GX-B1381/20-6-23005	2023/7/6	所检项目合格	 A worker in a blue uniform and helmet is standing in a factory setting, using a handheld device to inspect equipment. The worker is wearing a headlamp. The timestamp in the bottom right corner of the image is 2023 05 08.

87	GX-B1310/21-6-23065	2023/7/6	未发现超过 $\phi$ 2mm当量直径的缺陷	
88	GX-B1383/21-6-23005	2023/7/5	所检项目合格	
89	GX-B1383/21-6-23006	2023/7/5	所检项目合格	

90	GX-B1423/20-6-23657	2023/7/6	综合判定合格	
91	GX-B1423/20-6-23658	2023/7/6	综合判定合格	
92	GX-B1423/20-6-23659	2023/7/6	综合判定合格	

93	GX-B1328/20-6-23100	2023/7/7	所检项目合格	
94	GX-B1328/20-6-23101	2023/7/7	所检项目合格	
95	GX-B1328/20-6-23102	2023/7/7	所检项目合格	

96	GX-B1328/20-6-23103	2023/7/7	所检项目合格	
97	GX-B1328/20-6-23104	2023/7/7	所检项目合格	
98	GX-B1328/20-6-23105	2023/7/7	所检项目合格	

99	GX-B1520/20-6-23076	2023/7/7	综合判定合格		
100	GX-B1520/20-6-23077	2023/7/7	综合判定合格		
101	GX-B1520/20-6-23078	2023/7/7	综合判定合格		



102	GX-B1520/20-6-23079	2023/7/7	综合判定合格	
103	GX-B1520/20-6-23080	2023/7/7	综合判定合格	
104	GX-B1520/20-6-23081	2023/7/7	综合判定合格	

105	GX-B1423/20-6-23647	2023/7/7	综合判定合格	
106	GX-B1423/20-6-23648	2023/7/7	综合判定合格	
107	GX-B1423/20-6-23649	2023/7/7	综合判定合格	

108	GX-B1423/20-6-23650	2023/7/7	综合判定合格	
109	GX-B1423/20-6-23651	2023/7/7	综合判定合格	
110	GX-B1423/20-6-23652	2023/7/7	综合判定合格	

111	GX-B1423/20-6-23653	2023/7/7	综合判定合格	
112	GX-B1423/20-6-23654	2023/7/7	综合判定合格	
113	GX-B1423/20-6-23655	2023/7/7	综合判定合格	

114	GX-B1423/20-6-23656	2023/7/7	综合判定合格	
115	GX-B1423/20-6-23516	2023/7/7	综合判定合格	
116	GX-B1423/20-6-23517	2023/7/7	综合判定合格	

117	GX-B1423/20-6-23518	2023/7/7	综合判定合格	
118	GX-B1423/20-6-23519	2023/7/7	综合判定合格	
119	GX-B1423/20-6-23520	2023/7/7	综合判定合格	

120	GX-B1423/20-6-23521	2023/7/7	综合判定合格	
121	GX-B1328/20-6-23100	2023/7/7	所检项目合格	
122	GX-B1328/20-6-23101	2023/7/7	所检项目合格	

123	GX-B1328/20-6-23102	2023/7/7	所检项目合格	
124	GX-B1328/20-6-23103	2023/7/7	所检项目合格	
125	GX-B1328/20-6-23104	2023/7/7	所检项目合格	



126	GX-B1328/20-6-23105	2023/7/7	所检项目合格	
127	GX-B1310/21-6-23078	2023/7/7	符合标椎要求	
128	GX-B1423/20-6-23679	2023/7/10	综合判定合格	

129	GX-B1423/20-6-23680	2023/7/10	综合判定合格	
130	GX-B1423/20-6-23681	2023/7/10	综合判定合格	
131	GX-B1423/20-6-23682	2023/7/10	综合判定合格	

132	GX-B1495/20-6-231302~231311	2023/7/7	所检项目合格	
133	GX-B1306/21-6-23007	2023/7/11	所检项目合格	
134	GX-B1306/21-6-23008	2023/7/11	所检项目合格	

135	GX-B1306/21-6-23009	2023/7/11	所检项目合格	
136	GX-B1423/20-6-23700	2023/7/10	综合判定合格	
137	GX-B1423/20-6-23701	2023/7/10	综合判定合格	

138	GX-B1423/20-6-23702	2023/7/10	综合判定合格	
139	GX-B1423/20-6-23703	2023/7/10	综合判定合格	
140	GX-B1423/20-6-23704	2023/7/10	综合判定合格	

141	GX-B1423/20-6-23705	2023/7/10	综合判定合格	 A photograph showing two men in light-colored work shirts and safety helmets (one yellow, one red) standing in front of a yellow piece of heavy machinery. A date stamp '2023-7-5' is visible in the bottom right corner of the image.
142	GX-B1307/20-6-23030	2023/7/11	综合判定合格	 A photograph of two workers in camouflage uniforms and white hard hats standing in an industrial area with large metal cabinets. A date stamp '2023 06 20' is visible in the bottom right corner.
143	GX-B1307/20-6-23032	2023/7/11	综合判定合格	 A photograph of a worker in a camouflage uniform and white hard hat standing next to a large, vertical industrial tank. A date stamp '2023 06 21' is visible in the bottom right corner.

144	GX-B1307/20-6-23033	2023/7/11	综合判定合格	
145	GX-B1307/20-6-23034	2023/7/11	综合判定合格	
146	GX-B1307/20-6-23035	2023/7/11	综合判定合格	

147	GX-B1307/20-6-23036	2023/7/11	综合判定合格	 <p>2023/06/22</p>
148	GX-B1307/20-6-23037	2023/7/11	综合判定合格	 <p>2023/07/22</p>
149	GX-B1322/21-6-23172~23174	2023/7/11	所检项目合格	 <p>2023/06/22</p>



150	GX-B1322/21-6-23175~23185	2023/7/11	所检项目合格	 <p>2023 06 21</p>
151	GX-B1303/21-6-23008	2023/7/11	综合判定合格	 <p>2023 06 21</p>
152	GX-B1305/21-6-23007	2023/7/11	综合判定合格	 <p>2023 06 20</p>

153	GX-B1382/21-6-23016	2023/7/11	合格		
154	GX-B1382/21-6-23017	2023/7/11	合格		
155	GX-B1380/20-6-23022	2023/7/11	所检项目合格		

156	GX-B1380/20-6-23023	2023/7/12	所检项目合格	 2023.06.21
157	GX-B1380/20-6-23024	2023/7/13	所检项目合格	 2023.06.22