

序号	报告编号	发布日期	结论	影像资料
247	GX-B1321/20-Y-23440-23444	2023年7月5日	本次共检验电力电缆5条，5条电力电缆均合格。	
248	GX-B1321/20-Y-23445-23448	2023年7月5日	本次共检验电力电缆4条，4条电力电缆均合格。	

249	GX-B1321/20-Y-23449-23456	2023年7月5日	本次共检验电力电缆8条，8条电力电缆均合格。	
250	GX-B1312/20-Y-23355~23357	2023年7月6日	本次共检电力变压器3台，3台电力变压器所检项目合格。	

251	GX-B1312/20-Y-23358~23360	2023年7月6日	本次共检电力变压器3台，3台电力变压器所检项目合格。	
252	GX-B1312/20-Y-23361~23364	2023年7月6日	本次共检电力变压器4台，4台电力变压器所检项目合格。	

253	GX-B1312/20-Y-23365~23369	2023年7月6日	本次共检电力变压器4台，4台电力变压器所检项目合格。	
254	GX-B1385/21-Y-23072	2023年7月6日	所检项目合格。	

255	GX-B1307/20-Y-23007	2023年7月7日	综合判定：合格	
256	GX-B1307/20-Y-23008	2023年7月7日	综合判定：合格	

257	GX-B1306/21-Y-23105	2023年7月7日	所检项目合格。	 A worker wearing a grey uniform, a red hard hat, and a blue face mask is inspecting the engine compartment of a blue piece of machinery. The worker is leaning over the engine, and the machinery has various pipes and components visible. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.
258	GX-B1306/21-Y-23106	2023年7月7日	综合判定：合格	 A worker wearing a grey uniform, a red hard hat, and a blue face mask is standing next to a blue piece of machinery outdoors. The worker is looking at the machinery. The background shows a desert-like landscape with hills under a clear blue sky. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.

259	GX-B1306/21-Y-23107	2023年7月7日	所检项目合格。	
260	GX-B1306/21-Y-23108	2023年7月7日	综合判定：合格	

261	GX-B1306/21-Y-23109	2023年7月7日	所检项目合格。	
262	GX-B1306/21-Y-23110	2023年7月7日	综合判定：合格	

263	GX-B1306/21-Y-23111	2023年7月7日	所检项目合格。	
264	GX-B1306/21-Y-23112	2023年7月7日	综合判定：合格	

265	GX-B1306/21-Y-23113	2023年7月7日	所检项目合格。	
266	GX-B1306/21-Y-23114	2023年7月7日	综合判定：合格	

267	GX-B1306/21-Y-23115	2023年7月7日	所检项目合格。	
268	GX-B1306/21-Y-23116	2023年7月7日	综合判定：合格	

269	GX-B1559/22-Y-23010	2023年7月6日	所检项目合格。	
270	GX-B1559/22-Y-23011	2023年7月6日	所检项目合格。	

271	GX-B1517/20-Y-23018	2023年7月7日	所检项目合格。	
272	GX-B1517/20-Y-23019	2023年7月7日	所检项目合格。	

273	GX-B1517/20-Y-23020	2023年7月7日	综合判定：合格。 。	
274	GX-B1312/20-Y-23369	2023年7月7日	所检项目合格。	

275	GX-B1329/21-Y-23192~23199	2023年7月6日	本次共检氧化锌避雷器8组，8组氧化锌避雷器所检项目合格。	
276	GX-B1312/20-Y-23370	2023年7月7日	所检项目合格	

277	GX-B1312/20-Y-23371~23372	2023年7月7日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
278	GX-B1312/20-Y-23373	2023年7月7日	所检项目合格	

279	GX-B1312/20-Y-23374	2023年7月7日	所检项目合格	
280	GX-B1312/20-Y-23375	2023年7月7日	所检项目合格	

281	GX-B1495/20-Y-231511~ 231521	2023年7月6日	本次共检高压开关设备11台，11台高压开关设备所检项目合格。	
282	GX-B1495/20-Y-231522~ 231525	2023年7月6日	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	

283	GX-B1495/20-Y-231526~ 231534	2023年7月6日	本次共检高压开关设备9台，9台高压开关设备所检项目合格。	
284	GX-B1515/22-Y-23007	2023年7月10日	所检项目合格。	

285	GX-B1515/22-Y-23008	2023年7月10日	所检项目合格。	
286	GX-B1310/21-Y-23114	2023年7月10日	符合标准要求。	

287	GX-B1428/21-Y-23114	2023年7月10日	无缺陷迹痕显示。	
288	GX-B1310/21-Y-23115	2023年7月10日	符合标准要求。	

289	GX-B1428/21-Y-23115	2023年7月10日	无缺陷迹痕显示。	 <p>A photograph showing a worker wearing a red hard hat and dark clothing, leaning into a large, circular, metallic structure, possibly a tunnel or a large pipe. The worker appears to be inspecting the interior surface. A yellow timestamp '2023/6/10' is visible in the bottom right corner of the image.</p>
290	GX-B1522/20-Y-23111	2023年7月10日	所检项目合格。	 <p>A photograph of a worker in a red hard hat and light-colored uniform standing next to a yellow excavator. The excavator has 'ZL7M' and 'RT7M' markings on its side. The worker is holding a tool or device. The background shows a hilly, outdoor environment. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the image.</p>

291	GX-B1522/20-Y-23112	2023年7月10日	综合判定：合格	
292	GX-B1522/20-Y-23113	2023年7月10日	所检项目合格。	

293	GX-B1522/20-Y-23114	2023年7月10日	所检项目合格。	
294	GX-B1522/20-Y-23115	2023年7月10日	综合判定：合格	

295	GX-B1522/20-Y-23116	2023年7月10日	所检项目合格。	
296	GX-B1522/20-Y-23117	2023年7月10日	所检项目合格。	

297	GX-B1522/20-Y-23118	2023年7月10日	综合判定：合格	
298	GX-B1522/20-Y-23119	2023年7月10日	所检项目合格。	

299	GX-B1522/20-Y-23120	2023年7月10日	综合判定：合格	 <p>A photograph of a red tracked drilling rig at a construction site. Two workers in safety gear are visible. A date stamp '2023/6/26' is in the bottom right corner.</p>
300	GX-B1522/20-Y-23121	2023年7月10日	综合判定：合格	 <p>A photograph of an orange tracked drilling rig at a construction site. A worker in safety gear is standing next to it. A date stamp '2023/6/26' is in the bottom right corner.</p>

301	GX-B1495/20-Y-231535~ 231543	2023年7月10日	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	
302	GX-B1495/20-Y-231544~ 231554	2023年7月10日	本次共检高压防爆开关11台，11台高压防爆开关所检项目合格。	

303	GX-B1495/20-Y-231555~ 231561	2023年7月10日	本次共检高压防爆开关7台，7台高压防爆开关所检项目合格。	
304	GX-B1495/20-Y-231562~ 231569	2023年7月10日	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	

305	GX-B1495/20-Y-231570~ 231579	2023年7月10日	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
306	GX-B1495/20-Y-231580~ 231587	2023年7月10日	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	

307	GX-B1495/20-Y-231588~ 231597	2023年7月10日	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
308	GX-B1495/20-Y-231598~ 231605	2023年7月10日	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	

309	GX-B1329/21-Y-23200~23208	2023年7月10日	本次共检氧化锌避雷器9组，9组氧化锌避雷器所检项目合格。	
310	GX-B1329/21-Y-23209~23219	2023年7月10日	本次共检氧化锌避雷器11组，11组氧化锌避雷器所检项目合格。	

311	GX-B1329/21-Y-23220~23226	2023年7月10日	本次共检氧化锌避雷器7组，7组氧化锌避雷器所检项目合格。	
312	GX-B1329/21-Y-23227~23234	2023年7月10日	本次共检氧化锌避雷器8组，8组氧化锌避雷器所检项目合格。	

313	GX-B1329/21-Y-23235~23244	2023年7月10日	本次共检氧化锌避雷器10组，10组氧化锌避雷器所检项目合格。	
314	GX-B1329/21-Y-23245~23252	2023年7月10日	本次共检氧化锌避雷器8组，8组氧化锌避雷器所检项目合格。	

315	GX-B1329/21-Y-23253~23262	2023年7月10日	本次共检氧化锌避雷器10组，10组氧化锌避雷器所检项目合格。	
316	GX-B1329/21-Y-23263~23270	2023年7月10日	本次共检氧化锌避雷器8组，8组氧化锌避雷器所检项目合格。	

317	GX-B1423/20-Y-233850	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY SKT105E A157 dump truck parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date '2023/6/26' is visible in the bottom right corner of the image.
318	GX-B1423/20-Y-233851	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY SKT105E A151 dump truck parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date '2023/6/26' is visible in the bottom right corner of the image.

319	GX-B1423/20-Y-233852	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY SKT105E dump truck with the identification number A138. The truck is parked on a dirt surface. A person in a high-visibility vest is standing next to the truck. A yellow date stamp '2023/6/26' is visible in the bottom right corner of the image.
320	GX-B1423/20-Y-233853	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY SKT105E dump truck with the identification number A137. The truck is parked on a dirt surface. A person in a high-visibility vest is standing next to the truck. A yellow date stamp '2023/6/26' is visible in the bottom right corner of the image.

321	GX-B1423/20-Y-233854	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY A150 dump truck parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has 'SANY' and 'A150' written on its side. A yellow date stamp '2023/6/26' is visible in the bottom right corner of the image.
322	GX-B1423/20-Y-233855	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY A158 dump truck parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has 'SANY' and 'A158' written on its side. A yellow date stamp '2023/6/26' is visible in the bottom right corner of the image.

323	GX-B1423/20-Y-233856	2023年7月9日	综合判定：合格	
324	GX-B1423/20-Y-233857	2023年7月9日	综合判定：合格	

325	GX-B1423/20-Y-233858	2023年7月9日	综合判定：合格	
326	GX-B1423/20-Y-233859	2023年7月9日	综合判定：合格	

327	GX-B1423/20-Y-233860	2023年7月9日	综合判定：合格	
328	GX-B1423/20-Y-233861	2023年7月9日	综合判定：合格	

329	GX-B1423/20-Y-233862	2023年7月9日	综合判定：合格	 <p>2023/6/27</p>
330	GX-B1423/20-Y-233863	2023年7月9日	综合判定：合格	 <p>2023/6/27</p>

331	GX-B1423/20-Y-233864	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY SKT105E truck with a black cab and a yellow dump body. The truck is parked on a paved surface. Two workers in safety gear are standing in front of the truck. The truck has 'A155' written on the side of the cab and 'SANY SKT105E' on the side of the dump body. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the image.
332	GX-B1423/20-Y-233865	2023年7月9日	综合判定：合格	 A photograph of a yellow SANY SKT105E truck with a black cab and a yellow dump body. The truck is parked on a paved surface. Two workers in safety gear are standing in front of the truck. The truck has 'A128' written on the side of the cab and 'SANY SKT105E' on the side of the dump body. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the image.

333	GX-B1423/20-Y-233866	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow SANY SKT105E dump truck with the identification number A127 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/6/27 is visible in the bottom right corner of the image.</p>
334	GX-B1423/20-Y-233867	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow SANY SKT105E dump truck with the identification number A119 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/6/27 is visible in the bottom right corner of the image.</p>

335	GX-B1423/20-Y-233868	2023年7月9日	综合判定：合格	
336	GX-B1423/20-Y-233869	2023年7月9日	综合判定：合格	

337	GX-B1423/20-Y-233870	2023年7月9日	综合判定：合格	
338	GX-B1423/20-Y-233871	2023年7月9日	综合判定：合格	

339	GX-B1423/20-Y-233872	2023年7月9日	综合判定：合格	
340	GX-B1423/20-Y-233873	2023年7月9日	综合判定：合格	

341	GX-B1423/20-Y-233874	2023年7月9日	综合判定：合格	
342	GX-B1423/20-Y-233875	2023年7月9日	综合判定：合格	

343	GX-B1423/20-Y-233876	2023年7月9日	综合判定：合格	
344	GX-B1423/20-Y-233877	2023年7月9日	综合判定：合格	

345	GX-B1423/20-Y-233878	2023年7月9日	综合判定：合格	
346	GX-B1423/20-Y-233879	2023年7月9日	综合判定：合格	

347	GX-B1423/20-Y-233923	2023年7月9日	综合判定：合格	 <p>A photograph showing the front view of a yellow TONLY dump truck. Two workers wearing safety vests and hard hats are standing in front of the truck. The truck has 'TONLY' written on the top of the dump body. A yellow timestamp '2023/6/17' is visible in the bottom right corner of the image.</p>
348	GX-B1423/20-Y-233924	2023年7月9日	综合判定：合格	 <p>A photograph showing the side view of a yellow dump truck. The side of the dump body has the number '777' written on it. Two workers wearing safety vests and hard hats are standing next to the truck. A yellow timestamp '2023/6/17' is visible in the bottom right corner of the image.</p>

349	GX-B1423/20-Y-233925	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 785 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date 2023-6-17 is visible in the bottom right corner of the photo.
350	GX-B1423/20-Y-233926	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 780 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date 2023-6-17 is visible in the bottom right corner of the photo.

351	GX-B1423/20-Y-233927	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 787 on its side, parked on a dirt surface. Two workers in safety vests are standing near the front of the truck. The date 2023/6/17 is visible in the bottom right corner of the image.
352	GX-B1423/20-Y-233928	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 779 on its side, parked on a dirt surface. Two workers in safety vests are standing near the front of the truck. The date 2023/6/17 is visible in the bottom right corner of the image.

353	GX-B1423/20-Y-233929	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 786 on its side, parked on a dirt surface. Two workers in safety vests are standing in front of the truck. A yellow timestamp '2023/6/17' is visible in the bottom right corner of the photo.
354	GX-B1423/20-Y-233930	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 781 on its side, parked on a dirt surface. Two workers in safety vests are standing in front of the truck. A yellow timestamp '2023/6/17' is visible in the bottom right corner of the photo.

355	GX-B1423/20-Y-233931	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 778 on its side, parked on a dirt surface. Two workers in safety gear are standing in front of it. A yellow timestamp '2023/6/17' is visible in the bottom right corner of the photo.
356	GX-B1423/20-Y-233932	2023年7月9日	综合判定：合格	 A yellow dump truck with the number 783 on its side, parked on a dirt surface. Two workers in safety gear are standing in front of it. A yellow timestamp '2023/6/17' is visible in the bottom right corner of the photo.

357	GX-B1423/20-Y-233933	2023年7月9日	综合判定：合格	
358	GX-B1423/20-Y-233934	2023年7月9日	综合判定：合格	

359	GX-B1423/20-Y-233935	2023年7月9日	综合判定：合格	
360	GX-B1423/20-Y-233936	2023年7月9日	综合判定：合格	

361	GX-B1423/20-Y-233937	2023年7月9日	综合判定：合格	
362	GX-B1423/20-Y-233938	2023年7月9日	综合判定：合格	

363	GX-B1423/20-Y-233939	2023年7月9日	综合判定：合格	 A photograph of a yellow truck with a red bumper and a person in a high-visibility vest standing next to it on a dirt road. The truck has 'WT110FA' on the front. A yellow timestamp '2023/6/17' is in the bottom right corner.
364	GX-B1423/20-Y-233940	2023年7月9日	综合判定：合格	 A photograph of a yellow truck with a red bumper and a person in a high-visibility vest standing next to it on a dirt road. The truck has 'WT110FA' on the front. A yellow timestamp '2023/6/17' is in the bottom right corner.

365	GX-B1423/20-Y-233941	2023年7月9日	综合判定：合格	
366	GX-B1423/20-Y-233942	2023年7月9日	综合判定：合格	

367	GX-B1423/20-Y-233943	2023年7月9日	综合判定：合格	 A yellow dump truck with the number '95' on its side and '95' on the front. Two workers in safety gear are standing next to it. A yellow timestamp '2023/6/17' is in the bottom right corner.
368	GX-B1423/20-Y-233944	2023年7月9日	综合判定：合格	 A yellow dump truck with the number '761' on its side and '761' on the front. Two workers in safety gear are standing next to it. A yellow timestamp '2023/6/17' is in the bottom right corner.

369	GX-B1423/20-Y-233945	2023年7月9日	综合判定：合格	 <p>A yellow Weichai dump truck with the number 93 on its side and a blue license plate. Two workers in safety gear stand in front of it. A yellow timestamp '2023/6/17' is in the bottom right corner.</p>
370	GX-B1423/20-Y-233946	2023年7月9日	综合判定：合格	 <p>A yellow Weichai dump truck with the number 767 on its side and a blue license plate. Two workers in safety gear stand in front of it. A yellow timestamp '2023/6/17' is in the bottom right corner.</p>

371	GX-B1423/20-Y-233947	2023年7月9日	综合判定：合格	
372	GX-B1423/20-Y-233948	2023年7月9日	综合判定：合格	

373	GX-B1423/20-Y-233949	2023年7月9日	综合判定：合格	
374	GX-B1423/20-Y-233950	2023年7月9日	综合判定：合格	

375	GX-B1423/20-Y-233951	2023年7月9日	综合判定：合格	
376	GX-B1423/20-Y-233952	2023年7月9日	综合判定：合格	