

序号	报告编号	发布日期	结论	影像资料
377	GX-B1423/20-Y-233790	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow TONLY dump truck with license plate 16C. Two workers wearing red hard hats and safety vests are standing in front of the truck. The date 2023/6/13 is visible in the bottom right corner of the image.</p>
378	GX-B1423/20-Y-233791	2023年7月9日	综合判定：合格	 <p>A photograph of a brown dump truck with license plate 63. Two workers wearing safety gear are standing in front of the truck. The date 2023/6/18 is visible in the bottom right corner of the image.</p>

379	GX-B1423/20-Y-233792	2023年7月9日	综合判定：合格	
380	GX-B1423/20-Y-233793	2023年7月9日	综合判定：合格	

381	GX-B1423/20-Y-233794	2023年7月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The truck has the number '162' on its side. A date stamp '2023/6/18' is visible in the bottom right corner of the photo.
382	GX-B1423/20-Y-233796	2023年7月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The truck has the number '168' on its side. A date stamp '2023/6/18' is visible in the bottom right corner of the photo.

383	GX-B1423/20-Y-233797	2023年7月9日	综合判定：合格	
384	GX-B1423/20-Y-233798	2023年7月9日	综合判定：合格	

385	GX-B1423/20-Y-233799	2023年7月9日	综合判定：合格	
386	GX-B1423/20-Y-233800	2023年7月9日	综合判定：合格	

387	GX-B1423/20-Y-233801	2023年7月9日	综合判定：合格	
388	GX-B1423/20-Y-233802	2023年7月9日	综合判定：合格	

389	GX-B1423/20-Y-233803	2023年7月9日	综合判定：合格	
390	GX-B1423/20-Y-233804	2023年7月9日	综合判定：合格	

391	GX-B1423/20-Y-233805	2023年7月9日	综合判定：合格	 <p>A side-view photograph of a yellow TONLY dump truck. A worker in a red hard hat and high-visibility vest stands next to the front wheel. The truck has '同力重工' (Tongli Heavy Industry) written on its side. A yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.</p>
392	GX-B1423/20-Y-233806	2023年7月9日	综合判定：合格	 <p>A front-view photograph of a yellow TONLY dump truck. Two workers, one in a red hard hat and high-visibility vest, and another in a camouflage uniform, stand in front of the truck. The truck has 'TONLY' on the front and '140' on the grille. A yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.</p>

393	GX-B1423/20-Y-233807	2023年7月9日	综合判定：合格	
394	GX-B1423/20-Y-233808	2023年7月9日	综合判定：合格	

395	GX-B1423/20-Y-233809	2023年7月9日	综合判定：合格	
396	GX-B1423/20-Y-233810	2023年7月9日	综合判定：合格	



397	GX-B1423/20-Y-233811	2023年7月9日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. Two workers in safety gear stand in front of the truck. The date '2023/6/20' is visible in the bottom right corner of the image.
398	GX-B1423/20-Y-233812	2023年7月9日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective. Two workers in safety gear stand in front of the truck. The date '2023/6/20' is visible in the bottom right corner of the image.

399	GX-B1423/20-Y-233813	2023年7月9日	综合判定：合格	
400	GX-B1423/20-Y-233814	2023年7月9日	综合判定：合格	

401	GX-B1423/20-Y-233815	2023年7月9日	综合判定：合格	
402	GX-B1423/20-Y-233816	2023年7月9日	综合判定：合格	

403	GX-B1423/20-Y-233817	2023年7月9日	综合判定：合格	
404	GX-B1423/20-Y-233818	2023年7月9日	综合判定：合格	

405	GX-B1423/20-Y-233819	2023年7月9日	综合判定：合格	
406	GX-B1423/20-Y-233820	2023年7月9日	综合判定：合格	

407	GX-B1423/20-Y-233821	2023年7月9日	综合判定：合格	
408	GX-B1423/20-Y-233822	2023年7月9日	综合判定：合格	

409	GX-B1423/20-Y-233823	2023年7月9日	综合判定：合格	 A yellow TONLY truck with the number 119 on the front. Two workers in safety vests are standing in front of it. A yellow date stamp '2023/6/18' is in the bottom right corner.
410	GX-B1423/20-Y-233824	2023年7月9日	综合判定：合格	 A yellow TONLY truck with the number 122 on the front. Two workers in safety vests are standing in front of it. A yellow date stamp '2023/6/18' is in the bottom right corner.

411	GX-B1423/20-Y-233825	2023年7月9日	综合判定：合格	
412	GX-B1423/20-Y-233826	2023年7月9日	综合判定：合格	

413	GX-B1423/20-Y-233829	2023年7月9日	综合判定：合格	 A yellow dump truck is parked on a dirt road. Two workers wearing safety vests and hard hats are standing in front of the truck. The date '2023/6/19' is visible in the bottom right corner of the photo.
414	GX-B1423/20-Y-233830	2023年7月9日	综合判定：合格	 A yellow dump truck is parked on a dirt road. Two workers wearing safety vests and hard hats are standing in front of the truck. The date '2023/6/19' is visible in the bottom right corner of the photo.

415	GX-B1423/20-Y-233831	2023年7月9日	综合判定：合格	
416	GX-B1423/20-Y-233832	2023年7月9日	综合判定：合格	

417	GX-B1423/20-Y-233833	2023年7月9日	综合判定：合格	
418	GX-B1423/20-Y-233834	2023年7月9日	综合判定：合格	

419	GX-B1423/20-Y-233835	2023年7月9日	综合判定：合格	
420	GX-B1423/20-Y-233837	2023年7月9日	综合判定：合格	

421	GX-B1423/20-Y-233838	2023年7月9日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. A white pickup truck is visible in the background. A yellow timestamp '2023/6/19' is in the bottom right corner.</p>
422	GX-B1423/20-Y-233839	2023年7月9日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. A white pickup truck is visible in the background. A yellow timestamp '2023/6/19' is in the bottom right corner.</p>

423	GX-B1423/20-Y-233841	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow TONLY truck with the number 150 on its front. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck is parked on a dirt surface. A white pickup truck is visible in the background. A yellow timestamp '2023/6/20' is in the bottom right corner.</p>
424	GX-B1423/20-Y-233842	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow TONLY truck with the number 10 on its front. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck is parked on a dirt surface. A white pickup truck is visible in the background. A yellow timestamp '2023/6/20' is in the bottom right corner.</p>

425	GX-B1423/20-Y-233843	2023年7月9日	综合判定：合格	
426	GX-B1423/20-Y-233844	2023年7月9日	综合判定：合格	

427	GX-B1423/20-Y-233845	2023年7月9日	综合判定：合格	
428	GX-B1423/20-Y-233846	2023年7月9日	综合判定：合格	

429	GX-B1423/20-Y-233847	2023年7月9日	综合判定：合格	
430	GX-B1423/20-Y-233848	2023年7月9日	综合判定：合格	

431	GX-B1423/20-Y-233849	2023年7月9日	综合判定：合格	
432	GX-B1423/20-Y-233880	2023年7月9日	综合判定：合格	

433	GX-B1423/20-Y-233881	2023年7月9日	综合判定：合格	
434	GX-B1423/20-Y-233882	2023年7月9日	综合判定：合格	

435	GX-B1423/20-Y-233883	2023年7月9日	综合判定：合格	
436	GX-B1423/20-Y-233884	2023年7月9日	综合判定：合格	

437	GX-B1423/20-Y-233885	2023年7月9日	综合判定：合格	
438	GX-B1423/20-Y-233886	2023年7月9日	综合判定：合格	

439	GX-B1423/20-Y-233887	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow TONLY dump truck parked on a dirt surface. Two workers wearing high-visibility safety vests and hard hats are standing in front of the truck. The truck has 'TONLY' written on its side. A yellow timestamp '2023/8/16' is visible in the bottom right corner of the image.</p>
440	GX-B1423/20-Y-233888	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow dump truck with its bed raised, parked on a dirt surface. Two workers wearing high-visibility safety vests and hard hats are standing near the rear of the truck. A yellow timestamp '2023/6/16' is visible in the bottom right corner of the image.</p>

441	GX-B1423/20-Y-233889	2023年7月9日	综合判定：合格	
442	GX-B1423/20-Y-233890	2023年7月9日	综合判定：合格	

443	GX-B1423/20-Y-233891	2023年7月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '207181' on its side. A yellow timestamp '2023/6/16' is visible in the bottom right corner of the photo.
444	GX-B1423/20-Y-233892	2023年7月9日	综合判定：合格	 A yellow dump truck with 'TONLY' written on the front is parked. Two workers in high-visibility vests and hard hats stand in front of it. A yellow timestamp '2023/6/16' is visible in the bottom right corner of the photo.

445	GX-B1423/20-Y-233893	2023年7月9日	综合判定：合格	
446	GX-B1423/20-Y-233894	2023年7月9日	综合判定：合格	

447	GX-B1423/20-Y-233895	2023年7月9日	综合判定：合格	
448	GX-B1423/20-Y-233896	2023年7月9日	综合判定：合格	


449	GX-B1423/20-Y-233897	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow TONLY dump truck parked on a dirt road. Two workers in high-visibility vests and hard hats stand in front of the truck. The date '2023/6/16' is visible in the bottom right corner of the image.</p>
450	GX-B1423/20-Y-233898	2023年7月9日	综合判定：合格	 <p>A photograph of a yellow TONLY dump truck parked on a dirt road. Two workers in high-visibility vests and hard hats stand in front of the truck. The date '2023/6/16' is visible in the bottom right corner of the image.</p>

451	GX-B1531/20-Y-23470~23509	2023年7月10日	本次共检隔绝式压缩氧自救器40个，40个隔绝式压缩氧自救器所检项目合格。	
452	GX-B1531/20-Y-23510~23545	2023年7月10日	本次共检隔绝式压缩氧自救器36个，36个隔绝式压缩氧自救器所检项目合格。	

453	GX-B1531/20-Y-23546~23582	2023年7月10日	本次共检隔绝式压缩氧自救器37个，37个隔绝式压缩氧自救器所检项目合格。	
454	GX-B1531/20-Y-23363~23400	2023年7月10日	本次共检隔绝式压缩氧自救器38个，38个隔绝式压缩氧自救器所检项目合格。	

455	GX-B1531/20-Y-23401~23435	2023年7月10日	本次共检隔绝式压缩氧自救器35个，35个隔绝式压缩氧自救器所检项目合格。	
456	GX-B1531/20-Y-23436~23469	2023年7月10日	本次共检隔绝式压缩氧自救器34个，34个隔绝式压缩氧自救器所检项目合格。	

457	GX-B1354/20-Y-23013	2023年7月10日	电网接地电容电流符合规定。	
458	GX-B1300/20-Y-23008	2023年7月11日	综合判定：合格	


459	GX-B1350/21-Y-23017	2023年7月11日	本次共检接地装置 15处，15处接地装置所 检项目合格。	
460	GX-B1312/20-Y-23376~23378	2023年7月11日	本次共检电力变压器 3台，3台电力变压器所 检项目合格。	


461	GX-B1312/20-Y-23379~23384	2023年7月11日	本次共检电力变压器 6台，6台电力变压器所 检项目合格。	
462	GX-B1312/20-Y-23385	2023年7月11日	所检项目合格。	

463	GX-B1312/20-Y-23386	2023年7月11日	所检项目合格。	
464	GX-B1312/20-Y-23387~23391	2023年7月11日	本次共检电力变压器 5台，5台电力变压器所 检项目合格。	

465	GX-B1312/20-Y-23392	2023年7月11日	所检项目合格。	
466	GX-B1312/20-Y-23393~23394	2023年7月11日	本次共检电力变压器 2台，2台电力变压器所 检项目合格。	

467	GX-B1312/20-Y-23395	2023年7月11日	所检项目合格。	
468	GX-B1321/20-Y-23550~23555	2023年7月11日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	

469	GX-B1321/20-Y-23556~23558	2023年7月11日	本次共检验电力电缆 3条，3条电力电缆所检 项目合格。	
470	GX-B1321/20-Y-23559~23564	2023年7月11日	本次共检验电力电缆 6条，6条电力电缆所检 项目合格。	

471	GX-B1321/20-Y-23565~23573	2023年7月11日	本次共检验电力电缆 9条，9条电力电缆所检 项目合格。	
472	GX-B1321/20-Y-23574~23579	2023年7月11日	本次共检验电力电缆 6条，6条电力电缆所检 项目合格。	

473	GX-B1321/20-Y-23580~23584	2023年7月11日	本次共检验电力电缆5条，5条电力电缆所检项目合格。	
474	GX-B1321/20-Y-23585~23591	2023年7月11日	本次共检验电力电缆7条，7条电力电缆所检项目合格。	

475	GX-B1321/20-Y-23592~23598	2023年7月11日	本次共检验电力电缆7条，7条电力电缆所检项目合格。	
476	GX-B1312/20-Y-23396~23397	2023年7月11日	本次共检电力变压器2台，2台电力变压器所检项目合格。	

477	GX-B1306/21-Y-23118	2023年7月11日	所检项目合格。	
478	GX-B1306/21-Y-23119	2023年7月11日	所检项目合格。	

479	GX-B1306/21-Y-23120	2023年7月11日	所检项目合格。	
480	GX-B1306/21-Y-23121	2023年7月11日	所检项目合格。	

481	GX-B1306/21-Y-23122	2023年7月11日	所检项目合格。	 <p>A photograph showing a worker wearing a red hard hat and a light-colored uniform. The worker is standing next to a blue electrical cabinet, looking into it. A yellow timestamp '2023/6/11' is visible in the bottom right corner of the photo.</p>
482	GX-B1306/21-Y-23123	2023年7月11日	所检项目合格。	 <p>A photograph showing a worker in a red hard hat and light-colored uniform standing in a factory or industrial setting. The worker is looking at a blue electrical cabinet. A red circle with the number '6' is visible on the cabinet. A yellow timestamp '2023/6/11' is visible in the bottom right corner of the photo.</p>

483	GX-B1417/22-Y-23072	2023年7月11日	综合判定：合格	
484	GX-B1417/22-Y-23073	2023年7月11日	综合判定：合格	

485	GX-B1417/22-Y-23074	2023年7月11日	综合判定：合格	
486	GX-B1417/22-Y-23075	2023年7月11日	综合判定：合格	

487	GX-B1417/22-Y-23076	2023年7月11日	综合判定：合格	
-----	---------------------	------------	---------	---