

序号	报告编号	发布日期	结论	影像资料
488	GX-B1559/22-Y-23013	2023年7月11日	所检项目合格	 A photograph showing a worker in a red safety helmet and blue work clothes operating a piece of machinery. The worker is seated and looking towards the right. The machinery has a metal railing and a control lever. A yellow timestamp '2023/6/8' is visible in the bottom right corner of the image.

489	GX-B1559/22-Y-23014	2023年7月11日	所检项目合格	 <p>A photograph showing two workers in safety gear (hard hats and work clothes) standing next to a large yellow vehicle, likely a forklift or loader. The worker on the left is wearing a yellow hard hat and dark clothing, while the worker on the right is wearing a red hard hat and light-colored work clothes. The vehicle is yellow and has large tires. The date '2023/6/9' is visible in the bottom right corner of the photo.</p>
490	GX-B1559/22-Y-23015	2023年7月11日	所检项目合格	 <p>A photograph showing a worker in a red hard hat and light-colored work clothes sitting on a vehicle, possibly a forklift or loader, and inspecting a component. The worker is wearing safety glasses and is holding a tool or part. The date '2023/6/9' is visible in the bottom right corner of the photo.</p>

491	GX-B1559/22-Y-23016	2023年7月11日	所检项目合格	
492	GX-B1495/20-Y-231606~231613	2023年7月11日	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	

493	GX-B1321/20-Y-23599~23600	2023年7月12日	本次共检验电力电缆2条，2条电力电缆所检项目合格。	
494	GX-B1308/21-Y-23016	2023年7月11日	所检项目合格。	

495	GX-B1499/21-Y-23088	2023年7月11日	所检项目合格。	
496	GX-B1499/21-Y-23089	2023年7月11日	所检项目合格。	

497	GX-B1499/21-Y-23090	2023年7月11日	所检项目合格。	
498	GX-B1499/21-Y-23091	2023年7月11日	所检项目合格。	

499	GX-B1499/21-Y-23092	2023年7月11日	所检项目合格。	
500	GX-B1499/21-Y-23093	2023年7月11日	所检项目合格。	

501	GX-B1499/21-Y-23094	2023年7月11日	所检项目合格。	
502	GX-B1499/21-Y-23095	2023年7月11日	所检项目合格。	

503	GX-B1499/21-Y-23096	2023年7月11日	所检项目合格。	
504	GX-B1499/21-Y-23097	2023年7月11日	所检项目合格。	

505	GX-B1499/21-Y-23098	2023年7月11日	所检项目合格。	
506	GX-B1499/21-Y-23099	2023年7月11日	所检项目合格。	

507	GX-B1423/20-Y-233795	2023年7月11日	综合判定：合格	
508	GX-B1423/20-Y-233827	2023年7月11日	综合判定：合格	

509	GX-B1423/20-Y-233828	2023年7月11日	综合判定：合格	
510	GX-B1423/20-Y-233836	2023年7月11日	综合判定：合格	

511	GX-B1423/20-Y-233840	2023年7月11日	综合判定：合格	
512	GX-B1404/20-Y-23019	2023年7月12日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

513	GX-B1404/20-Y-23020	2023年7月12日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	
514	GX-B1354/20-Y-23014	2023年7月12日	电网接地电容电流符合规定。	

515	GX-B1404/20-Y-23021	2023年7月12日	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	
516	GX-B1404/20-Y-23022	2023年7月12日	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	

517	GX-B1423/20-Y-233522	2023年7月12日	综合判定：合格	
518	GX-B1423/20-Y-233523	2023年7月12日	综合判定：合格	

519	GX-B1423/20-Y-233524	2023年7月12日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of the truck. Two metal toolboxes are on the ground in the foreground. A yellow date stamp '2023/7/8' is in the bottom right corner.
520	GX-B1423/20-Y-233525	2023年7月12日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of the truck. Two metal toolboxes are on the ground in the foreground. A yellow date stamp '2023/7/8' is in the bottom right corner.

521	GX-B1423/20-Y-233526	2023年7月12日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear are standing near the truck. In the foreground, there are pieces of equipment, including a laptop and a control panel. The date '2023/7/8' is visible in the bottom right corner of the photo.</p>
522	GX-B1423/20-Y-233527	2023年7月12日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear are standing near the truck. In the foreground, there are pieces of equipment, including a laptop and a control panel. The date '2023/7/8' is visible in the bottom right corner of the photo.</p>

523	GX-B1423/20-Y-233528	2023年7月12日	综合判定：合格	
524	GX-B1423/20-Y-233529	2023年7月12日	综合判定：合格	

525	GX-B1423/20-Y-233530	2023年7月12日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. A small cart with equipment is on the ground. A yellow timestamp '2023/7/8' is in the bottom right corner.</p>
526	GX-B1423/20-Y-233531	2023年7月12日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. A yellow timestamp '2023/7/8' is in the bottom right corner.</p>

527	GX-B1423/20-Y-233532	2023年7月12日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. Inspection equipment, including a laptop and a control panel, is visible on the ground. A yellow timestamp '2023/7/8' is in the bottom right corner.
528	GX-B1423/20-Y-233533	2023年7月12日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. Inspection equipment, including a laptop and a control panel, is visible on the ground. A yellow timestamp '2023/7/8' is in the bottom right corner.

529	GX-B1423/20-Y-233534	2023年7月12日	综合判定：合格	
530	GX-B1423/20-Y-233535	2023年7月12日	综合判定：合格	

531	GX-B1423/20-Y-233536	2023年7月12日	综合判定：合格	
532	GX-B1423/20-Y-233537	2023年7月12日	综合判定：合格	

533	GX-B1423/20-Y-233538	2023年7月12日	综合判定：合格	
534	GX-B1423/20-Y-233539	2023年7月12日	综合判定：合格	

535	GX-B1423/20-Y-233540	2023年7月12日	综合判定：合格	
536	GX-B1423/20-Y-233541	2023年7月12日	综合判定：合格	

537	GX-B1423/20-Y-233542	2023年7月12日	综合判定：合格	
538	GX-B1423/20-Y-233543	2023年7月12日	综合判定：合格	

539	GX-B1423/20-Y-233544	2023年7月12日	综合判定：合格	
540	GX-B1423/20-Y-233545	2023年7月12日	综合判定：合格	

541	GX-B1423/20-Y-233546	2023年7月12日	综合判定：合格	
542	GX-B1423/20-Y-233547	2023年7月12日	综合判定：合格	

543	GX-B1423/20-Y-233548	2023年7月12日	综合判定：合格	
544	GX-B1423/20-Y-233549	2023年7月12日	综合判定：合格	

545	GX-B1423/20-Y-233550	2023年7月12日	综合判定：合格	
546	GX-B1423/20-Y-233551	2023年7月12日	综合判定：合格	

547	GX-B1427/21-Y-23109	2023年7月12日	符合标准要求	
548	GX-B1427/21-Y-23110	2023年7月12日	符合标准要求	

549	GX-B1416/22-Y-23076	2023年7月13日	综合判定：合格	 <p>A photograph showing a worker in a dark uniform and a black helmet with a headlamp. The worker is holding a handheld electronic device and appears to be operating or inspecting a piece of industrial machinery. The background shows a complex industrial environment with metal structures and pipes. A yellow timestamp '2023/6/30' is visible in the bottom right corner of the image.</p>
550	GX-B1416/22-Y-23077	2023年7月13日	综合判定：合格	 <p>A photograph showing two workers in a control room or office setting. Both are wearing dark uniforms and helmets. One worker is holding a document or a tablet, and the other is looking at a computer monitor. The room has large windows and various pieces of equipment. A yellow timestamp '2023/6/29' is visible in the bottom right corner of the image.</p>

551	GX-B1416/22-Y-23078	2023年7月13日	综合判定：合格	
552	GX-B1416/22-Y-23079	2023年7月13日	综合判定：合格	

553	GX-B1515/22-Y-23009	2023年7月12日	所检项目合格。	
554	GX-B1310/21-Y-23116	2023年7月12日	符合标准要求。	

555	GX-B1310/21-Y-23117	2023年7月12日	符合标准要求。	
556	GX-B1428/21-Y-23116	2023年7月12日	无缺陷迹痕显示。	

557	GX-B1428/21-Y-23117	2023年7月12日	无缺陷迹痕显示。	
558	GX-B1310/21-Y-23118	2023年7月12日	符合标准要求。	

559	GX-B1310/21-Y-23119	2023年7月12日	符合标准要求。	
-----	---------------------	------------	---------	---