

序号	报告编号	发布日期	结论	影像资料
118	GX-B1417/22-4-23081	2023. 7. 13	综合判定：合格。	
119	GX-B1417/22-4-23078	2023. 7. 13	综合判定：合格。	
120	GX-B1417/22-4-23073	2023. 7. 13	综合判定：合格。	

121	GX-B1417/22-4-23074	2023. 7. 13	综合判定：合格。	
122	GX-B1417/22-4-23075	2023. 7. 13	综合判定：合格。	
123	GX-B1417/22-4-23076	2023. 7. 13	综合判定：合格。	

124	GX-B1417/22-4-23077	2023. 7. 13	综合判定：合格。	
125	GX-B1417/22-4-23080	2023. 7. 13	综合判定：合格。	
126	GX-B1417/22-4-23079	2023. 7. 13	综合判定：合格。	

127	GX-B1300/20-4-23009	2023. 7. 13	综合判定：合格	
128	GX-B1328/20-4-23125	2023. 7. 13	本次共检绝缘手套 250只，250只所检项目 合格。	
129	GX-B1328/20-4-23126	2023. 7. 13	本次共检绝缘鞋160只， 160只所检项目合格。	

130	GX-B1328/20-4-23127	2023. 7. 13	本次共检绝缘手套 232只，232只所检项目 合格。	
131	GX-B1328/20-4-23128	2023. 7. 13	本次共检绝缘鞋150只， 150只所检项目合格。	
132	GX-B1328/20-4-23129	2023. 7. 13	本次共检绝缘鞋112只， 112只所检项目合格。	

133	GX-B1307/20-4-23013	2023. 7. 13	综合判定：合格。	
134	GX-B1306/21-4-23047	2023. 7. 13	所检项目合格。	
135	GX-B1306/21-4-23048	2023. 7. 13	所检项目合格。	

136	GX-B1306/21-4-23049	2023. 7. 13	所检项目合格。	 <p>2023/7/6</p>
137	GX-B1306/21-4-23050	2023. 7. 13	所检项目合格。	 <p>2023/7/6</p>
138	GX-B1423/20-4-23040	2023. 7. 13	综合判定：合格	 <p>2023. 6. 18</p>

139	GX-B1423/20-4-23041	2023. 7. 13	综合判定：合格	
140	GX-B1423/20-4-23042	2023. 7. 13	综合判定：合格	
141	GX-B1423/20-4-23043	2023. 7. 13	综合判定：合格	

142	GX-B1423/20-4-23044	2023. 7. 13	综合判定：合格	 A photograph showing two workers in grey uniforms and red hard hats standing in front of a yellow truck. The truck has '陕汽' (Shaanxi) written on its side. A red timestamp '2023. 6. 18' is visible in the bottom right corner of the image.
143	GX-B1423/20-4-23045	2023. 7. 13	综合判定：合格	 A photograph showing three workers in grey uniforms and red hard hats standing in front of a yellow truck. The truck has '陕汽' (Shaanxi) written on its side. A red timestamp '2023. 6. 18' is visible in the bottom right corner of the image.
144	GX-B1423/20-4-23046	2023. 7. 13	综合判定：合格	 A photograph showing a worker in a grey uniform and red hard hat kneeling on the ground next to a yellow truck. The worker appears to be inspecting or working on something on the ground. A red timestamp '2023. 6. 18' is visible in the bottom right corner of the image.

145	GX-B1423/20-4-23047	2023. 7. 13	综合判定：合格	 A yellow dump truck is parked on a dirt surface. A worker in a grey uniform and red hard hat stands near the front of the truck. A date stamp '2023. 6. 18' is visible in the bottom right corner of the photo.
146	GX-B1423/20-4-23048	2023. 7. 13	综合判定：合格	 Three workers in grey uniforms and red hard hats stand in front of a yellow truck. The truck has '陕汽重卡' (Shaanxi Heavy Duty Truck) written on its side. A date stamp '2023. 6. 18' is visible in the bottom right corner of the photo.
147	GX-B1423/20-4-23049	2023. 7. 13	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in grey uniforms and red hard hats are standing near the truck. A date stamp '2023. 6. 18' is visible in the bottom right corner of the photo.

148	GX-B1423/20-4-23050	2023. 7. 13	综合判定：合格	
149	GX-B1303/21-4-23004	2023. 7. 13	所检项目合格。	
150	GX-B1559/22-4-23021	2023. 7. 14	所检项目合格。	

151	GX-B1328/20-4-23144	2023. 7. 19	本次共检绝缘手套 10只，10只所检项目合格。	
152	GX-B1328/20-4-23145	2023. 7. 19	本次共检绝缘鞋10只， 10只所检项目合格。	
153	GX-B1328/20-4-23146	2023. 7. 19	所检项目合格。	

154	GX-B1310/21-4-23086	2023. 7. 20	符合标准要求	
155	GX-B1310/21-4-23087	2023. 7. 20	符合标准要求	
156	GX-B1310/21-4-23089	2023. 7. 20	符合标准要求	

157	GX-B1310/21-4-23090	2023. 7. 20	符合标准要求	
158	GX-B1310/21-4-23091	2023. 7. 20	符合标准要求	