

序号	报告编号	发布日期	结论	影像资料
560	GX-B1417/22-Y-23077	2023年7月13日	综合判定：合格	

561	GX-B1417/22-Y-23078	2023年7月13日	综合判定：合格	 <p>A photograph showing a worker wearing a red hard hat and safety glasses, operating a piece of heavy machinery. The worker is seated and looking towards the camera. The machinery is white and has a steering wheel. A yellow timestamp '2023/6/9' is visible in the bottom right corner of the photo.</p>
562	GX-B1417/22-Y-23079	2023年7月13日	综合判定：合格	 <p>A photograph showing two workers standing next to a large piece of heavy machinery. One worker is wearing a red hard hat and the other is wearing a yellow hard hat. The machinery is white and has a red circle with the number '3' on it. A yellow timestamp '2023/6/9' is visible in the bottom right corner of the photo.</p>

563	GX-B1417/22-Y-23080	2023年7月13日	综合判定：合格	 <p>A photograph showing a worker wearing a red hard hat and a light blue uniform, sitting in the driver's seat of a vehicle. The worker is looking down at a device or control panel. The date '2023/6/6' is visible in the bottom right corner of the image.</p>
564	GX-B1417/22-Y-23081	2023年7月13日	综合判定：合格	 <p>A photograph of a white K5 truck with a crane attachment, parked in an industrial area. Two workers, one in a red hard hat and one in a yellow hard hat, are standing next to the truck. The date '2023/6/6' is visible in the bottom right corner of the image.</p>

565	GX-B1417/22-Y-23082	2023年7月13日	综合判定：合格	
566	GX-B1417/22-Y-23083	2023年7月13日	综合判定：合格	

567	GX-B1417/22-Y-23084	2023年7月13日	综合判定：合格	
568	GX-B1417/22-Y-23085	2023年7月13日	综合判定：合格	

569	GX-B1417/22-Y-23086	2023年7月13日	综合判定：合格	
570	GX-B1417/22-Y-23087	2023年7月13日	综合判定：合格	

571	GX-B1417/22-Y-23088	2023年7月13日	综合判定：合格	
572	GX-B1417/22-Y-23089	2023年7月13日	综合判定：合格	

573	GX-B1417/22-Y-23090	2023年7月13日	综合判定：合格	 <p>A photograph showing a worker wearing a red hard hat and safety glasses operating a forklift. The worker is looking at a control panel with a monitor. The date stamp in the bottom right corner of the photo is 2023/6/9.</p>
574	GX-B1417/22-Y-23091	2023年7月13日	综合判定：合格	 <p>A photograph of a white forklift with a red '29 核定 10T' label on its side. Two workers, one in a red hard hat and one in a yellow hard hat, are standing next to the forklift. The date stamp in the bottom right corner of the photo is 2023/6/10.</p>

575	GX-B1417/22-Y-23092	2023年7月13日	综合判定：合格	 A photograph showing two workers in safety gear (hard hats and work clothes) standing next to a white forklift. The forklift has the number '31' on its side. The background shows a large industrial building under a clear blue sky. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the photo.
576	GX-B1306/21-Y-23124	2023年7月14日	所检项目合格。	 A photograph of a worker in a red hard hat and light blue work uniform inspecting a piece of machinery. The worker is holding a clipboard and a pen. A blue license plate with the number 'X-5CC01674' is visible on the machinery. A yellow timestamp '2023/7/5' is visible in the bottom right corner of the photo.

577	GX-B1423/20-Y-233953	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-391 is parked inside a large industrial building. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.
578	GX-B1423/20-Y-233954	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-387 is parked outdoors under a clear blue sky. A single worker in safety gear stands in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.
579	GX-B1423/20-Y-233955	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-373 is parked outdoors. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.

580	GX-B1423/20-Y-233956	2023年7月17日	综合判定：合格	 A yellow MTB truck with the identification number K-305 is shown from a side-rear perspective. Two workers in safety gear are standing in front of the truck. A red laser line is visible across the truck's body. A yellow timestamp '2023/6/25' is in the bottom right corner.
581	GX-B1423/20-Y-233957	2023年7月17日	综合判定：合格	 A yellow MTB truck with the identification number K-307 is shown from a side-rear perspective. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/25' is in the bottom right corner.
582	GX-B1423/20-Y-233958	2023年7月17日	综合判定：合格	 A yellow MTB truck with the identification number K-302 is shown from a side-rear perspective. One worker in safety gear is standing in front of the truck. A yellow timestamp '2023/6/25' is in the bottom right corner.

583	GX-B1423/20-Y-233959	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-308 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.
584	GX-B1423/20-Y-233960	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-308 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.
585	GX-B1423/20-Y-233961	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-399 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.

586	GX-B1423/20-Y-233962	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-370 is shown from a side-rear perspective. The truck's bed is raised. Two workers in high-visibility vests and hard hats are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.
587	GX-B1423/20-Y-233963	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-398 is shown from a side-rear perspective. The truck's bed is raised. Two workers in high-visibility vests and hard hats are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.
588	GX-B1423/20-Y-233964	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-378 is shown from a side-rear perspective. The truck's bed is raised. Two workers in high-visibility vests and hard hats are standing in front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the photo.

589	GX-B1423/20-Y-233965	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-380 is shown from a side-rear perspective. The truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats are standing near the front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the image.
590	GX-B1423/20-Y-233966	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-392 is shown from a side-rear perspective. The truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats are standing near the front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the image.
591	GX-B1423/20-Y-233967	2023年7月17日	综合判定：合格	 A yellow dump truck with the identification number K-393 is shown from a side-rear perspective. The truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats are standing near the front of the truck. A yellow timestamp '2023/6/25' is visible in the bottom right corner of the image.

592	GX-B1423/20-Y-233968	2023年7月17日	综合判定：合格	 A yellow K-301 dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date stamp '2023/6/23' is visible in the bottom right corner of the photo.
593	GX-B1423/20-Y-233969	2023年7月17日	综合判定：合格	 A yellow K-303 dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date stamp '2023/6/25' is visible in the bottom right corner of the photo.
594	GX-B1423/20-Y-233970	2023年7月17日	综合判定：合格	 A yellow K-304 dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date stamp '2023/6/25' is visible in the bottom right corner of the photo.

595	GX-B1423/20-Y-233971	2023年7月17日	综合判定：合格	 A yellow MT86H dump truck with license plate K-310. Two workers in safety gear stand in front of it. A yellow timestamp '2023/6/25' is in the bottom right corner.
596	GX-B1423/20-Y-233972	2023年7月17日	综合判定：合格	 A yellow MT86H dump truck with license plate K-389. Two workers in safety gear stand in front of it. A yellow timestamp '2023/6/25' is in the bottom right corner.
597	GX-B1423/20-Y-233973	2023年7月17日	综合判定：合格	 A yellow MT86H dump truck with license plate K-311. Two workers in safety gear stand in front of it. A yellow timestamp '2023/6/25' is in the bottom right corner.

598	GX-B1423/20-Y-233974	2023年7月17日	综合判定：合格	
599	GX-B1423/20-Y-233975	2023年7月17日	综合判定：合格	
600	GX-B1423/20-Y-233976	2023年7月17日	综合判定：合格	

601	GX-B1423/20-Y-233977	2023年7月17日	综合判定：合格	 A red dump truck with its bed tilted upwards. Two workers in safety gear stand near the front. A yellow date stamp '2023/6/22' is in the bottom right corner.
602	GX-B1423/20-Y-233978	2023年7月17日	综合判定：合格	 A red dump truck with its bed raised. Two workers in safety gear stand in front. The license plate area shows '桂K-188'. A yellow date stamp '2023/6/22' is in the bottom right corner.
603	GX-B1423/20-Y-233979	2023年7月17日	综合判定：合格	 A red dump truck with its bed raised. Two workers in safety gear stand in front. The license plate area shows '桂K-199'. A yellow date stamp '2023/6/22' is in the bottom right corner.

604	GX-B1423/20-Y-233980	2023年7月17日	综合判定：合格	 A photograph of a red truck with two workers in orange safety vests standing in front of it. The truck is parked on a dirt surface. A yellow timestamp '2023/6/22' is visible in the bottom right corner of the image.
605	GX-B1423/20-Y-233981	2023年7月17日	综合判定：合格	 A photograph of a red truck with two workers in orange safety vests standing in front of it. The truck is parked on a dirt surface. A yellow timestamp '2023/6/22' is visible in the bottom right corner of the image.
606	GX-B1423/20-Y-233982	2023年7月17日	综合判定：合格	 A photograph of a red truck with two workers in orange safety vests standing in front of it. The truck is parked on a dirt surface. A yellow timestamp '2023/6/22' is visible in the bottom right corner of the image.

607	GX-B1423/20-Y-233983	2023年7月17日	综合判定：合格	
608	GX-B1423/20-Y-233984	2023年7月17日	综合判定：合格	
609	GX-B1423/20-Y-233985	2023年7月17日	综合判定：合格	

610	GX-B1423/20-Y-233986	2023年7月17日	综合判定：合格	 <p>A yellow MTB50 dump truck with the identification number K169 is shown at a construction site. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.</p>
611	GX-B1423/20-Y-233987	2023年7月17日	综合判定：合格	 <p>A yellow MTB50 dump truck with the identification number K178 is shown at a construction site. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.</p>
612	GX-B1423/20-Y-233988	2023年7月17日	综合判定：合格	 <p>A yellow MTB50 dump truck with the identification number K182 is shown at a construction site. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.</p>

613	GX-B1423/20-Y-233989	2023年7月17日	综合判定：合格	 A yellow MT850 dump truck with license plate K-181 is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/6/23 is visible in the bottom right corner of the photo.
614	GX-B1423/20-Y-233990	2023年7月17日	综合判定：合格	 A yellow MT850 dump truck with license plate K-176 is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/6/23 is visible in the bottom right corner of the photo.
615	GX-B1423/20-Y-233991	2023年7月17日	综合判定：合格	 A yellow MT850 dump truck with license plate K-177 is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/6/23 is visible in the bottom right corner of the photo.

616	GX-B1423/20-Y-233992	2023年7月17日	综合判定：合格	 A yellow MT860 dump truck is shown from a side-rear perspective. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's body is marked with '180' and 'MT860'. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.
617	GX-B1423/20-Y-233993	2023年7月17日	综合判定：合格	 A yellow MT860 dump truck is shown from a side-front perspective. A single worker in a high-visibility vest and hard hat stands in front of the truck. The truck's body is marked with 'MT860'. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.
618	GX-B1423/20-Y-233994	2023年7月17日	综合判定：合格	 A yellow MT860 dump truck is shown from a side-rear perspective, parked in front of a building. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's body is marked with '172' and 'MT860'. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.

619	GX-B1423/20-Y-233995	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate K-291 is shown from a side-rear perspective. Two workers in safety gear are standing in front of the truck. A date stamp '2023/6/26' is visible in the bottom right corner of the image.
620	GX-B1423/20-Y-233996	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate K-299 is shown from a front-three-quarter view. Two workers in safety gear are standing in front of the truck. A date stamp '2023/6/26' is visible in the bottom right corner of the image.
621	GX-B1423/20-Y-233997	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate K-299 is shown from a front-three-quarter view. Two workers in safety gear are standing in front of the truck. A date stamp '2023/6/26' is visible in the bottom right corner of the image.

622	GX-B1423/20-Y-233998	2023年7月17日	综合判定：合格	 A yellow dump truck is parked in an outdoor setting. Two workers in high-visibility vests and hard hats are standing in front of the truck. A date stamp '2023/6/28' is visible in the bottom right corner of the image.
623	GX-B1423/20-Y-233999	2023年7月17日	综合判定：合格	 A yellow dump truck is parked in an outdoor setting. Two workers in high-visibility vests and hard hats are standing in front of the truck. A date stamp '2023/6/28' is visible in the bottom right corner of the image.
624	GX-B1423/20-Y-234000	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate '桂K-287' is parked in an outdoor setting. Several workers in high-visibility vests and hard hats are standing in front of the truck. A date stamp '2023/6/28' is visible in the bottom right corner of the image.

625	GX-B1423/20-Y-234001	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate K-276 is parked on a dirt road. Two workers in safety vests and hard hats are standing in front of it. The date 2023/6/26 is visible in the bottom right corner of the photo.
626	GX-B1423/20-Y-234002	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate K-276 is parked on a dirt road. Two workers in safety vests and hard hats are standing in front of it. The date 2023/6/26 is visible in the bottom right corner of the photo.
627	GX-B1423/20-Y-234003	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate K-276 is parked on a dirt road. Two workers in safety vests and hard hats are standing in front of it. The date 2023/6/26 is visible in the bottom right corner of the photo.

628	GX-B1423/20-Y-234004	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-269 is parked on a dirt surface. Two workers in red safety gear and hard hats are standing in front of the truck. A yellow timestamp '2023/8/26' is visible in the bottom right corner of the photo.
629	GX-B1423/20-Y-234005	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-270 is parked. Two workers in red safety gear and hard hats are standing in front of it. A yellow timestamp '2023/8/26' is visible in the bottom right corner of the photo.
630	GX-B1423/20-Y-234006	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-271 is parked. Two workers in red safety gear and hard hats are standing in front of it. A yellow timestamp '2023/8/26' is visible in the bottom right corner of the photo.

631	GX-B1423/20-Y-234007	2023年7月17日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing safety vests and hard hats are standing in front of the truck. The truck has 'TONLY' and '31814' visible on its side. A date stamp '2023/6/26' is in the bottom right corner.
632	GX-B1423/20-Y-234008	2023年7月17日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing safety vests and hard hats are standing in front of the truck. A date stamp '2023/6/26' is in the bottom right corner.
633	GX-B1423/20-Y-234009	2023年7月17日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing safety vests and hard hats are standing in front of the truck. A date stamp '2023/6/26' is in the bottom right corner.

634	GX-B1423/20-Y-234010	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-229 is shown from a front-quarter view. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.
635	GX-B1423/20-Y-234011	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-230 is shown from a side view. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.
636	GX-B1423/20-Y-234012	2023年7月17日	综合判定：合格	 A yellow dump truck with the license plate K-228 is shown from a side view. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.

637	GX-B1423/20-Y-234013	2023年7月17日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. Two workers in high-visibility vests and hard hats are standing near the rear of the truck. A date stamp '2023/6/27' is visible in the bottom right corner of the image.
638	GX-B1423/20-Y-234014	2023年7月17日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective. Two workers in high-visibility vests and hard hats are standing near the front of the truck. A date stamp '2023/6/27' is visible in the bottom right corner of the image.
639	GX-B1423/20-Y-234015	2023年7月17日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective. Two workers in high-visibility vests and hard hats are standing near the front of the truck. A date stamp '2023/6/27' is visible in the bottom right corner of the image.

640	GX-B1423/20-Y-234016	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate HK-753 is parked in a lot. Two workers in safety vests and hard hats stand in front of it. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.
641	GX-B1423/20-Y-234017	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate HK-261 is parked in a lot. Two workers in safety vests and hard hats stand in front of it. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.
642	GX-B1423/20-Y-234018	2023年7月17日	综合判定：合格	 A yellow dump truck with license plate HK-256 is parked in a lot. Two workers in safety vests and hard hats stand in front of it. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.

643	GX-B1423/20-Y-234019	2023年7月17日	综合判定：合格	 A yellow TONLY dump truck is parked in an outdoor setting. Two workers wearing safety vests and hard hats are standing in front of the truck. A date stamp '2023/6/27' is visible in the bottom right corner of the image.
644	GX-B1423/20-Y-234020	2023年7月17日	综合判定：合格	 A yellow TONLY dump truck is parked in an outdoor setting. Two workers wearing safety vests and hard hats are standing in front of the truck. A date stamp '2023/6/27' is visible in the bottom right corner of the image.
645	GX-B1423/20-Y-234021	2023年7月17日	综合判定：合格	 A yellow TONLY dump truck is parked in an outdoor setting. Two workers wearing safety vests and hard hats are standing in front of the truck. A date stamp '2023/6/27' is visible in the bottom right corner of the image.

646	GX-B1423/20-Y-234022	2023年7月17日	综合判定：合格	 A yellow TONLY dump truck with license plate K-286 is shown in a desert environment. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.
647	GX-B1423/20-Y-234023	2023年7月17日	综合判定：合格	 A yellow TONLY dump truck with license plate K-477 is shown in a desert environment. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.
648	GX-B1423/20-Y-234024	2023年7月17日	综合判定：合格	 A yellow TONLY dump truck with license plate K-722 is shown in a desert environment. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/27' is visible in the bottom right corner of the photo.

649	GX-B1423/20-Y-234025	2023年7月17日	综合判定：合格	
650	GX-B1423/20-Y-234026	2023年7月17日	综合判定：合格	
651	GX-B1423/20-Y-234027	2023年7月17日	综合判定：合格	

652	GX-B1423/20-Y-234028	2023年7月17日	综合判定：合格	
653	GX-B1423/20-Y-234029	2023年7月17日	综合判定：合格	
654	GX-B1423/20-Y-234030	2023年7月17日	综合判定：合格	

655	GX-B1423/20-Y-234031	2023年7月17日	综合判定：合格	
656	GX-B1423/20-Y-234032	2023年7月17日	综合判定：合格	
657	GX-B1423/20-Y-234033	2023年7月17日	综合判定：合格	

658	GX-B1423/20-Y-234034	2023年7月17日	综合判定：合格	
659	GX-B1423/20-Y-234035	2023年7月17日	综合判定：合格	
660	GX-B1423/20-Y-234036	2023年7月17日	综合判定：合格	

661	GX-B1423/20-Y-234037	2023年7月17日	综合判定：合格	
662	GX-B1522/20-Y-23122	2023年7月17日	所检项目合格。	
663	GX-B1312/20-Y-23398~23401	2023年7月18日	本次共检电力变压器4台，4台电力变压器所检项目合格。	

664	GX-B1559/22-Y-23017	2023年7月19日	所检项目合格。	
665	GX-B1531/20-Y-23583~23626	2023年7月19日	本次共检隔绝式压缩氧自救器44个，44个隔绝式压缩氧自救器所检项目合格。	
666	GX-B1531/20-Y-23627~23670	2023年7月19日	本次共检隔绝式压缩氧自救器44个，44个隔绝式压缩氧自救器所检项目合格。	

667	GX-B1531/20-Y-23671~23714	2023年7月19日	本次共检隔绝式压缩氧自救器44个，44个隔绝式压缩氧自救器所检项目合格。	
668	GX-B1531/20-Y-23715~23758	2023年7月19日	本次共检隔绝式压缩氧自救器44个，44个隔绝式压缩氧自救器所检项目合格。	
669	GX-B1531/20-Y-23759~23802	2023年7月19日	本次共检隔绝式压缩氧自救器44个，44个隔绝式压缩氧自救器所检项目合格。	

670	GX-B1531/20-Y-23803~23846	2023年7月19日	本次共检隔绝式压缩氧自救器44个，44个隔绝式压缩氧自救器所检项目合格。	
671	GX-B1531/20-Y-23847~23889	2023年7月19日	本次共检隔绝式压缩氧自救器43个，43个隔绝式压缩氧自救器所检项目合格。	
672	GX-B1531/20-Y-23890~23932	2023年7月19日	本次共检隔绝式压缩氧自救器43个，43个隔绝式压缩氧自救器所检项目合格。	

673	GX-B1557/22-Y-23020	2023. 7. 20	所检项目合格。	
674	GX-B1557/22-Y-23021	2023. 7. 20	所检项目合格。	
675	GX-B1499/21-Y-23100	2023年7月20日	实测流量为183.7m ³ /h	

676	GX-B1499/21-Y-23101	2023年7月20日	实测流量为175.3m ³ /h	
677	GX-B1499/21-Y-23102	2023年7月20日	实测流量为171.8m ³ /h	
678	GX-B1499/21-Y-23103	2023年7月20日	实测流量为188.5m ³ /h	

679	GX-B1499/21-Y-23104	2023年7月20日	实测流量为193.7m ³ /h	 <p>2023/7/9</p>
680	GX-B1499/21-Y-23105	2023年7月20日	实测流量为183.2m ³ /h	 <p>2023/7/9</p>
681	GX-B1499/21-Y-23106	2023年7月20日	实测流量为175.8m ³ /h	 <p>2023/7/9</p>

682	GX-B1415/22-Y-23009	2023年7月21日	综合判定：合格	
683	GX-B1517/20-Y-23021	2023年7月21日	综合判定：合格	
684	GX-B1517/20-Y-23022	2023年7月21日	综合判定：合格	