

序号	报告编号	发布日期	结论	影像资料
685	GX-B1300/20-Y-23009	2023年7月21日	综合判定：合格	
686	GX-B1300/20-Y-23010	2023年7月21日	综合判定：合格	

687	GX-B1423/20-Y-234145	2023年7月24日	综合判定：合格	
688	GX-B1423/20-Y-234146	2023年7月24日	综合判定：合格	

689	GX-B1423/20-Y-234147	2023年7月24日	综合判定：合格	
690	GX-B1423/20-Y-234148	2023年7月24日	综合判定：合格	

691	GX-B1423/20-Y-234149	2023年7月24日	综合判定：合格	 A photograph of a yellow ABG dump truck parked in an outdoor industrial area. A person wearing a white uniform and a red hard hat stands in the foreground to the left of the truck. The truck's bed is raised. The date '2023/7/3' is visible in the bottom right corner of the image.
692	GX-B1423/20-Y-234150	2023年7月24日	综合判定：合格	 A photograph of a yellow ABG dump truck parked in an outdoor industrial area. Two people, one in a white uniform and red hard hat, and another in a purple shirt, stand in the foreground in front of the truck. The truck's bed is raised. The date '2023/7/3' is visible in the bottom right corner of the image.

693	GX-B1423/20-Y-234151	2023年7月24日	综合判定：合格	
694	GX-B1423/20-Y-234152	2023年7月24日	综合判定：合格	

695	GX-B1423/20-Y-234153	2023年7月24日	综合判定：合格	
696	GX-B1423/20-Y-234154	2023年7月24日	综合判定：合格	

697	GX-B1423/20-Y-234155	2023年7月24日	综合判定：合格	
698	GX-B1423/20-Y-234156	2023年7月24日	综合判定：合格	

699	GX-B1423/20-Y-234157	2023年7月24日	综合判定：合格	
700	GX-B1423/20-Y-234158	2023年7月24日	综合判定：合格	

701	GX-B1423/20-Y-234159	2023年7月24日	综合判定：合格	
702	GX-B1423/20-Y-234160	2023年7月24日	综合判定：合格	

703	GX-B1423/20-Y-234161	2023年7月24日	综合判定：合格	
704	GX-B1423/20-Y-234162	2023年7月24日	综合判定：合格	

705	GX-B1423/20-Y-234163	2023年7月24日	综合判定：合格	
706	GX-B1423/20-Y-234164	2023年7月24日	综合判定：合格	

707	GX-B1423/20-Y-234165	2023年7月24日	综合判定：合格	
708	GX-B1423/20-Y-234166	2023年7月24日	综合判定：合格	

709	GX-B1423/20-Y-234167	2023年7月24日	综合判定：合格	
710	GX-B1423/20-Y-234168	2023年7月24日	综合判定：合格	

711	GX-B1423/20-Y-234169	2023年7月24日	综合判定：合格	
712	GX-B1423/20-Y-234170	2023年7月24日	综合判定：合格	

713	GX-B1423/20-Y-234171	2023年7月24日	综合判定：合格	
714	GX-B1423/20-Y-234172	2023年7月24日	综合判定：合格	

715	GX-B1423/20-Y-234173	2023年7月24日	综合判定：合格	
716	GX-B1423/20-Y-234174	2023年7月24日	综合判定：合格	

717	GX-B1423/20-Y-234175	2023年7月24日	综合判定：合格	
718	GX-B1423/20-Y-234176	2023年7月24日	综合判定：合格	

719	GX-B1423/20-Y-234177	2023年7月24日	综合判定：合格	
720	GX-B1423/20-Y-234178	2023年7月24日	综合判定：合格	

721	GX-B1423/20-Y-234179	2023年7月24日	综合判定：合格	
722	GX-B1423/20-Y-234180	2023年7月24日	综合判定：合格	

723	GX-B1423/20-Y-234181	2023年7月24日	综合判定：合格	 <p>A photograph showing a yellow dump truck parked on a dirt surface at a construction site. A person wearing a white shirt and a red hard hat stands to the left of the truck, facing it. The background shows a clear blue sky and some construction equipment. A small yellow timestamp '2023/7/6' is visible in the bottom right corner of the image.</p>
724	GX-B1423/20-Y-234182	2023年7月24日	综合判定：合格	 <p>A photograph showing a yellow dump truck parked on a dirt surface at a construction site. Two people are standing in front of the truck. One person is wearing a white shirt and a red hard hat, and the other is wearing a dark shirt and a dark hard hat. The background shows a clear blue sky and some construction equipment. A small yellow timestamp '2023/7/6' is visible in the bottom right corner of the image.</p>

725	GX-B1423/20-Y-234183	2023年7月24日	综合判定：合格	
726	GX-B1423/20-Y-234184	2023年7月24日	综合判定：合格	

727	GX-B1423/20-Y-234185	2023年7月24日	综合判定：合格	
728	GX-B1423/20-Y-234186	2023年7月24日	综合判定：合格	

729	GX-B1423/20-Y-234187	2023年7月24日	综合判定：合格	
730	GX-B1423/20-Y-234188	2023年7月24日	综合判定：合格	

731	GX-B1424/20-Y-23011	2023年7月24日	依据NB/T 10176-2019单轨吊车综合判定合格。	 A worker wearing a red safety suit and a red helmet is inspecting a component of a monorail crane. The worker is holding a small object, possibly a tool or a part, and is looking at it intently. The background shows the interior of the crane with various mechanical parts and a white panel. A yellow timestamp "2023/6/17" is visible in the bottom right corner of the image.
732	GX-B1310/21-Y-23120	2023年7月24日	符合标准要求。	 A worker wearing a white shirt and a red helmet is inspecting a component of a monorail crane. The worker is holding a small object, possibly a tool or a part, and is looking at it intently. The background shows the interior of the crane with various mechanical parts and a white panel. A yellow timestamp "2023/6/17" is visible in the bottom right corner of the image.

733	GX-B1328/20-Y-23084	2023年7月24日	本次共检绝缘手套82只，82只绝缘手套所检项目合格。	
734	GX-B1328/20-Y-23085	2023年7月24日	本次共检绝缘鞋90只，90只绝缘鞋所检项目合格。	

735	GX-B1521/20-Y-23381	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
736	GX-B1521/20-Y-23382	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

737	GX-B1521/20-Y-23383	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
738	GX-B1521/20-Y-23384	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

739	GX-B1521/20-Y-23385	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
740	GX-B1521/20-Y-23386	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

741	GX-B1521/20-Y-23387	2023. 7. 24	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
742	GX-B1521/20-Y-23388	2023. 7. 24	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	

743	GX-B1521/20-Y-23389	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
744	GX-B1521/20-Y-23390	2023. 7. 24	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

745	GX-B1521/20-Y-23391	2023. 7. 24	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
746	GX-B1539/22-Y-23162	2023. 7. 24	所检项目合格。	

747	GX-B1539/22-Y-23163	2023. 7. 24	所检项目合格。	
748	GX-B1539/22-Y-23164	2023. 7. 24	所检项目合格。	

749	GX-B1539/22-Y-23165	2023. 7. 24	所检项目合格。	
750	GX-B1539/22-Y-23166	2023. 7. 24	所检项目合格。	

751	GX-B1539/22-Y-23167	2023. 7. 24	所检项目合格。	
752	GX-B1539/22-Y-23168	2023. 7. 24	所检项目合格。	

753	GX-B1521/20-Y-23392	2023年7月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
754	GX-B1521/20-Y-23393	2023年7月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	

755	GX-B1521/20-Y-23394	2023年7月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
756	GX-B1521/20-Y-23395	2023年7月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	

757	GX-B1521/20-Y-23396	2023年7月25日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p> <p>。</p>	
758	GX-B1521/20-Y-23397	2023年7月25日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p> <p>。</p>	

759	GX-B1563/21-Y-23009	2023年7月25日	所检项目合格。	
760	GX-B1563/21-Y-23010	2023年7月25日	所检项目合格。	

761	GX-B1563/21-Y-23011	2023年7月25日	所检项目合格。	
762	GX-B1563/21-Y-23012	2023年7月25日	所检项目合格。	

763	GX-B1563/21-Y-23013	2023年7月25日	所检项目合格。	
764	GX-B1563/21-Y-23014	2023年7月25日	所检项目合格。	

765	GX-B1521/20-Y-23169	2023年7月26日	所检项目合格。	 <p>A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two workers in white uniforms and red hard hats are standing next to the loader. A yellow date stamp '2023/7/7' is visible in the bottom right corner of the photo.</p>
766	GX-B1521/20-Y-23170	2023年7月26日	所检项目合格。	 <p>A worker wearing a red hard hat and a white uniform is inspecting a yellow wheel loader. The worker is holding a clipboard and looking at the machine's components. The loader has 'Lonking 龙工' written on its side. A yellow date stamp '2023/7/7' is visible in the bottom right corner of the photo.</p>

767	GX-B1521/20-Y-23171	2023年7月26日	所检项目合格。	
768	GX-B1521/20-Y-23172	2023年7月26日	所检项目合格。	