

序号	报告编号	发布日期	结论	影像资料
108	GX-B1323/21-Y-23148~23150	2023年8月2日	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。	
109	GX-B1323/21-Y-23151~23152	2023年8月2日	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。	

110	GX-B1301/21-Y-23002	2023年8月4日	综合判定:合格。	 A photograph showing several workers in blue uniforms and red hard hats working in a large industrial facility. They are gathered around a large blue machine, possibly a cable testing or processing unit. The date stamp '2023/7/14' is visible in the bottom right corner of the image.
111	GX-B1321/20-Y-23601~23604	2023年8月2日	本次共检验电力电缆4条, 4条电力电缆所检项目合格。 。	 A photograph showing workers in blue uniforms and red hard hats working in a control room or office setting. They are gathered around a desk or workstation, possibly reviewing data or equipment. The date stamp '2023/7/14' is visible in the bottom right corner of the image.

112	GX-B1306/21-Y-23125	2023年8月1日	所检项目合格。	
113	GX-B1415/22-Y-23012	2023年8月4日	综合判定:合格。	

114	GX-B1321/20-Y-23601~23604	2023年8月2日	本次共检验电力电缆4条， 4条电力电缆所检项目合格。 。	 A photograph showing three workers in a room with rows of electrical cabinets. One worker is kneeling and testing a cable, while two others stand nearby. A date stamp '2023-7-18' is visible in the bottom right corner of the image.
115	GX-B1306/21-Y-23125	2023年8月1日	所检项目合格。	 A photograph of a worker wearing a red hard hat and a grey uniform, kneeling and testing a cable inside an electrical cabinet. A blue and orange testing device is on the floor next to him. A date stamp '2023-6-29' is visible in the bottom right corner of the image.

116	GX-B1423/20-Y-234700	2023年8月1日	综合判定：合格	 A yellow dump truck is parked on a dirt lot. A person in a high-visibility vest is standing next to the truck, and another person is kneeling on the ground in front of it. The truck has a license plate that reads '37'. A yellow date stamp '2023/7/27' is visible in the bottom right corner of the photo.
117	GX-B1423/20-Y-234701	2023年8月1日	综合判定：合格	 A yellow dump truck is parked on a dirt lot. Two people in high-visibility vests are standing next to the truck. The truck has a license plate that reads '37'. A yellow date stamp '2023/7/27' is visible in the bottom right corner of the photo.

118	GX-B1423/20-Y-234702	2023年8月1日	综合判定：合格	
119	GX-B1423/20-Y-234703	2023年8月1日	综合判定：合格	

120	GX-B1423/20-Y-234704	2023年8月1日	综合判定：合格	
121	GX-B1423/20-Y-234705	2023年8月1日	综合判定：合格	

122	GX-B1423/20-Y-234706	2023年8月1日	综合判定：合格	 A yellow dump truck with the number 36 on its side, parked on a dirt lot. Two workers in safety gear are standing near the front. A date stamp '2023/7/27' is visible in the bottom right corner.
123	GX-B1423/20-Y-234693	2023年8月1日	综合判定：合格	 A yellow dump truck with the number 41 on its side, parked on a dirt lot. Two workers in safety gear are standing near the front. A date stamp '2023/7/27' is visible in the bottom right corner.



124	GX-B1423/20-Y-234694	2023年8月1日	综合判定：合格	
125	GX-B1423/20-Y-234695	2023年8月1日	综合判定：合格	

126	GX-B1423/20-Y-234696	2023年8月1日	综合判定：合格	
127	GX-B1423/20-Y-234697	2023年8月1日	综合判定：合格	

128	GX-B1423/20-Y-234698	2023年8月1日	综合判定：合格	
129	GX-B1423/20-Y-234699	2023年8月1日	综合判定：合格	

130	GX-B1423/20-Y-234189	2023年8月2日	综合判定：合格	 A yellow dump truck with the number 20 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of it. The image has a timestamp '2023/7/8' in the bottom right corner and 'iQOO 8' in the bottom left corner.	
131	GX-B1423/20-Y-234190	2023年8月2日	综合判定：合格	 A yellow dump truck with the number 15 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of it. The image has a timestamp '2023/7/8' in the bottom right corner and 'iQOO 8' in the bottom left corner.	

132	GX-B1423/20-Y-234191	2023年8月2日	综合判定：合格	 <p>A yellow dump truck with the number 25 on its side, parked on a dirt surface. Two people are standing in front of the truck. The image has a timestamp '2023/7/8' in the bottom right corner and '1000 8' in the bottom left corner.</p>
133	GX-B1423/20-Y-234192	2023年8月2日	综合判定：合格	 <p>A yellow dump truck with the number 23 on its side, parked on a dirt surface. Two people are standing in front of the truck. The image has a timestamp '2023/7/8' in the bottom right corner and '1000 8' in the bottom left corner.</p>

134	GX-B1423/20-Y-234193	2023年8月2日	综合判定：合格	 A yellow dump truck with the number 19 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. The image has a timestamp '2023/7/8' in the bottom right corner.	
135	GX-B1423/20-Y-234194	2023年8月2日	综合判定：合格	 A yellow dump truck with the number 22 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. The image has a timestamp '2023/7/8' in the bottom right corner.	

136	GX-B1423/20-Y-234195	2023年8月2日	综合判定：合格	 <p>A yellow dump truck with license plate number 16 is shown in a photograph. Two workers in safety gear are standing in front of the truck. The photo includes a timestamp '2023/7/8' in the bottom right corner and 'IQQO 8' in the bottom left corner.</p>
137	GX-B1423/20-Y-234196	2023年8月2日	综合判定：合格	 <p>A yellow dump truck with license plate number 72 is shown in a photograph. Two workers in safety gear are standing in front of the truck. The photo includes a timestamp '2023/7/8' in the bottom right corner and 'IQQO 8' in the bottom left corner.</p>

138	GX-B1423/20-Y-234197	2023年8月2日	综合判定：合格	
139	GX-B1423/20-Y-234198	2023年8月2日	综合判定：合格	



140	GX-B1423/20-Y-234199	2023年8月2日	综合判定：合格	 <p>A yellow MT860 dump truck with the number 69 on its side. Two people are standing in front of the truck. The image includes a timestamp '2023/7/9' in the bottom right corner and 'IQQO 8' in the bottom left corner.</p>
141	GX-B1423/20-Y-234200	2023年8月2日	综合判定：合格	 <p>A yellow MT860 dump truck with the number 70 on its side. Two people are standing in front of the truck. The image includes a timestamp '2023/7/9' in the bottom right corner and 'IQQO 8' in the bottom left corner.</p>

142	GX-B1423/20-Y-234201	2023年8月2日	综合判定：合格	 <p>A yellow MT860 dump truck is shown from a front-three-quarter view. The truck has the number '188' on the top of the dump body and 'MT860' on the side. The license plate is '66'. Two men in work clothes are standing in front of the truck. The image has a yellow timestamp '2023/7/9' in the bottom right corner and '1000 8' in the bottom left corner.</p>
143	GX-B1423/20-Y-234202	2023年8月2日	综合判定：合格	 <p>A yellow MT860 dump truck is shown from a front-three-quarter view. The truck has the number '188' on the top of the dump body and 'MT860' on the side. The license plate is '63'. Two men in work clothes are standing in front of the truck. The image has a yellow timestamp '2023/7/9' in the bottom right corner and '1000 8' in the bottom left corner.</p>

144	GX-B1423/20-Y-234203	2023年8月2日	综合判定：合格	 <p>A yellow dump truck with the number 68 on its side, parked on a dirt surface. Two people are standing next to it. The image has a timestamp '2023/7/9' in the bottom right corner and 'iQOO 8' in the bottom left corner.</p>
145	GX-B1423/20-Y-234204	2023年8月2日	综合判定：合格	 <p>A yellow dump truck with the number 67 on its side, parked on a dirt surface. Two people are standing next to it. The image has a timestamp '2023/7/9' in the bottom right corner and 'iQOO 8' in the bottom left corner.</p>

146	GX-B1423/20-Y-234205	2023年8月2日	综合判定：合格	 A yellow MT859 truck with license plate 62 is parked on a dirt surface. Two workers in blue and grey uniforms are standing next to it. The image has a yellow timestamp '2023/7/9' in the bottom right corner and 'IQQ08' in the bottom left corner.
147	GX-B1423/20-Y-234206	2023年8月2日	综合判定：合格	 A grey truck with license plate 71 is parked on a dirt surface. Two workers in blue and grey uniforms are standing next to it. The image has a yellow timestamp '2023/7/9' in the bottom right corner and 'IQQ08' in the bottom left corner.

148	GX-B1423/20-Y-234207	2023年8月2日	综合判定：合格	
149	GX-B1423/20-Y-234208	2023年8月2日	综合判定：合格	

150	GX-B1423/20-Y-234209	2023年8月2日	综合判定：合格	
151	GX-B1423/20-Y-234210	2023年8月2日	综合判定：合格	

152	GX-B1423/20-Y-234211	2023年8月2日	综合判定：合格	
153	GX-B1423/20-Y-234212	2023年8月1日	综合判定：合格	

154	GX-B1423/20-Y-234213	2023年8月1日	综合判定：合格	
155	GX-B1423/20-Y-234214	2023年8月1日	综合判定：合格	



156	GX-B1423/20-Y-234215	2023年8月1日	综合判定：合格	
157	GX-B1423/20-Y-234216	2023年8月1日	综合判定：合格	

158	GX-B1423/20-Y-234217	2023年8月1日	综合判定：合格	
159	GX-B1423/20-Y-234218	2023年8月1日	综合判定：合格	

160	GX-B1423/20-Y-234219	2023年8月1日	综合判定：合格	
161	GX-B1423/20-Y-234220	2023年8月1日	综合判定：合格	

162	GX-B1423/20-Y-234221	2023年8月1日	综合判定：合格	
163	GX-B1423/20-Y-234222	2023年8月1日	综合判定：合格	

164	GX-B1423/20-Y-234223	2023年8月1日	综合判定：合格	
165	GX-B1423/20-Y-234224	2023年8月1日	综合判定：合格	

166	GX-B1423/20-Y-234225	2023年8月1日	综合判定：合格	
167	GX-B1423/20-Y-234226	2023年8月1日	综合判定：合格	

168	GX-B1423/20-Y-234227	2023年8月1日	综合判定：合格	
169	GX-B1423/20-Y-234228	2023年8月1日	综合判定：合格	

170	GX-B1423/20-Y-234229	2023年8月1日	综合判定：合格	
171	GX-B1423/20-Y-234230	2023年8月1日	综合判定：合格	



172	GX-B1423/20-Y-234231	2023年8月1日	综合判定：合格	
173	GX-B1423/20-Y-234232	2023年8月1日	综合判定：合格	

174	GX-B1423/20-Y-234233	2023年8月1日	综合判定：合格	
175	GX-B1423/20-Y-234234	2023年8月1日	综合判定：合格	

176	GX-B1423/20-Y-234235	2023年8月1日	综合判定：合格	
177	GX-B1423/20-Y-234236	2023年8月1日	综合判定：合格	

178	GX-B1423/20-Y-234237	2023年8月1日	综合判定：合格	
179	GX-B1423/20-Y-234238	2023年8月1日	综合判定：合格	

180	GX-B1423/20-Y-234239	2023年8月1日	综合判定：合格	
181	GX-B1423/20-Y-234240	2023年8月1日	综合判定：合格	

182	GX-B1423/20-Y-234241	2023年8月1日	综合判定：合格	
183	GX-B1423/20-Y-234242	2023年8月1日	综合判定：合格	

184	GX-B1423/20-Y-234243	2023年8月1日	综合判定：合格	
185	GX-B1423/20-Y-234244	2023年8月1日	综合判定：合格	

186	GX-B1423/20-Y-234245	2023年8月1日	综合判定：合格	
187	GX-B1423/20-Y-234246	2023年8月1日	综合判定：合格	



188	GX-B1423/20-Y-234247	2023年8月1日	综合判定：合格	
189	GX-B1423/20-Y-234248	2023年8月1日	综合判定：合格	

190	GX-B1423/20-Y-234249	2023年8月1日	综合判定：合格	
191	GX-B1423/20-Y-234250	2023年8月1日	综合判定：合格	

192	GX-B1423/20-Y-234251	2023年8月1日	综合判定：合格	
193	GX-B1423/20-Y-234252	2023年8月1日	综合判定：合格	

194	GX-B1423/20-Y-234253	2023年8月1日	综合判定：合格	
195	GX-B1423/20-Y-234254	2023年8月1日	综合判定：合格	

196	GX-B1423/20-Y-234255	2023年8月1日	综合判定：合格	
197	GX-B1423/20-Y-234256	2023年8月1日	综合判定：合格	

198	GX-B1423/20-Y-234257	2023年8月1日	综合判定：合格	
199	GX-B1423/20-Y-234258	2023年8月1日	综合判定：合格	

200	GX-B1423/20-Y-234259	2023年8月1日	综合判定：合格	
201	GX-B1423/20-Y-234260	2023年8月1日	综合判定：合格	

202	GX-B1423/20-Y-234261	2023年8月1日	综合判定：合格	
203	GX-B1423/20-Y-233899	2023年8月1日	综合判定：合格	



204	GX-B1423/20-Y-233900	2023年8月1日	综合判定：合格	
205	GX-B1423/20-Y-233901	2023年8月1日	综合判定：合格	

206	GX-B1423/20-Y-233902	2023年8月1日	综合判定：合格	
207	GX-B1423/20-Y-233903	2023年8月1日	综合判定：合格	

208	GX-B1423/20-Y-233904	2023年8月1日	综合判定：合格	
209	GX-B1423/20-Y-233905	2023年8月1日	综合判定：合格	

210	GX-B1423/20-Y-233906	2023年8月1日	综合判定：合格	
211	GX-B1423/20-Y-233907	2023年8月1日	综合判定：合格	

212	GX-B1423/20-Y-233908	2023年8月1日	综合判定：合格	
213	GX-B1423/20-Y-233909	2023年8月1日	综合判定：合格	

214	GX-B1423/20-Y-233910	2023年8月1日	综合判定：合格	
215	GX-B1423/20-Y-233911	2023年8月1日	综合判定：合格	

216	GX-B1423/20-Y-233912	2023年8月1日	综合判定：合格	
217	GX-B1423/20-Y-233913	2023年8月1日	综合判定：合格	

218	GX-B1423/20-Y-233914	2023年8月1日	综合判定：合格	 <p>A yellow TONLY dump truck is shown from a side-rear perspective. A worker in a high-visibility vest and red hard hat stands next to the truck. The truck has a blue number '11' on its side. A yellow date stamp '2023/6/24' is visible in the bottom right corner of the image.</p>
219	GX-B1423/20-Y-233915	2023年8月1日	综合判定：合格	 <p>A yellow TONLY dump truck is shown from a front-three-quarter view. A worker in a high-visibility vest and red hard hat stands in front of the truck. The truck has 'TONLY' written on the top of the dump body. A yellow date stamp '2023/6/21' is visible in the bottom right corner of the image.</p>



220	GX-B1423/20-Y-233916	2023年8月1日	综合判定：合格	
221	GX-B1423/20-Y-233917	2023年8月1日	综合判定：合格	

222	GX-B1423/20-Y-233918	2023年8月1日	综合判定：合格	
223	GX-B1423/20-Y-233919	2023年8月1日	综合判定：合格	

224	GX-B1423/20-Y-233920	2023年8月1日	综合判定：合格	
225	GX-B1423/20-Y-233921	2023年8月1日	综合判定：合格	

226	GX-B1423/20-Y-233922	2023年8月1日	综合判定：合格	
227	GX-B1301/21-Y-23002	2023年8月4日	综合判定：合格。	

228	GX-B1557/22-Y-23022	2023年8月4日	所检项目合格。	
-----	---------------------	-----------	---------	---