

序号	报告编号	发布日期	结论	影像资料
105	GX-B1300/20-1-23010	2023/8/9	合格	
106	GX-B1416/22-1-23016	2023/8/10	综合判定：合格。	
107	GX-B1416/22-1-23017	2023/8/10	综合判定：合格。	
108	GX-B1416/22-1-23019	2023/8/10	综合判定：合格。	

109	GX-B1416/22-1-23020	2023/8/10	综合判定：合格。	 A photograph showing two workers in safety gear (hard hats, high-visibility vests) inspecting industrial equipment. One worker is holding a clipboard. The date stamp '2023.07.08' is visible in the bottom left corner.
110	GX-B1416/22-1-23021	2023/8/10	综合判定：合格。	 A photograph of a worker in safety gear using a flashlight to inspect a dark area, possibly a confined space or a specific component of the equipment. The date stamp '2023.07.09' is visible in the bottom left corner.
111	GX-B1416/22-1-23022	2023/8/10	综合判定：合格。	 A photograph of a worker in safety gear inspecting a yellow safety railing or barrier. The worker is pointing towards the railing. The date stamp '2023.07.09' is visible in the bottom left corner.
112	GX-B1451/20-1-23623~23648	2023/8/11	所检项目合格	 A photograph of a worker in safety gear (hard hat, safety glasses, gloves) inspecting a confined space or a specific component of the equipment. The date stamp '2023.07.06' is visible in the bottom right corner.

113	GX-B1350/21-1-23026	2023. 8. 11	本次共检接地装置2处，2处所检项目全部合格			
114	GX-B1350/21-1-23027	2023. 8. 14	本次共检接地装置17处，17处所检项目全部合格			
115	GX-B1307/20-1-23076	2023. 8. 15	综合判定：合格			
116	GX-B1307/20-1-23077	2023. 8. 15	综合判定：合格			

117	GX-B1307/20-1-23078	2023. 8. 15	综合判定：合格		
118	GX-B1307/20-1-23079	2023. 8. 15	综合判定：合格		
119	GX-B1307/20-1-23080	2023. 8. 15	综合判定：合格		
120	GX-B1307/20-1-23081	2023. 8. 15	综合判定：合格		

121	GX-B1307/20-1-23082	2023. 8. 15	综合判定：合格			
122	GX-B1304/21-1-23005	2023. 8. 14	综合判定：合格			
123	GX-B1304/21-1-23006	2023. 8. 14	综合判定：合格			
124	GX-B1303/21-1-23008	2023. 8. 14	综合判定：合格			

125	GX-B1303/21-1-23009	2023. 8. 14	综合判定：合格	
126	GX-B1303/21-1-23010	2023. 8. 14	综合判定：合格	
127	GX-B1303/21-1-23011	2023. 8. 14	综合判定：合格	
128	GX-B1304/21-1-23005	2023. 8. 14	综合判定：合格	

129	GX-B1304/21-1-23006	2023. 8. 14	综合判定：合格	 <p>2023 07 22</p>
130	GX-B1304/21-1-23007	2023. 8. 14	综合判定：合格	 <p>2023/07/22</p>
131	GX-B1304/21-1-23008	2023. 8. 14	综合判定：合格	 <p>2023/07/22</p>
132	GX-B1304/21-1-23009	2023. 8. 14	综合判定：合格	 <p>2023 07 19</p>

133	GX-B1304/21-1-23010	2023. 8. 14	综合判定：合格	
134	GX-B1304/21-1-23011	2023. 8. 14	综合判定：合格	
135	GX-B1305/21-1-23016	2023/8/15	综合判定：合格	
136	GX-B1310/21-1-23112	2023. 8. 14	符合标准要求	

137	GX-B1427/21-1-23112	2023. 8. 14	符合标准要求			
138	GX-B1310/21-1-23113	2023. 8. 14	符合标准要求			
139	GX-B1310/21-1-23114	2023. 8. 14	符合标准要求			
140	GX-B1310/21-1-23115	2023. 8. 14	符合标准要求			

141	GX-B1310/21-1-23116	2023. 8. 14	符合标准要求		 2023/07/21	
142	GX-B1310/21-1-23117	2023. 8. 14	符合标准要求		 2023/07/21	
143	GX-B1310/21-1-23118	2023. 8. 14	符合标准要求		 2023/07/21	
144	GX-B1310/21-1-23119	2023. 8. 14	符合标准要求		 2023/07/21	

145	GX-B1310/21-1-23120	2023. 8. 14	符合标准要求		
146	GX-B1427/21-1-23120	2023. 8. 14	符合标准要求		
147	GX-B1310/21-1-23121	2023. 8. 14	符合标准要求		
148	GX-B1303/21-1-23007	2023/8/15	综合判定：合格		

149	GX-B1312/20-1-23479	2023. 8. 16	所检项目合格	
150	GX-B1321/20-1-23916	2023. 8. 16	所检项目合格	
151	GX-B1303/21-1-23012	2023/8/16	综合判定：合格	
152	GX-B1305/21-1-23012	2023. 8. 18	综合判定：合格	

153	GX-B1350/21-1-23028	2023. 8. 14	本次共检接地装置18处，18处所检项目全部合格	
154	GX-B1423/20-1-23531	2023/8/18	综合判定：合格	
155	GX-B1423/20-1-23532	2023/8/18	综合判定：合格	
156	GX-B1423/20-1-23533	2023/8/18	综合判定：合格	

157	GX-B1423/20-1-23534	2023/8/18	综合判定：合格	
158	GX-B1423/20-1-23535	2023/8/18	综合判定：合格	
159	GX-B1423/20-1-23536	2023/8/18	综合判定：合格	
160	GX-B1423/20-1-23537	2023/8/18	综合判定：合格	

161	GX-B1423/20-1-23538	2023/8/18	综合判定：合格		
162	GX-B1423/20-1-23539	2023/8/18	综合判定：合格		
163	GX-B1423/20-1-23540	2023/8/18	综合判定：合格		
164	GX-B1423/20-1-23541	2023/8/18	综合判定：合格		

165	GX-B1423/20-1-23542	2023/8/18	综合判定：合格	
166	GX-B1303/21-1-23012	2023. 8. 15	综合判定：合格	
167	GX-B1305/21-1-23013	2023. 8. 15	综合判定：合格	
168	GX-B1305/21-1-23014	2023. 8. 15	综合判定：合格	

169	GX-B1305/21-1-23015	2023. 8. 15	综合判定：合格			
170	GX-B1324/21-1-23010~23021	2023. 8. 14	本次共检测三相交流电动机12台，12台三相交流电动机所检项目合格			
171	GX-B1322/21-1-23208	2023. 8. 22	所检项目合格			
172	GX-B1313/21-1-23095~23096	2023. 8. 22	本次共检电力变压器2台，2台电力变压器所检项目合格			