


序号	报告编号	发布日期	结论	影像资料
321	GX-B1495/20-2-231400~231406	2023. 8. 22	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
322	GX-B1495/20-2-231407~231414	2023. 8. 22	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
323	GX-B1495/20-2-231415~231424	2023. 8. 22	本次共检高压开关柜10台，10台高压开关柜所检项目合格。	

324	GX-B1495/20-2-231425~231434	2023. 8. 22	本次共检高压开关柜10台，10台高压开关柜所检项目合格。	
325	GX-B1495/20-2-231435~231443	2023. 8. 22	本次共检高压开关柜9台，9台高压开关柜所检项目合格。	
326	GX-B1495/20-2-231444~231449	2023. 8. 22	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	


327	GX-B1495/20-2-231450~231459	2023. 8. 22	本次共检高压开关柜10台，10台高压开关柜所检项目合格。	
328	GX-B1495/20-2-231460~231467	2023. 8. 22	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
329	GX-B1495/20-2-231468~231474	2023. 8. 22	本次共检互感器7组，7组互感器所检项目合格。	

330	GX-B1495/20-2-231475~231482	2023. 8. 22	本次共检互感器8组，8组互感器所检项目合格。	
331	GX-B1495/20-2-231483~231492	2023. 8. 22	本次共检互感器10组，10组互感器所检项目合格。	
332	GX-B1495/20-2-231493~231502	2023. 8. 22	本次共检互感器10组，10组互感器所检项目合格。	


333	GX-B1495/20-2-231503~231511	2023. 8. 22	本次共检互感器9组，9组互感器所检项目合格。	
334	GX-B1495/20-2-231512~231517	2023. 8. 22	本次共检互感器6组，6组互感器所检项目合格。	
335	GX-B1495/20-2-231518~231527	2023. 8. 22	本次共检互感器10组，10组互感器所检项目合格。	


336	GX-B1495/20-2-231528~231535	2023. 8. 22	本次共检互感器8组，8组互感器所检项目合格。	
337	GX-B1495/20-2-231536~231539	2023. 8. 22	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
338	GX-B1495/20-2-231540~231542	2023. 8. 22	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	

339	GX-B1495/20-2-231543~231546	2023. 8. 22	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
340	GX-B1495/20-2-231219~231220	2023. 8. 22	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
341	GX-B1495/20-2-231221~231222	2023. 8. 22	本次共检互感器2组，2组互感器所检项目合格。	


342	GX-B1321/20-2-23585	2023. 8. 22	所检项目合格。		
343	GX-B1312/20-2-23230~23231	2023. 8. 22	本次共检电力变压器2台，2台所检项目合格。		
344	GX-B1495/20-2-231601~231607	2023. 8. 22	本次共检高压开关设备7台，7台所检项目合格。		

345	GX-B1415/22-2-23019	2023. 8. 21	综合判定：合格。	 2023/07/15
346	GX-B1359/21-2-23055~23056	2023. 8. 22	本次共检矿用隔爆型照明信号综合保护装置2台，2台所检项目合格。	 2023/07/15
347	GX-B1310/21-2-23169	2023. 8. 22	符合标准要求。	 2023/07/18

348	GX-B1495-20-2-231941~231954	2023. 8. 23	本次共检高压开关柜14台，14台高压开关柜所检项目合格。	
349	GX-B1495-20-2-231955~231959	2023. 8. 23	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	
350	GX-B1495-20-2-231960~231963	2023. 8. 23	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	

351	GX-B1495-20-2-231964~231973	2023. 8. 23	本次共检高压开关柜10台，10台高压开关柜所检项目合格。	
352	GX-B1495-20-2-231974~231980	2023. 8. 23	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
353	GX-B1495-20-2-231981~231987	2023. 8. 23	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	

354	GX-B1495-20-2-231988~231995	2023. 8. 23	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
355	GX-B1312/20-2-23308~23309	2023. 8. 24	本次共检电力变压器2台，2台所检项目合格。	
356	GX-B1312/20-2-23310	2023. 8. 24	所检项目合格。	

357	GX-B1312/20-2-23311~23312	2023. 8. 24	本次共检电力变压器2台，2台所检项目合格。	
358	GX-B1312/20-2-23313	2023. 8. 24	所检项目合格。	
359	GX-B1312/20-2-23314	2023. 8. 24	所检项目合格。	

360	GX-B1312/20-2-23315~23316	2023. 8. 24	本次共检电力变压器2台，2台所检项目合格。	
361	GX-B1312/20-2-23317	2023. 8. 24	所检项目合格。	
362	GX-B1312/20-2-23318	2023. 8. 24	所检项目合格。	

363	GX-B1312/20-2-23319~23321	2023. 8. 24	本次共检电力变压器3台，3台所检项目合格。		
364	GX-B1499/21-2-23086	2023. 8. 23	所检项目合格。		
365	GX-B1499/21-2-23087	2023. 8. 23	所检项目合格。		

366	GX-B1499/21-2-23088	2023. 8. 23	所检项目合格。	 2023/08/09
367	GX-B1499/21-2-23089	2023. 8. 23	所检项目合格。	 2023/08/09
368	GX-B1499/21-2-23090	2023. 8. 23	所检项目合格。	 2023/08/09

369	GX-B1499/21-2-23098	2023. 8. 23	所检项目合格。	 <p>2023/08/10</p>
370	GX-B1548/20-2-23102	2023. 8. 23	所检项目合格。	 <p>2023/08/11</p>
371	GX-B1548/20-2-23088	2023. 8. 23	所检项目合格。	 <p>2023/08/09</p>

372	GX-B1548/20-2-23089	2023. 8. 23	所检项目合格。	 A man wearing glasses and a light blue short-sleeved shirt stands in front of a yellow vehicle. The vehicle's license plate is WKF-180. The background shows an outdoor area with some equipment and a building.
373	GX-B1548/20-2-23090	2023. 8. 23	所检项目合格。	 A man wearing glasses and a light blue short-sleeved shirt stands next to a yellow vehicle. The vehicle is parked in an outdoor area with a building in the background.
374	GX-B1534/20-2-23064	2023. 8. 23	所检项目合格。	 A man wearing glasses and a light blue short-sleeved shirt stands in front of a large yellow vehicle. Other people and vehicles are visible in the background, including a red vehicle and a building.

375	GX-B1534/20-2-23065	2023. 8. 23	所检项目合格。	 <p>2023/08/11</p>
376	GX-B1534/20-2-23066	2023. 8. 23	所检项目合格。	 <p>2023/08/11</p>
377	GX-B1534/20-2-23067	2023. 8. 23	所检项目合格。	 <p>2023/08/11</p>

378	GX-B1534/20-2-23068	2023. 8. 23	所检项目合格。	 <p>2023/08/11</p>
379	GX-B1548/20-2-23096	2023. 8. 23	所检项目合格。	 <p>2023/08/11</p>
380	GX-B1548/20-2-23097	2023. 8. 23	所检项目合格。	 <p>2023/08/11</p>

381	GX-B1548/20-2-23098	2023. 8. 23	所检项目合格。	
382	GX-B1548/20-2-23099	2023. 8. 23	所检项目合格。	
383	GX-B1548/20-2-23100	2023. 8. 23	所检项目合格。	


384	GX-B1548/20-2-23101	2023. 8. 23	所检项目合格。	
385	GX-B1548/20-2-23058	2023. 8. 23	所检项目合格。	
386	GX-B1548/20-2-23062	2023. 8. 23	所检项目合格。	

387	GX-B1548/20-2-23068	2023. 8. 23	所检项目合格。	
388	GX-B1548/20-2-23063	2023. 8. 23	所检项目合格。	
389	GX-B1548/20-2-23064	2023. 8. 23	所检项目合格。	

390	GX-B1548/20-2-23065	2023. 8. 23	所检项目合格。	
391	GX-B1548/20-2-23059	2023. 8. 23	所检项目合格。	
392	GX-B1548/20-2-23060	2023. 8. 23	所检项目合格。	

393	GX-B1548/20-2-23061	2023. 8. 23	所检项目合格。	 <p>A photograph showing four people in safety gear (hard hats and high-visibility vests) standing around a yellow truck. One person is kneeling on the ground, possibly using a tool or measuring device. The scene is outdoors on a dirt or gravel surface. A date stamp '2023/05/24' is visible in the bottom right corner of the photo.</p>
394	GX-B1534/20-2-23061	2023. 8. 24	所检项目合格。	 <p>A photograph showing three people in safety gear standing next to a yellow forklift. One person is holding a clipboard. The scene is outdoors on a dirt or gravel surface. A date stamp '2023/05/24' is visible in the bottom right corner of the photo.</p>
395	GX-B1534/20-2-23062	2023. 8. 24	所检项目合格。	 <p>A photograph showing three people in safety gear standing next to a yellow forklift. One person is holding a clipboard. The scene is outdoors on a dirt or gravel surface. A date stamp '2023/05/24' is visible in the bottom right corner of the photo.</p>

396	GX-B1534/20-2-23063	2023. 8. 24	所检项目合格。	 <p>2023/08/24</p>
397	GX-B1548/20-2-23066	2023. 8. 24	除未设置车身反光标志，其余所检项目合格。	 <p>2023/08/24</p>
398	GX-B1548/20-2-23067	2023. 8. 24	所检项目合格。	 <p>2023/08/24</p>

399	GX-B1534/20-2-23024	2023. 8. 23	所检项目合格。	
400	GX-B1495/20-2-231996~232003	2023. 8. 24	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	
401	GX-B1495/20-2-232091~232094	2023. 8. 24	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	

402	GX-B1495/20-2-232095~232098	2023. 8. 24	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	 <p>2023/07/30</p>
403	GX-B1495/20-2-232099~232106	2023. 8. 24	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	 <p>2023/07/31</p>
404	GX-B1495/20-2-232126~232129	2023. 8. 24	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	 <p>2023/08/01</p>


405	GX-B1495/20-2-232130~232140	2023. 8. 24	本次共检高压防爆开关11台，11台高压防爆开关所检项目合格。	
406	GX-B1495/20-2-232141~232150	2023. 8. 24	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
407	GX-B1495/20-2-232151~232157	2023. 8. 24	本次共检高压防爆开关7台，7台高压防爆开关所检项目合格。	

408	GX-B1495/20-2-232158~232166	2023. 8. 24	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	 <p>2023/08/05</p>
409	GX-B1323/21-2-23105~23108	2023. 8. 24	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	 <p>2023.7.29</p>
410	GX-B1323/21-2-23109~23111	2023. 8. 24	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。	 <p>2023/8</p>

411	GX-B1323/21-2-23112~23114	2023. 8. 24	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。	
412	GX-B1323/21-2-23103~23104	2023. 8. 24	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。	
413	GX-B1321/20-2-23460~23461	2023. 8. 24	本次共检验电力电缆2条，2条所检项目合格。	

414	GX-B1312/20-2-23216~23217	2023. 8. 24	本次共检电力变压器2台，2台所检项目合格。	
415	GX-B1312/20-2-23218~23223	2023. 8. 24	本次共检电力变压器6台，6台所检项目合格。	
416	GX-B1312/20-2-23224~23227	2023. 8. 24	本次共检电力变压器4台，4台所检项目合格。	

417	GX-B1312/20-2-23228~23229	2023. 8. 24	本次共检电力变压器2台，2台所检项目合格。	
418	GX-B1495/20-2-232107~232113	2023. 8. 24	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
419	GX-B1495/20-2-232114~232117	2023. 8. 24	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	

420	GX-B1495/20-2-232020~232037	2023. 8. 24	本次共检互感器18组，18组互感器所检项目合格。	
421	GX-B1495/20-2-232038~232043	2023. 8. 24	本次共检互感器6组，6组互感器所检项目合格。	
422	GX-B1495/20-2-232044~232048	2023. 8. 24	本次共检互感器5组，5组互感器所检项目合格。	

423	GX-B1495/20-2-232049~232062	2023. 8. 24	本次共检互感器14组，14组互感器所检项目合格。	
424	GX-B1495/20-2-232063~232071	2023. 8. 24	本次共检互感器9组，9组互感器所检项目合格。	
425	GX-B1495/20-2-232072~232080	2023. 8. 24	本次共检互感器9组，9组互感器所检项目合格。	

426	GX-B1495/20-2-232081~232090	2023. 8. 24	本次共检互感器10组，10组互感器所检项目合格。	
427	GX-B1495/20-2-232118~232119	2023. 8. 24	本次共检互感器2组，2组互感器所检项目合格。	
428	GX-B1495/20-2-232120~232125	2023. 8. 24	本次共检互感器6组，6组互感器所检项目合格。	

429	GX-B1495/20-2-232167~232172	2023. 8. 24	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	 2023/07/08
430	GX-B1495/20-2-232173~232176	2023. 8. 24	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	 2023/07/09
431	GX-B1495/20-2-232177~232178	2023. 8. 24	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	 2023/07/17

432	GX-B1495/20-2-232179~232180	2023. 8. 24	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
433	GX-B1495/20-2-232181~232182	2023. 8. 24	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
434	GX-B1495/20-2-232183~232186	2023. 8. 24	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	

435	GX-B1495/20-2-232187~232192	2023. 8. 24	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	
436	GX-B1495/20-2-232193~232198	2023. 8. 24	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	
437	GX-B1495/20-2-232199~232201	2023. 8. 24	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	

438	GX-B1495/20-2-232202~232205	2023. 8. 24	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
439	GX-B1310/21-2-23163	2023. 8. 24	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
440	GX-B1310/21-2-23164	2023. 8. 24	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

441	GX-B1310/21-2-23165	2023. 8. 24	未发现超过 Φ 2mm当量直径的缺陷。	
442	GX-B1310/21-2-23166	2023. 8. 24	未发现超过 Φ 2mm当量直径的缺陷。	
456	GX-B1310/21-2-23167	2023. 8. 24	未发现超过 Φ 2mm当量直径的缺陷。	

457	GX-B1310/21-2-23168	2023. 8. 24	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
-----	---------------------	-------------	----------------------------------	---