

序号	报告编号	发布日期	结论	影像资料
279	GX-B1423/20-6-23805	2023/8/23	综合判定合格	
280	GX-B1423/20-6-23806	2023/8/23	综合判定合格	

281	GX-B1423/20-6-23807	2023/8/23	综合判定合格	
282	GX-B1423/20-6-23808	2023/8/23	综合判定合格	
283	GX-B1423/20-6-23809	2023/8/23	综合判定合格	

284	GX-B1423/20-6-23810	2023/8/23	综合判定合格	
285	GX-B1423/20-6-23811	2023/8/23	综合判定合格	
286	GX-B1423/20-6-23812	2023/8/23	综合判定合格	

287	GX-B1423/20-6-23813	2023/8/23	综合判定合格	
288	GX-B1423/20-6-23814	2023/8/23	综合判定合格	
289	GX-B1423/20-6-23815	2023/8/23	综合判定合格	

290	GX-B1423/20-6-23816	2023/8/23	综合判定合格	 A photograph showing two men standing in front of a green vehicle. The man on the left is wearing a red hard hat and a light blue short-sleeved shirt. The man on the right is wearing a white t-shirt. The vehicle has a license plate that reads "E6556". The date "2023 08 23" is visible in the bottom right corner of the photo.
291	GX-B1350/21-6-23046	2023/8/24	所检项目合格	 A photograph showing a worker wearing a red hard hat and a dark shirt kneeling on a grey floor. The worker is focused on a piece of equipment or a task on the floor. There are some tools and equipment scattered around. The date "2023 08 24" is visible in the bottom right corner of the photo.
292	GX-B1307/20-6-23042	2023. 8. 24	综合判定：合格。	 A photograph showing a worker wearing a red hard hat and a light blue shirt standing on a red step ladder. The worker is holding a white document or clipboard. The worker is positioned in front of a blue cabinet or door. The date "2023 08 04" is visible in the bottom right corner of the photo.

293	GX-B1307/20-6-23043	2023. 8. 24	综合判定：合格。	 <p>2023 08 04</p>
294	GX-B1307/20-6-23044	2023. 8. 24	综合判定：合格。	 <p>2023 08 04</p>
295	GX-B1307/20-6-23045	2023. 8. 24	综合判定：合格。	 <p>2023 08 04</p>

296	GX-B1307/20-6-23046	2023. 8. 24	综合判定：合格。	
297	GX-B1307/20-6-23047	2023. 8. 24	综合判定：合格。	
298	GX-B1307/20-6-23048	2023. 8. 24	综合判定：合格。	

299	GX-B1323/21-6-23240	2023. 8. 24	所检项目合格	
300	GX-B1548/20-6-23012	2023. 8. 25	所检项目合格。	
301	GX-B1548/20-6-23013	2023. 8. 25	所检项目合格。	

302	GX-B1548/20-6-23014	2023. 8. 25	所检项目合格。	
303	GX-B1548/20-6-23015	2023. 8. 25	所检项目合格。	
304	GX-B1548/20-6-23016	2023. 8. 25	所检项目合格。	

305	GX-B1548/20-6-23017	2023. 8. 25	所检项目合格。			
306	GX-B1548/20-6-23018	2023. 8. 25	所检项目合格。			
307	GX-B1548/20-6-23019	2023. 8. 25	所检项目合格。			

308	GX-B1548/20-6-23020	2023. 8. 25	所检项目合格。			
309	GX-B1548/20-6-23021	2023. 8. 25	所检项目合格。			
310	GX-B1548/20-6-23022	2023. 8. 25	所检项目合格。			

311	GX-B1548/20-6-23023	2023. 8. 25	所检项目合格。	
312	GX-B1534/20-6-23011	2023. 8. 24	所检项目合格。	
313	GX-B1534/20-6-23012	2023. 8. 24	所检项目合格。	

314	GX-B1534/20-6-23013	2023. 8. 24	所检项目合格。			
315	GX-B1534/20-6-23014	2023. 8. 24	所检项目合格。			
316	GX-B1534/20-6-23015	2023. 8. 24	所检项目合格。			

317	GX-B1534/20-6-23016	2023. 8. 24	所检项目合格。		 <p>2023 08 05</p>	
318	GX-B1534/20-6-23017	2023. 8. 24	所检项目合格。		 <p>2023 08 05</p>	
319	GX-B1534/20-6-23018	2023. 8. 24	所检项目合格。		 <p>2023 08 05</p>	

320	GX-B1534/20-6-23019	2023. 8. 24	所检项目合格。	 A worker wearing a red hard hat and a blue jacket is operating a piece of machinery, possibly a generator or a pump, outdoors. The worker is looking down at a document or control panel. The date stamp '2023 08 05' is visible in the bottom right corner of the photo.
321	GX-B1534/20-6-23020	2023. 8. 24	所检项目合格。	 A worker wearing a red hard hat and a dark jacket with reflective stripes is operating a piece of machinery in a dark, possibly underground, environment. The worker is looking towards the camera. The date stamp '2023 08 05' is visible in the bottom right corner of the photo.
322	GX-B1534/20-6-23021	2023. 8. 24	所检项目合格。	 A worker wearing a red hard hat and a dark jacket with reflective stripes is operating a piece of machinery in a dark environment. The worker is looking towards the camera. The date stamp '2023 08 05' is visible in the bottom right corner of the photo.

323	GX-B1323/21-6-23241~23242	2023/8/29	所检项目合格	 <p>2023 08 16</p>
324	GX-B1306/21-6-23014	2023/8/29	所检项目合格	 <p>2023 07 09</p>
325	GX-B1520/20-6-23094	2023/8/29	综合判定：合格	 <p>2023 08 29</p>

326	GX-B1598/21-6-23032	2023/8/29	<p>实测钢丝绳有效截面积损失百分比最大为2.43%，小于5%为正常。</p>			
327	GX-B1598/21-6-23033	2023/8/29	<p>实测钢丝绳有效截面积损失百分比最大为2.81%，小于5%为正常。</p>			
328	GX-B1598/21-6-23034	2023/8/29	<p>实测钢丝绳有效截面积损失百分比最大为2.55%，小于5%为正常。</p>			

329	GX-B1598/21-6-23035	2023/8/29	实测钢丝绳有效截面积损失百分比最大为2.50%，小于5%为正常。	
330	GX-B1598/21-6-23036	2023/8/29	实测钢丝绳有效截面积损失百分比最大为2.64%，小于5%为正常。	
331	GX-B1520/20-6-23095	2023/8/30	综合判定：合格	



































