

序号	报告编号	发布日期	结论	影像资料
1	GX-B1495/20-Y-231636~231637	2023年9月1日	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	 A photograph showing a worker in a white uniform and red helmet kneeling in a room filled with high-voltage switchgear cabinets. The worker is focused on a task, possibly inspecting or working on one of the cabinets. A yellow timestamp '2023/9/24' is visible in the bottom right corner of the image.
2	GX-B1415/22-Y-23014	2023年9月4日	综合判定：合格。	 A photograph showing two workers in orange uniforms and red helmets in a dark environment, likely a substation or control room. One worker is holding a yellow tool or component, while the other is looking at a mobile device. The scene is illuminated by overhead lights. A yellow timestamp '2023/8/24' is visible in the bottom right corner of the image.

3	GX-B1557/22-Y-23023	2023年9月1日	所检项目合格。	
4	GX-B1557/22-Y-23024	2023年9月1日	所检项目合格。	

5	GX-B1557/22-Y-23025	2023年9月1日	所检项目合格。	
6	GX-B1557/22-Y-23026	2023年9月1日	所检项目合格。	

7	GX-B1556/22-Y-23005	2023年9月1日	所检项目合格。	
8	GX-B1557/22-Y-23027	2023年9月1日	所检项目合格。	

9	GX-B1557/22-Y-23028	2023年9月1日	所检项目合格。	
10	GX-B1557/22-Y-23029	2023年9月1日	所检项目合格。	

11	GX-B1557/22-Y-23036	2023年9月1日	所检项目合格。	
12	GX-B1557/22-Y-23037	2023年9月1日	所检项目合格。	

13	GX-B1557/22-Y-23038	2023年9月1日	所检项目合格。	
14	GX-B1557/22-Y-23039	2023年9月1日	所检项目合格。	

15	GX-B1310/21-Y-23139	2023年9月3日	符合标准要求。	
16	GX-B1310/21-Y-23140	2023年9月3日	符合标准要求。	

17	GX-B1428/21-Y-23140	2023年9月3日	无缺陷迹痕显示	
18	GX-B1310/21-Y-23141	2023年9月3日	符合标准要求。	

19	GX-B1428/21-Y-23141	2023年9月3日	无缺陷迹痕显示	 <p>2023/8/24</p>
20	GX-B1312/20-Y-23415~23416	2023年9月6日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2023/8/24</p>

21	GX-B1539/20-Y-23230	2023年9月7日	所检项目合格。	
22	GX-B1539/20-Y-23231	2023年9月7日	所检项目合格。	

23	GX-B1521/20-Y-23544	2023年9月7日	所检项目合格。	
24	GX-B1416/22-Y-23082	2023年9月7日	综合判定：合格。	

25	GX-B1416/22-Y-23083	2023年9月7日	综合判定：合格。	
----	---------------------	-----------	----------	---