

序号	报告编号	发布日期	结论	影像资料
43	GX-B1423/20-Y-234968	2023年9月18日	综合判定：合格	
44	GX-B1423/20-Y-234969	2023年9月18日	综合判定：合格	
45	GX-B1423/20-Y-234970	2023年9月18日	综合判定：合格	

46	GX-B1423/20-Y-234971	2023年9月18日	综合判定：合格	
47	GX-B1423/20-Y-234972	2023年9月18日	综合判定：合格	
48	GX-B1423/20-Y-234973	2023年9月18日	综合判定：合格	

49	GX-B1423/20-Y-234974	2023年9月18日	综合判定：合格	
50	GX-B1423/20-Y-234975	2023年9月18日	综合判定：合格	
51	GX-B1423/20-Y-234976	2023年9月18日	综合判定：合格	

52	GX-B1423/20-Y-234977	2023年9月18日	综合判定：合格	
53	GX-B1423/20-Y-234978	2023年9月18日	综合判定：合格	
54	GX-B1423/20-Y-234979	2023年9月18日	综合判定：合格	

55	GX-B1423/20-Y-234980	2023年9月18日	综合判定：合格	 A photograph of a yellow truck with the number A102 on its front. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023-9-18' is visible in the bottom right corner of the image.
56	GX-B1423/20-Y-234981	2023年9月18日	综合判定：合格	 A photograph of a yellow truck with the number A95 on its front. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023-9-18' is visible in the bottom right corner of the image.
57	GX-B1423/20-Y-234982	2023年9月18日	综合判定：合格	 A photograph of a yellow truck with the number A98 on its front. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023-9-18' is visible in the bottom right corner of the image.

58	GX-B1423/20-Y-234983	2023年9月18日	综合判定：合格	 A yellow truck with 'A105' on the front bumper. Two workers in hard hats and work clothes stand in front of the truck. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.
59	GX-B1423/20-Y-234984	2023年9月18日	综合判定：合格	 A yellow truck with 'A111' on the front bumper. Two workers in hard hats and work clothes stand in front of the truck. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.
60	GX-B1423/20-Y-234985	2023年9月18日	综合判定：合格	 A yellow truck with 'A90' on the side of the body. Two workers in hard hats and work clothes stand in front of the truck. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.

61	GX-B1423/20-Y-234986	2023年9月18日	综合判定：合格	
62	GX-B1423/20-Y-234987	2023年9月18日	综合判定：合格	
63	GX-B1423/20-Y-234988	2023年9月18日	综合判定：合格	

64	GX-B1423/20-Y-234989	2023年9月18日	综合判定：合格	
65	GX-B1423/20-Y-234990	2023年9月18日	综合判定：合格	
66	GX-B1423/20-Y-234991	2023年9月18日	综合判定：合格	

67	GX-B1423/20-Y-234992	2023年9月18日	综合判定：合格	 A yellow dump truck with the identification number 'A89' on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023.9.20' is visible in the bottom right corner of the photo.
68	GX-B1423/20-Y-234993	2023年9月18日	综合判定：合格	 A yellow dump truck parked on a dirt surface. Two workers in safety gear are standing in front of it. A yellow timestamp '2023.9.20' is visible in the bottom right corner of the photo.
69	GX-B1423/20-Y-234994	2023年9月18日	综合判定：合格	 A yellow dump truck with the identification number 'A109' on its side. A worker in safety gear is standing in front of the truck. A yellow timestamp '2023.9.20' is visible in the bottom right corner of the photo.

70	GX-B1423/20-Y-234995	2023年9月18日	综合判定：合格	
71	GX-B1423/20-Y-234996	2023年9月18日	综合判定：合格	
72	GX-B1423/20-Y-234997	2023年9月18日	综合判定：合格	

73	GX-B1423/20-Y-234998	2023年9月18日	综合判定：合格	
74	GX-B1423/20-Y-234958	2023年9月18日	综合判定：合格	
75	GX-B1423/20-Y-234959	2023年9月18日	综合判定：合格	

76	GX-B1423/20-Y-234960	2023年9月18日	综合判定：合格	 A photograph of an orange truck with a dump body. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/9/17' is visible in the bottom right corner.
77	GX-B1423/20-Y-234961	2023年9月18日	综合判定：合格	 A photograph of an orange truck with a dump body. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/9/17' is visible in the bottom right corner.
78	GX-B1423/20-Y-234962	2023年9月18日	综合判定：合格	 A photograph of an orange truck with a dump body. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/9/17' is visible in the bottom right corner.

79	GX-B1423/20-Y-234963	2023年9月18日	综合判定：合格	 A yellow truck with a black canopy is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate area shows '139'. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.
80	GX-B1423/20-Y-234964	2023年9月18日	综合判定：合格	 An orange truck with a black canopy is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate area shows '1332'. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.
81	GX-B1423/20-Y-234965	2023年9月18日	综合判定：合格	 An orange truck with a black canopy is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate area shows '1330'. A yellow timestamp '2023/9/18' is visible in the bottom right corner of the photo.

82	GX-B1423/20-Y-234966	2023年9月18日	综合判定：合格	
83	GX-B1423/20-Y-234967	2023年9月18日	综合判定：合格	
84	GX-B1423/20-Y-234928	2023年9月18日	综合判定：合格	

85	GX-B1423/20-Y-234929	2023年9月18日	综合判定：合格	
86	GX-B1423/20-Y-234930	2023年9月18日	综合判定：合格	
87	GX-B1423/20-Y-234931	2023年9月18日	综合判定：合格	

88	GX-B1423/20-Y-234932	2023年9月18日	综合判定：合格	
89	GX-B1423/20-Y-234933	2023年9月18日	综合判定：合格	
90	GX-B1423/20-Y-234934	2023年9月18日	综合判定：合格	

91	GX-B1423/20-Y-234935	2023年9月18日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has 'Y6S1T' visible on its side.
92	GX-B1423/20-Y-234936	2023年9月18日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has 'Y6S1T' visible on its side.
93	GX-B1423/20-Y-234937	2023年9月18日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has 'Y6S1T' visible on its side.

94	GX-B1423/20-Y-234938	2023年9月18日	综合判定：合格	
95	GX-B1423/20-Y-234939	2023年9月18日	综合判定：合格	
96	GX-B1423/20-Y-234940	2023年9月18日	综合判定：合格	

97	GX-B1423/20-Y-234941	2023年9月18日	综合判定：合格	
98	GX-B1423/20-Y-234942	2023年9月18日	综合判定：合格	
99	GX-B1423/20-Y-234943	2023年9月18日	综合判定：合格	

100	GX-B1423/20-Y-234944	2023年9月18日	综合判定：合格	
101	GX-B1423/20-Y-234945	2023年9月18日	综合判定：合格	
102	GX-B1423/20-Y-234946	2023年9月18日	综合判定：合格	

103	GX-B1423/20-Y-235320	2023年9月18日	综合判定：合格	
104	GX-B1423/20-Y-235321	2023年9月18日	综合判定：合格	
105	GX-B1423/20-Y-235322	2023年9月18日	综合判定：合格	

106	GX-B1423/20-Y-235323	2023年9月18日	综合判定：合格	
107	GX-B1415/22-Y-23015	2023年9月18日	综合判定：合格	
108	GX-B1415/22-Y-23016	2023年9月18日	综合判定：合格	

109	GX-B1328/20-Y-23108	2023年9月18日	本次共检绝缘手套68只，68只绝缘手套合格。	
110	GX-B1328/20-Y-23109	2023年9月18日	本次共检绝缘鞋54只，54只绝缘鞋合格。	
111	GX-B1328/20-Y-23110	2023年9月18日	本次共检验电器6支，6支验电器合格。	

112	GX-B1328/20-Y-23111	2023年9月18日	本次共检便携式接地和接地短路装置3套，3套便携式接地和接地短路装置合格。	
113	GX-B1423/20-Y-234720	2023年9月18日	综合判定：合格	
114	GX-B1423/20-Y-234721	2023年9月18日	综合判定：合格	

115	GX-B1423/20-Y-234722	2023年9月18日	综合判定：合格	
116	GX-B1423/20-Y-234723	2023年9月18日	综合判定：合格	
117	GX-B1423/20-Y-234724	2023年9月18日	综合判定：合格	

118	GX-B1423/20-Y-234725	2023年9月18日	综合判定：合格	
119	GX-B1423/20-Y-234726	2023年9月18日	综合判定：合格	
120	GX-B1423/20-Y-234727	2023年9月18日	综合判定：合格	

121	GX-B1423/20-Y-234728	2023年9月18日	综合判定：合格	
122	GX-B1423/20-Y-234729	2023年9月18日	综合判定：合格	
123	GX-B1423/20-Y-234730	2023年9月18日	综合判定：合格	

124	GX-B1423/20-Y-234731	2023年9月18日	综合判定：合格	
125	GX-B1423/20-Y-234732	2023年9月18日	综合判定：合格	
126	GX-B1423/20-Y-234733	2023年9月18日	综合判定：合格	

127	GX-B1423/20-Y-234734	2023年9月18日	综合判定：合格	
128	GX-B1423/20-Y-234735	2023年9月18日	综合判定：合格	
129	GX-B1423/20-Y-234736	2023年9月18日	综合判定：合格	

130	GX-B1423/20-Y-234737	2023年9月18日	综合判定：合格	
131	GX-B1423/20-Y-234738	2023年9月18日	综合判定：合格	
132	GX-B1423/20-Y-234739	2023年9月18日	综合判定：合格	

133	GX-B1423/20-Y-234740	2023年9月18日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective with its bed lowered. Two workers in white uniforms and hard hats stand in front of the truck. A yellow timestamp '2023 9 18' is visible in the bottom right corner of the image.
134	GX-B1423/20-Y-234741	2023年9月18日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective with its bed raised. Two workers in white uniforms and hard hats stand in front of the truck. A yellow timestamp '2023 9 18' is visible in the bottom right corner of the image.
135	GX-B1423/20-Y-234742	2023年9月18日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective with its bed raised. Two workers in white uniforms and hard hats stand in front of the truck. A yellow timestamp '2023 9 18' is visible in the bottom right corner of the image.

136	GX-B1423/20-Y-234743	2023年9月18日	综合判定：合格	
137	GX-B1423/20-Y-234744	2023年9月18日	综合判定：合格	
138	GX-B1423/20-Y-234745	2023年9月18日	综合判定：合格	

139	GX-B1423/20-Y-234746	2023年9月18日	综合判定：合格	
140	GX-B1423/20-Y-234747	2023年9月18日	综合判定：合格	
141	GX-B1423/20-Y-234748	2023年9月18日	综合判定：合格	
142	GX-B1423/20-Y-234749	2023年9月18日	综合判定：合格	

143	GX-B1423/20-Y-234750	2023年9月18日	综合判定：合格	
144	GX-B1423/20-Y-234751	2023年9月18日	综合判定：合格	
145	GX-B1423/20-Y-234752	2023年9月18日	综合判定：合格	
146	GX-B1423/20-Y-234753	2023年9月18日	综合判定：合格	

147	GX-B1423/20-Y-234754	2023年9月18日	综合判定：合格	
148	GX-B1423/20-Y-234755	2023年9月18日	综合判定：合格	
149	GX-B1423/20-Y-234756	2023年9月18日	综合判定：合格	
150	GX-B1423/20-Y-234757	2023年9月18日	综合判定：合格	

151	GX-B1423/20-Y-234758	2023年9月18日	综合判定：合格	
152	GX-B1423/20-Y-234759	2023年9月18日	综合判定：合格	
153	GX-B1423/20-Y-234760	2023年9月18日	综合判定：合格	