

序号	报告编号	发布日期	结论	影像资料
154	GX-B1521/20-Y-23535	2023年9月19日	所检项目合格。	
155	GX-B1521/20-Y-23536	2023年9月19日	所检项目合格。	

156	GX-B1521/20-Y-23451	2023年9月19日	所检项目合格。	
157	GX-B1521/20-Y-23452	2023年9月19日	所检项目合格。	

158	GX-B1521/20-Y-23453	2023年9月19日	所检项目合格。	
159	GX-B1521/20-Y-23454	2023年9月19日	所检项目合格。	

160	GX-B1521/20-Y-23455	2023年9月19日	所检项目合格。	
161	GX-B1521/20-Y-23456	2023年9月19日	所检项目合格。	

162	GX-B1521/20-Y-23457	2023年9月19日	所检项目合格。	
163	GX-B1521/20-Y-23458	2023年9月19日	所检项目合格。	

164	GX-B1423/20-Y-235325	2023年9月20日	综合判定：合格	 A yellow dump truck with the number 37 on its side, parked on a dirt surface. Two workers in blue and white uniforms stand in front of it. A date stamp '2023/9/15' is visible in the bottom right corner of the photo.
165	GX-B1423/20-Y-235326	2023年9月20日	综合判定：合格	 A yellow dump truck with the number 43 on its side, parked on a dirt surface. Two workers in blue and white uniforms stand in front of it. A date stamp '2023/9/15' is visible in the bottom right corner of the photo.

166	GX-B1563/21-Y-23028	2023年9月19日	所检项目合格。	
167	GX-B1563/21-Y-23029	2023年9月19日	所检项目合格。	

168	GX-B1563/21-Y-23030	2023年9月19日	所检项目合格。	 <p>A photograph showing a yellow truck with a white tank on top. Two workers in safety gear (one in dark clothing and a blue helmet, the other in light clothing and a red helmet) are standing in front of the truck. The date stamp '2023/8/17' is visible in the bottom right corner of the image.</p>
169	GX-B1539/22-Y-23229	2023年9月19日	所检项目合格。	 <p>A photograph showing a yellow wheel loader with 'LUGONG' and '855N' visible on its side. Two workers in safety gear (one in dark clothing and a blue helmet, the other in light clothing and a red helmet) are standing in front of the loader. The date stamp '2023/8/18' is visible in the bottom right corner of the image.</p>

170	GX-B1539/22-Y-23204	2023年9月19日	所检项目合格。	
171	GX-B1539/22-Y-23205	2023年9月19日	所检项目合格。	

172	GX-B1539/22-Y-23196	2023年9月19日	所检项目合格。	
173	GX-B1539/22-Y-23197	2023年9月19日	所检项目合格。	

174	GX-B1539/22-Y-23198	2023年9月19日	所检项目合格。	
175	GX-B1539/22-Y-23199	2023年9月19日	所检项目合格。	

176	GX-B1539/22-Y-23200	2023年9月19日	所检项目合格。	
177	GX-B1539/22-Y-23201	2023年9月19日	所检项目合格。	

178	GX-B1539/22-Y-23202	2023年9月19日	所检项目合格。	
179	GX-B1539/22-Y-23203	2023年9月19日	所检项目合格。	

180	GX-B1563/21-Y-23027	2023年9月20日	所检项目合格。	
181	GX-B1539/22-Y-23206	2023年9月20日	所检项目合格。	

182	GX-B1539/22-Y-23207	2023年9月20日	所检项目合格。	
183	GX-B1539/22-Y-23208	2023年9月20日	所检项目合格。	

184	GX-B1539/22-Y-23209	2023年9月20日	所检项目合格。	
185	GX-B1539/22-Y-23210	2023年9月20日	所检项目合格。	

186	GX-B1539/22-Y-23211	2023年9月20日	所检项目合格。	
187	GX-B1521/20-Y-23465	2023年9月20日	所检项目合格。	

188	GX-B1521/20-Y-23466	2023年9月20日	所检项目合格。	
189	GX-B1521/20-Y-23467	2023年9月20日	所检项目合格。	

190	GX-B1521/20-Y-23468	2023年9月20日	所检项目合格。	
191	GX-B1521/20-Y-23469	2023年9月20日	所检项目合格。	

192	GX-B1521/20-Y-23470	2023年9月20日	所检项目合格。	
193	GX-B1521/20-Y-23471	2023年9月20日	所检项目合格。	

194	GX-B1521/20-Y-23472	2023年9月20日	所检项目合格。	 A yellow tracked excavator with a large bucket, parked on a dirt surface. A person is standing near the machine. The date stamp in the bottom right corner of the photo is 2023/8/22.
195	GX-B1521/20-Y-23473	2023年9月20日	所检项目合格。	 A yellow tracked excavator with a large bucket, parked on a dirt surface. A person is standing near the machine. The date stamp in the bottom right corner of the photo is 2023/8/24.

196	GX-B1521/20-Y-23474	2023年9月20日	所检项目合格。	
197	GX-B1521/20-Y-23475	2023年9月20日	所检项目合格。	

198	GX-B1521/20-Y-23476	2023年9月20日	所检项目合格。	
199	GX-B1521/20-Y-23477	2023年9月20日	所检项目合格。	

200	GX-B1521/20-Y-23478	2023年9月20日	所检项目合格。	
201	GX-B1521/20-Y-23479	2023年9月20日	所检项目合格。	

202	GX-B1521/20-Y-23480	2023年9月20日	所检项目合格。	 <p>A yellow XCMG crawler excavator is shown in a desert environment. The excavator is positioned on a sandy surface, and its arm is extended. The background shows a clear blue sky and distant hills. A yellow timestamp '2023/8/24' is visible in the bottom right corner of the image.</p>
203	GX-B1521/20-Y-23481	2023年9月20日	所检项目合格。	 <p>A yellow XCMG crawler excavator is shown at a construction site. The excavator is positioned on a dirt surface, and its arm is extended. The background shows a clear blue sky and a building under construction. A yellow timestamp '2023/8/24' is visible in the bottom right corner of the image.</p>

204	GX-B1521/20-Y-23482	2023年9月20日	所检项目合格。	
205	GX-B1521/20-Y-23483	2023年9月20日	所检项目合格。	

206	GX-B1521/20-Y-23484	2023年9月20日	所检项目合格。	
207	GX-B1521/20-Y-23485	2023年9月20日	所检项目合格。	

208	GX-B1521/20-Y-23486	2023年9月20日	所检项目合格。	
209	GX-B1521/20-Y-23487	2023年9月20日	所检项目合格。	

210	GX-B1521/20-Y-23488	2023年9月20日	所检项目合格。	 A yellow excavator with "CMG" branding is shown at a construction site. The excavator's arm is raised, and its bucket is positioned over a pile of earth. A person in a white uniform and a red hard hat stands next to the excavator. The background shows a clear blue sky and a dirt area. A yellow timestamp "2023/8/24" is visible in the bottom right corner of the image.
211	GX-B1521/20-Y-23489	2023年9月20日	所检项目合格。	 A yellow excavator with "CMG" branding is shown at a construction site. The excavator's arm is raised, and its bucket is positioned over a pile of earth. A person in a white uniform and a red hard hat stands next to the excavator. The background shows a clear blue sky and a dirt area. A yellow timestamp "2023/8/25" is visible in the bottom right corner of the image.

212	GX-B1521/20-Y-23490	2023年9月20日	所检项目合格。	 A yellow HCMG excavator is shown at a construction site. The excavator is positioned on a dirt mound, and its bucket is lowered. A person in a white shirt and a red hard hat stands next to the excavator. The background shows a clear blue sky and a dirt embankment. A yellow timestamp '2023/8/25' is visible in the bottom right corner of the photo.
213	GX-B1521/20-Y-23491	2023年9月20日	所检项目合格。	 A yellow HCMG excavator is shown at a construction site. The excavator is positioned on a dirt mound, and its bucket is raised. A person in a blue shirt and a red hard hat stands next to the excavator. The background shows a clear blue sky and a dirt embankment. A yellow timestamp '2023/8/25' is visible in the bottom right corner of the photo.

214	GX-B1521/20-Y-23459	2023年9月20日	所检项目合格。	
215	GX-B1521/20-Y-23460	2023年9月20日	所检项目合格。	

216	GX-B1521/20-Y-23461	2023年9月20日	所检项目合格。	
217	GX-B1521/20-Y-23462	2023年9月20日	所检项目合格。	

218	GX-B1521/20-Y-23463	2023年9月20日	所检项目合格。	 A photograph of a red Hitachi excavator at a construction site. The excavator is positioned on a dirt surface, and its arm is extended. Two workers in safety gear are visible near the machine. The background shows a clear blue sky with some clouds. A yellow timestamp '2023/8/21' is located in the bottom right corner of the image.
219	GX-B1521/20-Y-23464	2023年9月20日	所检项目合格。	 A photograph of a red Hitachi excavator at a construction site. The excavator is positioned on a dirt surface, and its arm is extended. Two workers in safety gear are visible near the machine. The background shows a clear blue sky with some clouds. A yellow timestamp '2023/8/21' is located in the bottom right corner of the image.