


序号	报告编号	发布日期	结论	影像资料
40	GX-B1377/22-F-23274	2023. 9. 19	所检项目合格	 A photograph showing two female technicians in white lab coats and face masks working in a laboratory. They are positioned around a large, dark piece of equipment, possibly a detector or spectrometer. One technician is looking at the equipment while the other is looking down. The background shows a window with light-colored curtains and a desk with various items. A small timestamp '2023/9/15' is visible in the bottom right corner of the image.
41	GX-B1377/22-F-23275	2023. 9. 19	所检项目合格	 A photograph showing two female technicians in white lab coats and face masks working in a laboratory. They are positioned around a large, dark piece of equipment, similar to the one in the previous image. One technician is looking at the equipment while the other is looking down. The background shows a window with light-colored curtains and a desk with various items. A small timestamp '2023/9/15' is visible in the bottom right corner of the image.

42	GX-B1377/22-F-23276	2023. 9. 19	所检项目合格	 A photograph showing two female lab technicians in white lab coats and face masks. They are standing at a lab bench equipped with a biosafety cabinet. One technician is looking at a document while the other is working with equipment. The background shows a clean laboratory environment with white walls and a door.
43	GX-B1377/22-F-23277	2023. 9. 19	所检项目合格	 A photograph showing two female lab technicians in white lab coats and face masks. They are standing at a lab bench with a biosafety cabinet. One technician is looking down at something on the bench, while the other stands beside her. The setting is a laboratory with white walls and a door in the background.
44	GX-B1377/22-F-23272	2023. 9. 19	所检项目合格	 A photograph showing two female lab technicians in white lab coats and face masks. They are working at a lab bench. One technician is looking at a computer monitor, while the other is looking down at something on the bench. There are various lab equipment and glassware on the bench. A date stamp '2023/9/12' is visible in the bottom right corner of the photo.

45	GX-B1377/22-F-23273	2023. 9. 19	所检项目合格	
46	GX-B1377/22-F-23268	9. 19	所检项目合格	
47	GX-B1377/22-F-23269	9. 19	所检项目合格	

48	GX-B1377/22-F-23270	9.19	所检项目合格	
49	GX-B1377/22-F-23271	9.19	所检项目合格	
50	GX-B1378/22-F-23202	9.19	所检项目合格	

51	GX-B1489/21-F- 23084	2023. 9. 19	所检项目合格	 A photograph showing two individuals in a laboratory. One person, wearing a light blue lab coat and a face mask, is pointing at a computer monitor. The other person, wearing a grey lab coat, is looking at the monitor. The monitor displays some data. The date '2023/9/19' is visible in the bottom right corner of the photo.
52	GX-B1378/22-F-23207~F-23210	2023. 9. 26	所检项目合格	 A photograph showing two individuals in a laboratory. One person, wearing a light blue lab coat and a face mask, is pointing at a computer monitor. The other person, wearing a grey lab coat, is looking at the monitor. The monitor displays some data. The date '2023/9/19' is visible in the bottom right corner of the photo.
53	GX-B1378/22-F-23211~F-23214	2023. 9. 26	所检项目合格	 A photograph showing two individuals in a laboratory. One person, wearing a light blue lab coat and a face mask, is pointing at a computer monitor. The other person, wearing a grey lab coat, is looking at the monitor. The monitor displays some data. The date '2023/9/19' is visible in the bottom right corner of the photo.

54	GX-B1378/22-F-23203~F-23205	2023. 9. 26	所检项目合格	
55	GX-B1377/22-F-23281	2023. 9. 26	所检项目合格	
56	GX-B1377/22-F-23282	2023. 9. 26	所检项目合格	

57	GX-B1377/22-F-23278	9.26	所检项目合格	
58	GX-B1377/22-F-23279	9.26	所检项目合格	
59	GX-B1377/22-F-23280	9.26	所检项目合格	

60	GX-B1492/21-F-23022	2023. 9. 26	所检项目合格	
61	GX-B1492/21-F-23018~F-23021	2023. 9. 26	所检项目合格	
62	GX-B1601/22-B- 230671~230672	2023. 9. 25	所检项目合格	