

序号	报告编号	发布日期	结论	影像资料
16	GX-B1548/20-3-23032	2023年10月11日	所检项目合格。	
17	GX-B1548/20-3-23033	2023年10月11日	所检项目合格。	

18	GX-B1548/20-3-23031	2023年10月11日	所检项目合格。	
19	GX-B308/21-3-23024	2023年10月9日	所检项目合格	
20	GX-B1424/20-3-23021	2023年10月13日	依据NB/T 10176-2019单轨吊车综合判定合格。	


21	GX-B1424/20-3-23037	2023年10月13日	依据NB/T 10176-2019单轨吊车综合判定合格。	
22	GX-B1303/21-3-23010	2023年10月13日	综合判定：合格。	
23	GX-B1303/21-3-23011	2023年10月13日	综合判定：合格。	

24	GX-B1305/21-3-23011	2023年10月13日	综合判定：合格。	
25	GX-B1305/21-3-23012	2023年10月13日	综合判定：合格。	
26	GX-B1307/20-3-23051	2023年10月13日	综合判定：合格。	

27	GX-B1307/20-3-23052	2023年10月13日	综合判定：合格。	
28	GX-B1307/20-3-23053	2023年10月13日	综合判定：合格。	
29	GX-B1307/20-3-23054	2023年10月13日	综合判定：合格。	

30	GX-B1307/20-3-23055	2023年10月13日	综合判定：合格。	
31	GX-B1307/20-3-23056	2023年10月13日	综合判定：合格。	
32	GX-B1307/20-3-23057	2023年10月13日	综合判定：合格。	

33	GX-B1307/20-3-23058	2023年10月13日	综合判定：合格。	
34	GX-B1307/20-3-23059	2023年10月13日	综合判定：合格。	
35	GX-B1307/20-3-23060	2023年10月13日	综合判定：合格。	

36	GX-B1307/20-3-23061	2023年10月13日	综合判定：合格。	
37	GX-B1307/20-3-23062	2023年10月13日	综合判定：合格。	
38	GX-B1307/20-3-23063	2023年10月13日	综合判定：合格。	

39	GX-B1307/20-3-23064	2023年10月13日	综合判定：合格。	 A worker wearing a red hard hat and safety glasses is using a handheld electronic device to inspect a piece of machinery. The date stamp in the bottom right corner of the photo is 2023.10.09.
40	GX-B1307/20-3-23065	2023年10月13日	综合判定：合格。	 A worker in a red hard hat is inspecting the interior of a large industrial cabinet. A laptop and other equipment are on the floor nearby. The date stamp in the bottom right corner is 2023.10.09.
41	GX-B1312/20-3-23639	2023年10月16日	所检项目合格。	 Two workers in red hard hats are standing next to a large industrial transformer or generator. The date stamp in the bottom right corner is 2023.06.28.

42	GX-B1312/20-3-23640	2023年10月16日	所检项目合格。	
43	GX-B1312/20-3-23641	2023年10月16日	所检项目合格。	
44	GX-B1305/21-3-23010	2023年10月17日	综合判定：合格。	

45	GX-B1547/20-3-23031~23033	2023. 10. 16	所检项目合格	
46	GX-B1547/20-3-23034~23036	2023. 10. 16	所检项目合格	
47	GX-B1547/20-3-23037~23039	2023. 10. 16	所检项目合格	

48	GX-B1451/20-3-23349-23380	2023年10月16日	本次共检电流互感器 32只，32只所检项目合格。 。	 A worker in a red uniform and helmet is working on electrical equipment. The date stamp '2023.09.17' is visible in the bottom right corner of the photo.
49	GX-B1451/20-3-23429-23456	2023年10月16日	本次共检电流互感器 28只，28只所检项目合格。 。	 A worker in a red uniform and helmet is working on electrical equipment. The date stamp '2023.09.19' is visible in the bottom right corner of the photo.
50	GX-B1451/20-3-23391-23428	2023年10月16日	本次共检电流互感器 38只，38只所检项目合格。 。	 A worker in a red uniform and helmet is working on electrical equipment. The date stamp '2023.09.19' is visible in the bottom right corner of the photo.

51	GX-B1328/20-3-23238	2023年10月17日	本次共检绝缘手套2只， 2只绝缘手套合格。	
52	GX-B1328/20-3-23239	2023年10月17日	本次共检绝缘鞋2只，2 只绝缘鞋合格。	
53	GX-B1328/20-3-23230	2023年10月17日	本次共检绝缘手套4只， 4只绝缘手套合格。	
54	GX-B1328/20-3-23231	2023年10月17日	本次共检绝缘鞋4只，4 只绝缘鞋合格。	
55	GX-B1328/20-3-23236	2023年10月17日	本次共检绝缘手套6只， 6只绝缘手套合格。	

56	GX-B1328/20-3-23237	2023年10月17日	本次共检绝缘鞋6只，6只绝缘鞋合格。	
57	GX-B1339/21-3-23015	2023年10月17日	所检项目合格	
58	GX-B1339/21-3-23016	2023年10月17日	所检项目合格	

59	GX-B1339/21-3-23017	2023年10月17日	所检项目合格	
60	GX-B1339/21-3-23018	2023年10月17日	所检项目合格	
61	GX-B1339/21-3-23019	2023年10月17日	所检项目合格	

62	GX-B1339/21-3-23020	2023年10月17日	所检项目合格	
63	GX-B1339/21-3-23021	2023年10月17日	所检项目合格	
64	GX-B1339/21-3-23022	2023年10月17日	所检项目合格	

65	GX-B1339/21-3-23023	2023年10月17日	所检项目合格		
66	GX-B1339/21-3-23024	2023年10月17日	所检项目合格		
67	GX-B1339/21-3-23025	2023年10月17日	所检项目合格		

68	GX-B1339/21-3-23026	2023年10月17日	所检项目合格	
69	GX-B1339/21-3-23027	2023年10月17日	所检项目合格	
70	GX-B1339/21-3-23028	2023年10月17日	所检项目合格	

71	GX-B1339/21-3-23029	2023年10月17日	所检项目合格	 A worker wearing a red hard hat, safety glasses, and a green shirt with a white scarf is inspecting a large blue industrial machine. The machine has a prominent red cylindrical component. The worker is leaning forward, looking at the machine. A yellow timestamp '2023.09.12' is visible in the bottom right corner of the photo.
72	GX-B1339/21-3-23030	2023年10月17日	所检项目合格	 A worker wearing a red hard hat, safety glasses, and a green shirt with a white scarf is inspecting a large blue industrial machine. The machine has a prominent red cylindrical component. The worker is leaning forward, looking at the machine. A yellow timestamp '2023.09.12' is visible in the bottom right corner of the photo.
73	GX-B1339/21-3-23031	2023年10月17日	所检项目合格	 A worker wearing a red hard hat, safety glasses, and a green shirt with a white scarf is inspecting a large blue industrial machine. The machine has a prominent red cylindrical component. The worker is standing and looking at the machine. A yellow timestamp '2023.09.12' is visible in the bottom right corner of the photo.

74	GX-B1350/21-3-23026	2023年10月19日	本次共检验接地装置10处，10处所检项目合格。		
75	GX-B1350/21-3-23027	2023年10月19日	本次共检验接地装置6处，6处所检项目合格。		
76	GX-B1548/20-3-23034	2023年10月19日	所检项目合格。		

77	GX-B1548/20-3-23035	2023年10月19日	所检项目合格。	
78	GX-B1305/21-3-23009	2023年10月20日	综合判定：合格。	