

序号	报告编号	发布日期	结论	影像资料
6	GX-B1501/21-F-23040	2023. 10. 13	煤尘具有爆炸性	
7	GX-B1502/21-F-23040	2023. 10. 13	II类自燃	
8	GX-B1502/21-F-23041	2023. 10. 13	II类, 自燃	
9	GX-B1502/21-F-23042	2023. 10. 13	II类, 自燃	
10	GX-B1502/21-F-23043	2023. 10. 13	II类, 自燃	
11	GX-B1377/22-F-23289	2023. 10. 18	所检项目合格	

12	GX-B1377/22-F-23290	2023. 10. 18	所检项目合格	 A photograph showing two individuals in a laboratory. One person, wearing a grey lab coat and a face mask, is operating a piece of equipment with a large screen. Another person, wearing a white lab coat and a face mask, stands beside them, observing. The equipment is on a green table. A timestamp '2023/10/12' is visible in the bottom right corner of the image.
13	GX-B1377/22-F-23291	2023. 10. 18	所检项目合格	 A photograph of a person in a white lab coat and a face mask, viewed from the side, operating a piece of laboratory equipment. The equipment is on a green table. A timestamp '2023/10/12' is visible in the bottom right corner of the image.
14	GX-B1377/22-F-23292	2023. 10. 18	所检项目合格	 A photograph showing two individuals in a laboratory. One person, wearing a grey lab coat and a face mask, is operating a piece of equipment. Another person, wearing a white lab coat and a face mask, stands beside them, observing. The equipment is on a green table. A timestamp '2023/10/12' is visible in the bottom right corner of the image.

15	GX-B1378/22-F-23232	2023.10.18	所检项目合格	
16	GX-B1378/22-F-23222~F-23223	2023.10.18	所检项目合格	

17	GX-B1378/22-F-23224	2023.10.18	所检项目合格	 <p>2023/10/7</p>
18	GX-B1489/21-F- 23086	2023.10.18	所检项目合格	 <p>2023/10/8</p>

19	GX-B1492/21-F-23023	2023. 10. 18	所检项目合格	
20	GX-B1377/22-F-23284	2023. 10. 18	所检项目合格	

21	GX-B1377/22-F-23285	2023. 10. 18	所检项目合格	
22	GX-B1377/22-F-23286	2023. 10. 18	所检项目合格	

23	GX-B1377/22-F-23287	2023. 10. 18	所检项目合格	 A photograph showing two female laboratory technicians in white lab coats and face masks. They are standing at a workstation with a green surface. One technician is looking at a computer monitor while the other is looking down at something on the table. There are various pieces of laboratory equipment, including a large grey machine on the left and a smaller device on the right. A date stamp '2023/10/9' is visible in the bottom right corner of the image.
24	GX-B1377/22-F-23288	2023. 10. 18	所检项目合格	 A photograph showing two female laboratory technicians in white lab coats and face masks. They are standing at a workstation with a green surface. One technician is looking at a large white container while the other is looking down at something on the table. There are various pieces of laboratory equipment, including a large grey machine on the left and a smaller device on the right. A date stamp '2023/10/9' is visible in the bottom right corner of the image.

25	GX-B1378/22-F-23225~F-23231	2023. 10. 18	所检项目合格	
----	-----------------------------	--------------	--------	---