


序号	报告编号	发布日期	结论	影像资料
76	GX-B1374/22-B-230790~230798	2023.10.23	所检项目合格	
77	GX-B1465/22-B-23156~23157	2023.10.23	所检项目合格	
78	GX-B1373/21-B-23377~23383	2023.10.23	所检项目合格	

79	GX-B1593/21-B-23106~23109	2023.10.23	所检项目合格	
80	GX-B1592/21-B-23066	2023.10.23	所检项目合格	
81	GX-B1540/20-B-233106~233117	2023.10.23	所检项目合格	


82	GX-B1374/22-B-230713	2023.10.23	所检项目合格	
83	GX-B1373/21-B-23482~23489	2023.10.23	所检项目合格	
84	GX-B1540/20-B-233073~233105	2023.10.23	所检项目合格	

85	GX-B1475/22-B-230335~230342	2023.10.26	所检项目合格	
86	GX-B1372/22-B-230854~230863	2023.10.26	所检项目合格	
87	GX-B1372/22-B-230864~230872	2023.10.26	所检项目合格	

88	GX-B1601/22-B-230267~230268	2023.10.26	所检项目合格	
89	GX-B1372/22-B-230888~230893	2023.10.26	所检项目合格	
90	GX-B1475/22-B-230290~230293	2023.10.26	所检项目合格	

91	GX-B1475/22-B-230286	2023.10.27	所检项目合格	
92	GX-B1542/21-B-230391~230395	2023.10.27	所检项目合格	
93	GX-B1540/20-B-232785~232800	2023.10.27	所检项目合格	

94	GX-B1540/20-B-232754~232768	2023.10.26	所检项目合格	
95	GX-B1540/20-B-232770~232784	2023.10.27	所检项目合格	
96	GX-B1540/20-B-232801~232815	2023.10.27	所检项目合格	

97	GX-B1540/20-B-232816~232830	2023.10.27	所检项目合格	
98	GX-B1373/21-B-23392~23394	2023.10.26	所检项目合格	
99	GX-B1540/20-B-233255~233284	2023.10.28	所检项目合格	

100	GX-B1373/21-B-23452~23454	2023.10.28	所检项目合格	
101	GX-B1465/22-B-23140~23142	2023.10.28	所检项目合格	
102	GX-B1465/22-B-23164~23168	2023.10.28	所检项目合格	

103	GX-B1373/21-B-23385~23387	2023.10.28	所检项目合格	
104	GX-B1374/22-B-230722~230725	2023.10.28	所检项目合格	
105	GX-B1466/22-B-23100~23101	2023.10.28	所检项目合格	

106	GX-B1475/22-B-230343~230347	2023.10.30	所检项目合格	
107	GX-B1603/22-B-230112~230114	2023.10.30	所检项目合格	
108	GX-B1603/22-B-230131	2023.10.30	所检项目合格	

109	GX-B1601/22-B-230297~230298	2023.10.30	所检项目合格	
110	GX-B1592/21-B-230343~230347	2023.10.28	所检项目合格	
111	GX-B1466/22-B-23080~23090	2023.10.28	所检项目合格	

112	GX-B1540/20-B-232739~232753	2023.10.28	所检项目合格	
113	GX-B1540/20-B-233285~233289	2023.10.28	所检项目合格	
114	GX-B1466/22-B-23091~23095	2023.10.28	所检项目合格	

115	GX-B1465/22-B-23169	2023.10.28	所检项目合格	
116	GX-B1374/22-B-230809~230819	2023.10.28	所检项目合格	
117	GX-B1374/22-B-230804~230808	2023.10.28	所检项目合格	

118	GX-B1374/22-B-230768~230770	2023.10.28	所检项目合格	
119	GX-B1373/21-B-23513~23515	2023.10.28	所检项目合格	
120	GX-B1373/21-B-23388~23391	2023.10.28	所检项目合格	

121	GX-B1592/21-B-23070~23072	2023.10.28	所检项目合格	 A technician in a grey uniform is working on a piece of equipment. A date stamp '2023.9.30' is visible in the bottom right corner of the image.
122	GX-B1374/22-B-230799~230803	2023.10.28	所检项目合格	 Two technicians in grey uniforms are working at a lab bench. One is adjusting a device while the other looks on. A date stamp '2023.10.6' is visible in the bottom right corner of the image.
123	GX-B1373/21-B-23516~23523	2023.10.28	所检项目合格	 Two technicians in grey uniforms are standing next to two large pieces of equipment with yellow high-voltage warning symbols. One technician is adjusting a component on the right machine. A date stamp '2023.10.7' is visible in the bottom right corner of the image.

124	GX-B1542/21-B-23726~23742	2023.10.31	所检项目合格	
125	GX-B1542/21-B-23663~23672	2023.10.31	所检项目合格	
126	GX-B1542/21-B-23706~23725	2023.10.31	所检项目合格	

127	GX-B1544/21-B-23096~23100	2023.10.31	所检项目合格	
128	GX-B1529/20-B-23734~23745	2023.10.31	所检项目合格	
129	GX-B1529/20-B-23729~23733	2023.10.31	所检项目合格	

130	GX-B1475/22-B-230301	2023.10.30	所检项目合格	 <p>2023.9.26</p>
-----	----------------------	------------	--------	--