

序号	报告编号	发布日期	结论	影像资料
1	GX-B1521/20-Y-23594	2023年11月2日	所检项目合格。	
2	GX-B1521/20-Y-23595	2023年11月2日	所检项目合格。	

3	GX-B1521/20-Y-23596	2023年11月2日	所检项目合格。	
4	GX-B1521/20-Y-23597	2023年11月2日	所检项目合格。	

5	GX-B1521/20-Y-23598	2023年11月2日	所检项目合格。	
6	GX-B1521/20-Y-23599	2023年11月2日	所检项目合格。	

7	GX-B1521/20-Y-23600	2023年11月2日	所检项目合格。	
8	GX-B1521/20-Y-23601	2023年11月2日	所检项目合格。	

9	GX-B1557/22-Y-23045	2023年11月2日	所检项目合格。	
10	GX-B1521/20-Y-23616	2023年11月2日	所检项目合格。	

11	GX-B1521/20-Y-23617	2023年11月2日	所检项目合格。	
12	GX-B1539/22-Y-23261	2023年11月2日	所检项目合格。	

13	GX-B1563/21-Y-23043	2023年11月2日	所检项目合格。	
14	GX-B1557/22-Y-23043	2023年11月2日	所检项目合格。	

15	GX-B1415/22-Y-23018	2023年11月2日	所检项目合格。	
16	GX-B1328/20-Y-23138	2023年11月2日	本次共检绝缘鞋76只， 76只绝缘鞋合格。	

17	GX-B1495/20-Y-231639~ 231652	2023年11月2日	本次共检高压开关设备 14台，14台高压开关设 备所检项目合格。	
18	GX-B1495/20-Y-231653~ 231665	2023年11月2日	本次共检高压开关设备 13台，13台高压开关设 备所检项目合格。	

19	GX-B1423/20-Y-235707	2023年11月2日	综合判定：合格	
20	GX-B1423/20-Y-236074	2023年11月2日	综合判定：合格	

21	GX-B1423/20-Y-236075	2023年11月2日	综合判定：合格	
22	GX-B1423/20-Y-236076	2023年11月2日	综合判定：合格	

23	GX-B1423/20-Y-236077	2023年11月2日	综合判定：合格	
24	GX-B1423/20-Y-236078	2023年11月2日	综合判定：合格	

25	GX-B1423/20-Y-236079	2023年11月2日	综合判定：合格	
26	GX-B1423/20-Y-236080	2023年11月2日	综合判定：合格	

27	GX-B1423/20-Y-236081	2023年11月2日	综合判定：合格	
28	GX-B1339/21-Y-23017	2023年11月3日	所检项目合格	

29	GX-B1328/20-Y-23141	2023年11月3日	本次共检绝缘手套 62只，62只绝缘手套合格。	 A photograph showing several workers in a workshop setting. One worker in the foreground is kneeling and testing a pair of orange insulation gloves using a specialized device. Other workers are visible in the background, some standing and some working. The floor is concrete, and there are various tools and equipment scattered around. A date stamp '2023/10/19' is visible in the bottom right corner of the image.
30	GX-B1328/20-Y-23142	2023年11月3日	本次共检绝缘鞋36只， 36只绝缘鞋合格。	 A photograph showing workers in a workshop testing insulation shoes. One worker is kneeling and testing a shoe, while another worker stands nearby. The floor is concrete, and there are various tools and equipment scattered around. A date stamp '2023/10/19' is visible in the bottom right corner of the image.

31	GX-B1328/20-Y-23143	2023年11月3日	本次共检验电器10支， 10支验电器合格。	
32	GX-B1328/20-Y-23144	2023年11月3日	本次共检便携式接地和 接地短路装置5组，5组 便携式接地和接地短路 装置合格。	

33	GX-B1328/20-Y-23145	2023年11月3日	本次共检验电器2支，2支验电器合格。		
34	GX-B1521/20-Y-23612	2023年11月3日	所检项目合格。		

35	GX-B1521/20-Y-23613	2023年11月3日	所检项目合格。	 <p>2023/10/4</p>	
36	GX-B1521/20-Y-23614	2023年11月3日	所检项目合格。	 <p>2023/10/4</p>	

37	GX-B1415/22-Y-23019	2023年11月3日	所检项目合格。	 A photograph showing a worker in a red safety suit and helmet standing in a control room or office environment, looking at a computer monitor. The date stamp at the bottom right of the image is 2023-10-24.
38	GX-B1321/20-Y-23624~23625	2023年11月3日	本次共检电力电缆2条， 2条电力电缆所检项目合格。	 A photograph showing a worker in a blue safety suit and helmet inspecting a large bundle of power cables in a large industrial facility. The date stamp at the bottom right of the image is 2023-10-15.

39	GX-B1539/22-Y-23257	2023年11月3日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface at a construction site. A worker in a high-visibility vest and hard hat stands next to the loader. The background shows a cloudy sky and some construction materials. A yellow timestamp '2023/11/4' is visible in the bottom right corner of the image.
40	GX-B1539/22-Y-23258	2023年11月3日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface at a construction site. A worker in a high-visibility vest and hard hat stands next to the loader. The background shows a cloudy sky and some construction materials. A yellow timestamp '2023/11/4' is visible in the bottom right corner of the image.

41	GX-B1539/22-Y-23259	2023年11月3日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface under a blue sky with scattered clouds. A worker in a high-visibility vest and hard hat stands to the left of the machine. The loader has a large front bucket and heavy-duty tires. A yellow timestamp '2023/10/4' is visible in the bottom right corner of the photo.
42	GX-B1539/22-Y-23260	2023年11月3日	所检项目合格。	 A yellow wheel loader is parked on a dirt and gravel surface. A worker in a high-visibility vest and hard hat stands to the left of the machine. The loader has a large front bucket and heavy-duty tires. A yellow timestamp '2023/10/4' is visible in the bottom right corner of the photo.

43	GX-B1563/21-Y-23036	2023年11月3日	所检项目合格。	
44	GX-B1539/22-Y-23268	2023年11月3日	所检项目合格。	

45	GX-B1563/21-Y-23044	2023年11月3日	所检项目合格。	
46	GX-B1328/20-Y-23132	2023年11月3日	本次共检绝缘手套 36只，36只绝缘手套所 检项目合格。	

47	GX-B1328/20-Y-23133	2023年11月3日	本次共检绝缘鞋36只，36只绝缘鞋所检项目合格。	 <p>2023/10/16</p>
48	GX-B1328/20-Y-23151	2023年11月6日	本次共检携带式接地和接地短路装置10组，10组携带式接地和接地短路装置所检项目合格。	 <p>2023/10/20</p>

49	GX-B1328/20-Y-23152	2023年11月6日	所检项目合格。	
----	---------------------	------------	---------	---