


序号	报告编号	发布日期	结论	影像资料
1	GX-B1328/20-4-23206	2023. 11. 1	本次共检绝缘手套8只，8只所检项目合格。	 <p>A photograph showing two workers in safety gear inspecting equipment outdoors. A yellow bucket and various tools are on the ground. A red timestamp '2023-10-13' is visible at the bottom of the image.</p>
2	GX-B1328/20-4-23207	2023. 11. 1	本次共检绝缘鞋8只，8只所检项目合格。	 <p>A photograph showing two workers in safety gear inspecting equipment outdoors. A yellow bucket and various tools are on the ground. A red timestamp '2023-10-13' is visible at the bottom of the image.</p>
3	GX-B1328/20-4-23208	2023. 11. 1	本次共检短路接地线4套，4套短路接地线所检项目合格。	 <p>A photograph showing two workers in safety gear inspecting equipment outdoors. A yellow bucket and various tools are on the ground. A red timestamp '2023-10-13' is visible at the bottom of the image.</p>

4	GX-B1328/20-4-23209	2023. 11. 1	本次共检验电器4支，4支验电器所检项目合格。	
5	GX-B1313/21-4-23055	2023. 11. 1	所检项目合格。	
6	GX-B1322/21-4-23110~23113	2023. 11. 1	本次共检电力电缆4条，4条所检项目合格。	
7	GX-B1350/21-4-23069	2023. 11. 1	所检项目合格。	

8	GX-B1307/20-4-23028	2023. 11. 1	综合判定：合格。		
9	GX-B1307/20-4-23029	2023. 11. 1	综合判定：合格。		
10	GX-B1307/20-4-23030	2023. 11. 1	综合判定：合格。		
11	GX-B1324/21-4-23024	2023. 11. 2	本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。		

12	GX-B1451/20-4-23126~23131	2023. 11. 2	本次共检高压开关柜6面，6面高压开关柜所检项目合格。	
13	GX-B1300/23-4-23016	2023. 11. 3	综合判定：合格。	