

序号	报告编号	发布日期	结论	影像资料
44	GX-B1339/21-5-23006	2023. 11. 14	所检项目合格。	 A worker in a red uniform and hard hat is inspecting a large blue industrial component, possibly a valve or part of a machine, in an industrial setting. The date stamp '2023. 10. 31' is visible at the bottom right of the image.
45	GX-B1339/21-5-23007	2023. 11. 14	所检项目合格。	 A worker in a red uniform and hard hat is inspecting a blue industrial component, possibly a valve or part of a machine, in an industrial setting. The date stamp '2023. 10. 31' is visible at the bottom right of the image.
46	GX-B1548/20-5-23001	2023/11/15	所检项目合格。	 A worker in a blue uniform and white hard hat is inspecting a yellow industrial component, possibly a valve or part of a machine, in an outdoor setting. The date stamp '2023. 10. 15' is visible at the bottom right of the image.

47	GX-B1548/20-5-23002	2023/11/15	所检项目合格。	 <p>2023/10/16</p>
48	GX-B1548/20-5-23003	2023/11/15	所检项目合格。	 <p>2023/10/16</p>
49	GX-B1548/20-5-23004	2023/11/15	所检项目合格。	 <p>2023/10/16</p>

50	GX-B1548/20-5-23005	2023/11/15	所检项目合格。	
51	GX-B1548/20-5-23006	2023/11/15	所检项目合格。	
52	GX-B1548/20-5-23007	2023/11/15	所检项目合格。	

53	GX-B1548/20-5-23008	2023/11/15	所检项目合格。	
54	GX-B1534/20-5-23001	2023/11/15	所检项目合格。	
55	GX-B1534/20-5-23002	2023/11/15	所检项目合格。	


56	GX-B1534/20-5-23003	2023/11/15	所检项目合格。	
57	GX-B1534/20-5-23004	2023/11/15	所检项目合格。	
58	GX-B1534/20-5-23005	2023/11/15	所检项目合格。	

59	GX-B1534/20-5-23006	2023/11/15	所检项目合格。	 A man in a grey jacket and black pants stands in front of a yellow truck. The date stamp '2023/10/15' is visible in the bottom right corner of the photo.
60	GX-B1534/20-5-23007	2023/11/15	所检项目合格。	 A man in a grey jacket and black pants stands in front of a yellow truck. The date stamp '2023/10/15' is visible in the bottom right corner of the photo.
61	GX-B1534/20-5-23008	2023/11/15	所检项目合格。	 A man in a grey jacket and black pants stands in front of a yellow truck. The date stamp '2023/10/15' is visible in the bottom right corner of the photo.

62	GX-B1534/20-5-23009	2023/11/15	所检项目合格。	
63	GX-B1534/20-5-23010	2023/11/15	所检项目合格。	
64	GX-B1534/20-5-23011	2023/11/15	所检项目合格。	

65	GX-B1534/20-5-23012	2023/11/15	所检项目合格。	
66	GX-B1534/20-5-23013	2023/11/15	所检项目合格。	
67	GX-B1534/20-5-23014	2023/11/15	所检项目合格。	

68	GX-B1534/20-5-23015	2023/11/15	所检项目合格。	
69	GX-B1534/20-5-23016	2023/11/15	所检项目合格。	
70	GX-B1416/22-5-23091	2023. 11. 15	综合判定：合格。	




71	GX-B1416/22-5-23092	2023. 11. 15	综合判定：合格。	
72	GX-B1416/22-5-23093	2023. 11. 15	综合判定：合格。	
73	GX-B1416/22-5-23090	2023. 11. 15	综合判定：合格。	

74	GX-B1424/20-5-23048	2023/11/15	依据NB/T 10176-2019单轨吊车综合判定合格。	
75	GX-B1300/23-5-23040	2023. 11. 16	所检项目合格	
76	GX-B1424/20-5-23051	2023/11/15	依据NB/T 10176-2019单轨吊车所检项目合格。	




77	GX-B1300/23-5-23041	2023. 11. 17	所检项目合格。	 <p>2023/11/17</p>
78	GX-B1386/21-5-23001	2023/11/17	所检项目合格	 <p>2023/9/12</p>
79	GX-B1386/21-5-23002	2023/11/17	所检项目合格	 <p>2023/9/12</p>




80	GX-B1386/21-5-23003	2023/11/17	所检项目合格	
81	GX-B1310/21-5-23276	2023. 11. 19	符合标准要求。	
82	GX-B1310/21-5-23277	2023. 11. 19	符合标准要求。	




83	GX-B1310/21-5-23278	2023. 11. 19	符合标准要求。	
84	GX-B1310/21-5-23279	2023. 11. 19	符合标准要求。	
85	GX-B1310/21-5-23280	2023. 11. 19	符合标准要求。	

86	GX-B1310/21-5-23281	2023. 11. 19	符合标准要求。		
87	GX-B1310/21-5-23282	2023. 11. 19	符合标准要求。		
88	GX-B1310/21-5-23283	2023. 11. 19	符合标准要求。		


89	GX-B1310/21-5-23275	2023/11/17	符合标准要求。	
90	GX-B1328/20-5-23181	2023. 11. 20	本次共检绝缘手套4只，4只绝缘手套合格。	
91	GX-B1328/20-5-23182	2023. 11. 20	本次共检绝缘鞋4只，4只绝缘鞋合格。	

92	GX-B1321/20-5-23921~23932	2023. 11. 20	本次共检电力电缆12条，12条电力电缆所检项目合格。	
93	GX-B1321/20-5-23965~23968	2023. 11. 20	本次共检电力电缆4条，4条电力电缆所检项目合格。	
94	GX-B1321/20-5-23961~23964	2023. 11. 20	本次共检电力电缆4条，4条电力电缆所检项目合格。	

95	GX-B1321/20-5-23951~23960	2023. 11. 20	本次共检电力电缆10条，10条电力电缆所检项目合格。	
96	GX-B1321/20-5-23948~23950	2023. 11. 20	本次共检电力电缆3条，3条电力电缆所检项目合格。	
97	GX-B1321/20-5-23933~23947	2023. 11. 20	本次共检电力电缆15条，15条电力电缆所检项目合格。	

98	GX-B1314/20-5-23016~23018	2023. 11. 20	本次共检干式电抗器3台，3台干式电抗器所检项目合格。	
99	GX-B1424/20-5-23052	2023/11/20	依据NB/T 10176-2019单轨吊车综合判定合格。	
100	GX-B1424/20-5-23053	2023/11/20	依据NB/T 10176-2019单轨吊车综合判定合格。	

101	GX-B1424/20-5-23054	2023/11/20	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2023/11/9</p>
102	GX-B1424/20-5-23055	2023/11/20	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2023/11/9</p>
103	GX-B1310/21-5-23284	2023/11/22	符合标准要求。	 <p>2023/11/9</p>

104	GX-B1310/21-5-23285	2023/11/22	符合标准要求。	
-----	---------------------	------------	---------	---