

序号	报告编号	发布日期	结论	影像资料
31	GX-B1312/20-1-23501~23502	2023. 11. 23	本次共检电力变压器 2台，2台电力变压器 所检项目合格	

32	GX-B1321/20-1-23958~23959	2023. 11. 23	电缆2条, 2条电力电缆	
----	---------------------------	--------------	--------------	---

33	GX-B1328/20-1-23110	2023/11/27	本次共检绝缘手套26只，26只所检项目合格。	
34	GX-B1328/20-1-23111	2023/11/27	本次共检绝缘鞋22只，22只所检项目合格。	

35	GX-B1310/21-1-23160	2023. 11. 5	符合标准要求	
36	GX-B1416/22-1-23024	2023/11/28	综合判定：合格。	

37	GX-B1416/22-1-23025	2023/11/28	综合判定：合格。	 <p>A photograph of a worker in an orange safety suit and red helmet with a headlamp. The worker is holding a device and standing in a dark industrial setting. A yellow vertical timestamp '2023/10/18' is visible on the left side of the image.</p>
38	GX-B1416/22-1-23026	2023/11/28	综合判定：合格。	 <p>A photograph of a worker in an orange safety suit and red helmet, standing next to a metal gate in a dark industrial setting. A yellow vertical timestamp '2023/11/06' is visible on the left side of the image.</p>

39	GX-B1416/22-1-23027	2023/11/28	综合判定：合格。	
40	GX-B1416/22-1-23028	2023/11/28	综合判定：合格。	

41	GX-B1423/20-1-23730	2023/11/28	综合判定：合格	 A photograph showing the front of a yellow truck. Two men are standing in front of the truck. The man on the left is wearing a white shirt, a yellow high-visibility vest, and a red hard hat. The man on the right is wearing a dark blue polo shirt and a red hard hat. The truck has a red ribbon tied across the front. A red date stamp '2023/11/23' is visible in the bottom right corner of the photo.
42	GX-B1423/20-1-23731	2023/11/28	综合判定：合格	 A photograph showing a yellow truck from a different angle. Two men are standing in front of the truck. The man on the left is wearing a white shirt, a yellow high-visibility vest, and a red hard hat. The man on the right is wearing a light grey t-shirt and a red hard hat. A red date stamp '2023/11/23' is visible in the bottom right corner of the photo.

43	GX-B1423/20-1-23732	2023/11/28	综合判定：合格	
44	GX-B1423/20-1-23733	2023/11/28	综合判定：合格	
45	GX-B1423/20-1-23734	2023/11/28	综合判定：合格	

46	GX-B1423/20-1-23735	2023/11/28	综合判定：合格	
47	GX-B1423/20-1-23736	2023/11/28	综合判定：合格	

48	GX-B1423/20-1-23737	2023/11/28	综合判定：合格	 <p>A photograph of a green 48-ton truck. Two workers in safety gear are standing in front of the truck. The truck has "48 TONLY" written on its side. A red date stamp "2023.11.28" is visible in the bottom right corner of the photo.</p>
49	GX-B1423/20-1-23738	2023/11/28	综合判定：合格	 <p>A photograph of a green 51-ton truck. Two workers in safety gear are standing in front of the truck. The truck has "51 TONLY" written on its side. A red date stamp "2023.11.23" is visible in the bottom right corner of the photo.</p>

50	GX-B1423/20-1-23739	2023/11/28	综合判定：合格	
51	GX-B1423/20-1-23740	2023/11/28	综合判定：合格	

52	GX-B1423/20-1-23741	2023/11/28	综合判定：合格	
53	GX-B1423/20-1-23742	2023/11/28	综合判定：合格	

54	GX-B1423/20-1-23743	2023/11/28	综合判定：合格	
55	GX-B1423/20-1-23744	2023/11/28	综合判定：合格	

56	GX-B1520/20-1-23051	2023/11/28	综合判定：合格。	
57	GX-B1548/20-1-23032	2023. 11. 29	所检项目合格。	

58	GX-B1548/20-1-23033	2023. 11. 29	所检项目合格。	
59	GX-B1354/20-1-23009	2023. 11. 29	电网接地电容电流符合规定。	

60	GX-B1328/20-1-23112	2023/11/29	所检项目合格	 A photograph showing a laboratory bench with a red bucket and a white cloth. The date 2023/11/24 is visible in the bottom right corner of the image.
61	GX-B1328/20-1-23113	2023/11/29	所检项目合格	 A photograph showing a laboratory bench with a red bucket and a white cloth. The date 2023/11/24 is visible in the bottom right corner of the image.

23045

