


序号	报告编号	发布日期	结论	影像资料
20	GX-B1520/20-1-23052	2023/12/14	综合判定：合格。	
21	GX-B1328/20-1-23118	2023. 12. 15	本次共检绝缘鞋32只，32只绝缘鞋合格	
22	GX-B1328/20-1-23119	2023. 12. 15	本次共检绝缘杆6套，6套绝缘杆合格	

23	GX-B1328/20-1-23120	2023. 12. 15	本次共检验电器9支，9支 验电器合格			
24	GX-B1328/20-1-23121	2023. 12. 15	本次共检绝缘胶垫10个， 10个绝缘胶垫合格			
25	GX-B1304/21-1-23010	2023/12/5	所检项目合格			

26	GX-B1308/21-1-23034	2023. 12. 15	所检项目合格	
27	GX-B1499/21-1-23080	2023. 12. 15	所检项目合格	

28	GX-B1499/21-1-23081	2023. 12. 15	所检项目合格	
29	GX-B1499/21-1-23082	2023. 12. 15	所检项目合格	
30	GX-B1332/21-1-23067~23078	2023. 12. 15	本次共检电力电容器 12台，12台所检项目合	

31	GX-B1306/21-1-23040	2023. 12. 15	所检项目合格		
32	GX-B1306/21-1-23041	2023. 12. 15	所检项目合格		
33	GX-B1306/21-1-23042	2023. 12. 15	所检项目合格		

34	GX-B1548/20-1-23034	2023. 12. 15	所检项目合格	
35	GX-B1306/21-1-23039	2023. 12. 16	所检项目合格	
36	GX-B1520/20-1-23053	2023/12/16	综合判定：合格。	

37	GX-B1424/20-1-23015	2023/12/18	所检项目合格	
38	GX-B1309/21-1-23031	2023/12/16	所检项目合格。	
39	GX-B1309/21-1-23032	2023/12/16	所检项目合格。	

40	GX-B1500/21-1-23118	2023/12/16	综合判定：合格。	
41	GX-B1500/21-1-23119	2023/12/16	综合判定：合格。	
42	GX-B1500/21-1-23120	2023/12/16	综合判定：合格。	

43	GX-B1500/21-1-23121	2023/12/16	综合判定：合格。	
44	GX-B1500/21-1-23122	2023/12/16	综合判定：合格。	
45	GX-B1500/21-1-23123	2023/12/16		

46	GX-B1500/21-1-23124	2023/12/16		
47	GX-B1382/21-1-23038	2023/12/18	合格	
48	GX-B1309/21-1-23033	2023. 12. 20	所检项目合格	

49	GX-B1500/21-1-23125	2023. 12. 20	综合判定：合格		
50	GX-B1500/21-1-23126	2023. 12. 20	综合判定：合格		
51	GX-B1500/21-1-23127	2023. 12. 20	综合判定：合格		

52	GX-B1500/21-1-23128	2023. 12. 20	综合判定：合格	
53	GX-B1385/21-1-23032	2023/12/21	所检项目合格	
54	GX-B1385/21-1-23033	2023/12/21	所检项目合格	

55	GX-B1385/21-1-23034	2023/12/21	所检项目合格		 <p>2023/12/8</p>
56	GX-B1385/21-1-23035	2023/12/21	所检项目合格		 <p>2023/12/8</p>