

序号	报告编号	发布日期	结论	影像资料
1	GX-B1309/21-1-23034	2024. 1. 2	所检项目合格	
2	GX-B1500/21-1-23129	2024. 1. 2	综合判定：合格	

3	GX-B1500/21-1-23130	2024.1.2	综合判定：合格	 A worker in camouflage gear is operating a green machine in a dark environment. The machine has red handwheels. A red timestamp '2023/12/9' is visible in the bottom right corner of the photo.
4	GX-B1500/21-1-23131	2024.1.2	综合判定：合格	 A worker in camouflage gear is holding a document and looking at it next to a green machine. The machine has red handwheels. A red timestamp '2023/12/9' is visible in the bottom right corner of the photo.
5	GX-B1302/23-1-23010	2024.1.3	综合判定：合格	 A worker in a blue uniform and red helmet is operating a machine. The machine is green and blue. A yellow timestamp '2023 12 08' is visible in the bottom right corner of the photo.

6	GX-B1307/20-1-23092	2024. 1. 5	综合判定：合格		
7	GX-B1307/20-1-23093	2024. 1. 5	综合判定：合格		
8	GX-B1307/20-1-23094	2024. 1. 5	综合判定：合格		

9	GX-B1307/20-1-23095	2024. 1. 5	综合判定：合格	
---	---------------------	------------	---------	---

23045

