

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------------|------------|---------------------------------|--|
| 1 | GX-B1324/21-2-23006~23010 | 2024. 1. 2 | 本次共检三相交流电动机5台，5台三相交流电动机所检项目合格。 |  |
| 2 | GX-B1324/21-2-23011~23017 | 2024. 1. 2 | 本次共检验三相交流电动机7台，7台三相交流电动机所检项目合格。 |  |


| | | | | |
|---|---------------------------|------------|--------------------------------|--|
| 3 | GX-B1324/21-2-23018~23019 | 2024. 1. 2 | 本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。 |  <p>2023/12/06</p> |
| 4 | GX-B1324/21-2-23020~23023 | 2024. 1. 2 | 本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。 |  <p>2023/12/07</p> |

| | | | | |
|---|---------------------------|------------|--------------------------------|--|
| 5 | GX-B1324/21-2-23024 | 2024. 1. 2 | 本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。 |  <p>2023/12/08</p> |
| 6 | GX-B1323/21-2-23180~23183 | 2024. 1. 2 | 本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。 |  <p>2023/12/21</p> |

| | | | | |
|---|---------------------|------------|--------|--|
| 7 | GX-B1328/20-2-23180 | 2024/1/2 | 所检项目合格 |  |
| 8 | GX-B1328/20-2-23181 | 2023/12/27 | 所检项目合格 |  |

| | | | | |
|----|---------------------|----------|--------|--|
| 9 | GX-B1328/20-2-23182 | 2024/1/2 | 所检项目合格 |  |
| 10 | GX-B1328/20-2-23183 | 2024/1/2 | 所检项目合格 |  |


| | | | | |
|----|---------------------|----------|--------|--|
| 11 | GX-B1328/20-2-23184 | 2024/1/2 | 所检项目合格 |  |
| 12 | GX-B1328/20-2-23185 | 2024/1/2 | 所检项目合格 |  |

| | | | | |
|----|---------------------|----------|--------|--|
| 13 | GX-B1328/20-2-23186 | 2024/1/2 | 所检项目合格 |  |
| 14 | GX-B1328/20-2-23187 | 2024/1/2 | 所检项目合格 |  |

| | | | | |
|----|---------------------|----------|--------|--|
| 15 | GX-B1328/20-2-23188 | 2024/1/2 | 所检项目合格 |  A photograph showing a yellow safety cage with two green platforms, positioned outdoors in an industrial area. A person wearing a red hard hat and dark clothing is standing near the cage. The background features a building with a large blue door. A timestamp '2023/12/07' is visible in the bottom right corner of the image. |
| 16 | GX-B1328/20-2-23189 | 2024/1/2 | 所检项目合格 |  A photograph showing a yellow safety cage with two green platforms, positioned outdoors in an industrial area. A person wearing a red hard hat and dark clothing is standing near the cage. The background features a building with a large blue door. A timestamp '2023/12/07' is visible in the bottom right corner of the image. |

| | | | | |
|----|---------------------|----------|--------|--|
| 17 | GX-B1328/20-2-23190 | 2024/1/2 | 所检项目合格 |  |
| 18 | GX-B1328/20-2-23191 | 2024/1/2 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|------------|---------|--|
| 19 | GX-B1314/21-2-23019~23021 | 2024/1/2 | 所检项目合格 |  <p>2023/12/21</p> |
| 20 | GX-B1310/21-2-23416 | 2024. 1. 4 | 符合标准要求。 |  <p>2023/12/11</p> |

| | | | | |
|----|---------------------|------------|---------|--|
| 21 | GX-B1427/21-2-23416 | 2024. 1. 4 | 符合标准要求。 |  A photograph showing a worker in a red hard hat and blue jacket kneeling on a concrete floor, working on a metal structure. The worker is wearing safety glasses and gloves. The date '2023/12/11' is visible in the bottom right corner of the photo. |
|----|---------------------|------------|---------|--|