


序号	报告编号	发布日期	结论	影像资料
10	GX-B1310/21-3-23287	2024年1月2日	符合标准要求。	 A photograph showing two workers in a large industrial machine. One worker is wearing a white jacket and a red hard hat, and the other is wearing a blue jacket and a red hard hat. They are working on a large, orange, curved component. The date stamp '2023.12.24' is visible in the bottom right corner of the image.
11	GX-B1306/23-3-23081	2024年1月10日	综合判定：合格。	 A photograph of a worker in a control room. The worker is wearing a dark jacket, blue pants, and a red hard hat. They are standing next to a large, white control panel with a red stripe. The date stamp '2023.12.21' is visible in the bottom right corner of the image.

12	GX-B1306/23-3-23082	2024年1月10日	综合判定：合格。	
13	GX-B1306/23-3-23083	2024年1月10日	综合判定：合格。	
14	GX-B1306/23-3-23084	2024年1月10日	综合判定：合格。	

15	GX-B1306/23-3-23085	2024年1月10日	综合判定：合格。	
----	---------------------	------------	----------	---