

序号	报告编号	发布日期	结论	影像资料
32	GX-B1350/21-5-23072	2024. 1. 5	本次共检接地装置2处，2处接地装置所检项目合格。	
33	GX-B1351/21-5-23005~23006	2024. 1. 5	本次共检矿用隔爆型检漏继电器2台, 2台矿用隔爆型检漏继电器所检项目合格	
34	GX-B1354/20-5-23020	2024. 1. 8	电网接地电容电流符合规定。	

35	GX-B1352/21-5-23834~23837	2024. 1. 8	<p>本次共检矿用防爆低压交流真空馈电开关漏电保护4台, 4台防爆低压交流真空馈电开关漏电保护所检项目合格。</p>	
36	GX-B1352/21-5-23838~23842	2024. 1. 8	<p>本次共检矿用防爆低压交流真空馈电开关漏电保护5台, 5台矿用防爆低压交流真空馈电开关漏电所检项目合格。</p>	
37	GX-B1415/22-5-23019	2024/1/8	<p>综合判定：合格</p>	

38	GX-B1323/21-5-23223~23226	2024. 1. 8	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	
39	GX-B1323/21-5-23220~23222	2024. 1. 8	本次共检交流三相电动机3台，3台三相交流电动机所检项目合格。	
40	GX-B1314/21-5-23019~23021	2024. 1. 8	本次共检干式电抗器3台，3台干式电抗器所检项目合格。	

41	GX-B1328/20-5-23189	2024. 1. 8	本次共检绝缘手套26只，26只绝缘手套合格。	
42	GX-B1328/20-5-23190	2024. 1. 8	本次共检绝缘鞋26只，26只绝缘鞋合格。	
43	GX-B1328/20-5-23191	2024. 1. 8	本次共检验电器10支，10支验电器合格。	

44	GX-B1328/20-5-23192	2024. 1. 8	本次共检便携式接地和接地短路装置10套，10套便携式接地和接地短路装置合格。	
45	GX-B1328/20-5-23193	2024. 1. 8	本次共检绝缘杆10支，10支绝缘杆合格。	
46	GX-B1359/21-5-23141	2024. 1. 8	所检项目合格。	

47	GX-B1359/21-5-23142-23157	2024. 1. 8	护装置16台，16台矿用隔爆型照	 <p>2023/12/10</p>
48	GX-B1359/21-5-23158	2024. 1. 8	所检项目合格。	 <p>2023/12/11</p>
49	GX-B1310/21-5-23320	2024. 1. 8	符合标准要求。	 <p>2023/12/30</p>

50	GX-B1427/21-5-23025	2024. 1. 8	符合标准要求。	 <p>2023/12/30</p>
51	GX-B1321/20-5-231009	2024. 1. 8	所检项目合格。	 <p>2023.12.5</p>
52	GX-B1417/22-5-23039	2024. 1. 9	综合判定：合格。	 <p>2023.12.4</p>

53	GX-B1417/22-5-23040	2024. 1. 9	综合判定：合格。	 A photograph showing two workers in safety gear standing next to a forklift at an industrial site. The worker on the left is wearing a blue jacket and a black helmet, while the worker on the right is wearing a grey jacket and a red helmet. The forklift is a yellow and black model. The background shows industrial buildings and a clear sky. A red timestamp '2023.12.4' is visible in the bottom right corner of the image.
54	GX-B1417/22-5-23041	2024. 1. 9	综合判定：合格。	 A photograph showing two workers in safety gear standing next to a forklift at an industrial site. The worker on the left is wearing a blue jacket and a black helmet, while the worker on the right is wearing a grey jacket and a red helmet. The forklift is a yellow and black model. The background shows industrial buildings and a clear sky. A red timestamp '2023.12.4' is visible in the bottom right corner of the image.
55	GX-B1417/22-5-23042	2024. 1. 9	综合判定：合格。	 A photograph showing two workers in safety gear standing next to a forklift at an industrial site. The worker on the left is wearing a blue jacket and a black helmet, while the worker on the right is wearing a grey jacket and a red helmet. The forklift is a yellow and black model. The background shows industrial buildings and a clear sky. A red timestamp '2023.12.4' is visible in the bottom right corner of the image.

56	GX-B1417/22-5-23043	2024. 1. 9	综合判定：合格。	 <p>2023.12.4</p>
57	GX-B1417/22-5-23044	2024. 1. 9	综合判定：合格。	 <p>2023.12.4</p>
58	GX-B1417/22-5-23045	2024. 1. 9	综合判定：合格。	 <p>2023.12.4</p>

59	GX-B1417/22-5-23046	2024. 1. 9	综合判定：合格。	 A photograph showing two workers in safety gear. One worker is wearing a grey uniform and a red hard hat, while the other is wearing a blue uniform and a grey hard hat. They are standing in an industrial area with buildings and equipment in the background. A red timestamp '2023.12.4' is visible in the bottom right corner of the image.
60	GX-B1417/22-5-23047	2024. 1. 9	综合判定：合格。	 A photograph of a white utility vehicle, possibly a generator or power unit, parked in an industrial yard. Two workers in safety gear are standing near the vehicle. The background shows industrial buildings and a clear sky. A red timestamp '2023.12.4' is visible in the bottom right corner of the image.
61	GX-B1417/22-5-23048	2024. 1. 9	综合判定：合格。	 A photograph of a white utility vehicle, similar to the one in the previous row, parked in an industrial yard. Two workers in safety gear are standing near the vehicle. The background shows industrial buildings and a clear sky. A red timestamp '2023.12.4' is visible in the bottom right corner of the image.

62	GX-B1559/22-5-23026	2024/1/9	所检项目合格。	 <p>2023/12/5</p>
63	GX-B1559/22-5-23027	2024/1/9	所检项目合格。	 <p>2023/12/5</p>
64	GX-B1559/22-5-23028	2024/1/9	所检项目合格。	 <p>2023/12/5</p>

65	GX-B1559/22-5-23029	2024/1/9	所检项目合格。	
66	GX-B1417/22-5-23049	2024. 1. 9	综合判定：合格。	
67	GX-B1417/22-5-23050	2024. 1. 9	综合判定：合格。	

68	GX-B1417/22-5-23051	2024. 1. 9	综合判定：合格。	 2023/12/4
69	GX-B1417/22-5-23052	2024. 1. 9	综合判定：合格。	 2023/12/4
70	GX-B1417/22-5-23053	2024. 1. 9	综合判定：合格。	 2023/12/4

71	GX-B1417/22-5-23054	2024. 1. 9	综合判定：合格。	
72	GX-B1417/22-5-23055	2024. 1. 9	综合判定：合格。	
73	GX-B1417/22-5-23056	2024. 1. 9	综合判定：合格。	

74	GX-B1417/22-5-23057	2024. 1. 9	综合判定：合格。	
75	GX-B1417/22-5-23058	2024. 1. 9	综合判定：合格。	
76	GX-B1417/22-5-23059	2024. 1. 9	综合判定：合格。	

77	GX-B1417/22-5-23060	2024. 1. 9	综合判定：合格。	 A photograph showing two workers in safety gear (hard hats and work clothes) standing next to a white industrial machine. The worker on the right is wearing a red hard hat and a grey work suit, while the worker on the left is wearing a blue hard hat and a dark blue work suit. The machine has the number '311' on its side. A yellow timestamp '2023/12/5' is visible in the bottom right corner of the photo.
78	GX-B1417/22-5-23061	2024. 1. 9	综合判定：合格。	 A photograph showing two workers in safety gear standing next to a white pickup truck. The worker on the right is wearing a red hard hat and a grey work suit, while the worker on the left is wearing a blue hard hat and a dark blue work suit. A yellow timestamp '2023/12/5' is visible in the bottom right corner of the photo.
79	GX-B1417/22-5-23062	2024. 1. 9	综合判定：合格。	 A photograph showing two workers in safety gear standing next to a white car. The worker on the right is wearing a red hard hat and a grey work suit, while the worker on the left is wearing a blue hard hat and a dark blue work suit. A yellow timestamp '2023/12/5' is visible in the bottom right corner of the photo.

80	GX-B1417/22-5-23063	2024. 1. 9	综合判定：合格。	
81	GX-B1417/22-5-23064	2024. 1. 9	综合判定：合格。	
82	GX-B1417/22-5-23065	2024. 1. 9	综合判定：合格。	

83	GX-B1417/22-5-23066	2024. 1. 9	综合判定：合格。	 <p>2023/12/5</p>
84	GX-B1417/22-5-23067	2024. 1. 9	综合判定：合格。	 <p>2023/12/5</p>
85	GX-B1417/22-5-23068	2024. 1. 9	综合判定：合格。	 <p>2023/12/5</p>

86	GX-B1321/20-5-24001~24008	2024. 1. 11	本次共检电力电缆8条，8条电力电缆所检项目合格。	 <p>HONOR 80 Pro 160MP Matrix Camera 2024. 1. 8</p>
87	GX-B1321/20-5-24009	2024. 1. 11	所检项目合格。	 <p>HONOR 80 Pro 160MP Matrix Camera 2024. 1. 8</p>

88	GX-B1321/20-5-24010	2024. 1. 11	所检项目合格。	
89	GX-B1302/23-5-23003	2024/1/15	综合判定：合格。	